

UNIT CONDITION ASSESSMENT

Unit #: G5-3433 WO #: 11642733 Mileage: 12489 hrs

INSPECT:

- ☐ Body condition – rust – collision damage.
- ☐ Frame condition – rust – damaged – bent.
- ☐ Fluid leaks – Powertrain - etc.
- ☐ Inside cab – seats – floor – dash.
- ☐ Controls – brake – gearshift – signals - steering.
- ☐ Attachments

CONDITION		
GOOD	FAIR	POOR
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

ROAD TEST:

- ☐ Engine – starts – runs –noises.
- ☐ Transmission – slippage - noises.
- ☐ Handling – steering – brakes – suspension.
- ☐ Trucks and Tractors – hydraulics – accessories.

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

COMMENTS:

- ☐ Overall condition.
- ☐ Any major repairs required.

2

Y

Left cylinder leaking

1 = Consider immediate replacement. 2 = Consider replacing the following year. 3 = Consider replacing in 2 years or more.

- ☐ REPLACEMENT PRIORITY (circle one, and record on Work Order Main Job Line Priority). 1 2 3

Work Order Main

General	Job	Labor	Part	Comment	Fluid	Zone	Location	Status	Complete Date	Job Run	Defect #	Defect Date	Cannot be Driven	Es. Hrs	Book Time Vendor	Est Cost	Priority
10/14/2021	REPAIR CHECK LIST						STANISSE	COM	02/04/2022 15:36:40	Y				C	0	10.00	3

☐ _____