



Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>2019</u> Make <u>Dodge</u> Model <u>Charger</u>		
VIN: <u>2C3CDXKT8KH718514</u> Title: ☒ Clean Title ☐ Salvage Title ☐ No Title ☐ Court Documents Only ☐ SF97 Form ☐ Other		
Odometer: <u>64,147</u> ☒ Miles ☐ Kilometers ☐ Hours Odometer Accurate? ☒ Yes ☐ No ☐ Unknown		
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Drivable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>5.7 L, V 8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles/Kilometers Date Removed from Service: <u>09/18/2025</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: <u>Good All Wheel Drive</u> Exterior: Color: <u>Destroyer Gray</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: <u>Good</u> Tread: <u>Good</u> #Flat Hubcaps # <u>4</u> Major Damage to: _____ Additional Damage: <u>Driver door drops some when opening and closing</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No impressions Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes Interior: Color <u>Black</u> ☒ Cloth ☒ Vinyl ☐ Leather Damage to Seats: <u>Some wear from usage</u> Damage to Dash/Floor: <u>N/A</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD AC Condition: ☒ Cold ☐ Unknown ☐ No AC Air Bags: ☒ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: <u>11323 N. Jacob Smart Blvd, Ridgeland, SC 29936</u>		