Shop Tools/Machinery/Generators/Pumps Inspection Form

Asset contact for Questions and viewing appointments:							Vic Castela							
Department: Technology														
Short Description					Rotary Table									
Condition		Used/See Description ☑			New/Unused □			Is this a Gro	oup of Ite	No ☑	Yes □			
Serial #:		133684/179				Make/Brand:			Victoria Made In England					
Model Year:		N/A			Model Year:			N/A						
Hour Meter:		N/A				Inventory ID:		D :	N/A					
Date Removed from service:		Mo 0 th		2025		QT\	QTY:		1					
Voltage	N/A	N/A Phase N/		A Amp			N/A		НР	N/A		Hz	N/A	
Condition when removed from service:				Working⊊			3		Not working□			Unknown□		
Current condition:				Working□			Not working□		☐ Unknown☑ S		Sugg	Suggested for parts only□		
Reason for being auctioned:				Scheduled for re			eplacem	cement ☑ No		No longer required□		Does not operate□		
Notable attachments:					None									
Notable damage:					None									
Notable:					None									
Known issu	nown issues: None													
Opening/Reserve Bid Price: \$ 150.00 This is the minimum \$ amount you will sell this														
Please send 10 – 15 pictures to help sell the asset. Pictures of the hour meter, serial plate an										l plate and a	ny			
Pictures:	I	damage are always recommended.												
Video:	Vide	Video of the item working can bring a significantly higher bid												