Heavy Truck Inspection Form

Inventory ID: 14-88273 | **Asset Number:** 210-72 | **Fair Market Value:** 30000

Short Description:
Year 2014 Manufacturer International Model 7300 SFA 4x2

VIN: 1HTWAAAR8EH788273 Title Restriction: ☐ Y ■ N

Mileage/Odometer: 48259 Odometer Accurate ■ Y ☐ N: _____

Long Description: Primary Use for Vehicle: Municipal roadways and snow removal GVW: 39000

This Vehicle: ■ Starts ☐ Starts with a Boost & ■ Is Operable ☐ Is Not Operable ☐ **For Parts Only**

Date Removed From Service: October 31, 2025 Maintenance Records: ■ Available ☐ Not Available For Inspection

Engine Manufacture: International MaxxForce DT **Engine:** 7.6 L, V 466 ☐ Gas ■ Diesel

This vehicle was maintained every 3000 ☐ Days ☐ Hours ■ Miles # of Axles 2

Engine Condition: ■ Is operable ☐ Needs repair ☐ Is in Unknown Condition Jake Brake: ☐ Yes ■ No

Engine Repairs needed: _____

Transmission Manufacture: Allison (3500_RDS_P) ■ Automatic ☐ Manual 5 Speed

Transmission Condition is: ■ Operable ☐ Needs Repair ☐ Unknown ☐ Rebuilt (Date: _____)

Transmission Repairs Needed: _____

Exterior: Color White **Windows**: ■ No Cracked Glass ☐ Cracked _____

Minor: ■ Dents ■ Scratches ■ Dings **Tire Condition**: ☐ Low_____ ☐ Flat_____

Damage to: _____

Additional Damage to: _____

Decals: ☐ None ☐ Have been sprayed ■ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Capacity: 5-8 cu. yds. Loader: ☐ Front ☐ Side Electronic Tarp: ☐ Yes ■ No Condition: _____

Interior: Color Gray ☐ Cloth ■ Vinyl ☐ Leather

Damage to Seats: _____

Damage to Dash/Floor: _____

Radio: Brand International ☐ AM ■ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

■ Cruise Control ■ Tilt Steering ☐ Remote Mirrors **Airbags:** ☐ Driver's Side ☐ Dual

■ AC ☐ No AC AC Condition: ■ Cold ☐ Unknown **Power:** ■ Windows ■ Doorlocks ■ Steering ☐ Seats

Additional Equipment: Manufacturer: Monroe Model: _____

Serial # _____ Description: Monroe front plow, wing, underbody scraper, and auger system

Equipment Condition: ■ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Other Equipment: 1-11' HEIL dump body (model SLB-316), 12' MP41R11-ISCT reversible front plow, 9' wing plow, 10' scraper, stainless steel sander system

Location of Asset: 9401 Hickman Road, Urbandale Iowa, 50322

For more information contact: Patrick Halsey, City of Urbandale, Fleet Supervisor