Vehicle Inspection Form

Inventory ID:	Asset Number: 0610650	Fair Market Value: $15,000.00

Short Description:
Year 2020   Make INTERNATIONAL   Model TRACTOR HV613 SINGLE AXLE

VIN: 3HSERTZR8LN849939   **Title:** ☐ Clean Title   ☐ Salvage Title   ☐ No Title
☐ Court Documents Only   ☑ SF97 Form   ☐ Other

Odometer: 395642   ☑ Miles ☐ Kilometers ☐ Hours   **Odometer Accurate?** ☑ Yes ☐ No ☐ Unknown

Long Description:
This Vehicle: ☐ Starts ☑ Starts with a Boost & ☐ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: ____ L, V _____   ☐ Gas ☑ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☐ Needs repair ☑ is in unknown condition

Repairs needed: MAJOR ACCIDENT UNKNOWN ISSUES, PREVIOUSLY STARTED AFTER ACCIDENT

This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: 9/24/2025   Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☑ Automatic ☐ Manual ____ Speed   Condition: ☐ Operable ☐ Needs repair ☑ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☑ 2 Wheel Drive ☐ 4 Wheel Drive   Condition: _____

Exterior: Color: WHITE   Windows: ☐ No Cracked Glass ☐ Cracked _____

Minor: ☑ Dents ☑ Scratches ☐ Dings   Tire Condition: WORN   Tread: ____ #Flat ____ Hubcaps # ____

Major Damage to: MAJOR ACCIDENT DAMAGE / UNKNOWN FRAME DAMAGE

Additional Damage: FRONT END DAMAGE / D/S HEAVY DAMAGE / DEF TANK & AIR TANKS DAMAGED

Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color GRAY   ☐ Cloth ☑ Vinyl ☐ Leather

Damage to Seats: _____

Damage to Dash/Floor: _____

Radio: ☑ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☑ Unknown ☐ No AC   Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☑ Steering ☑ Windows ☑ Door Locks ☐ Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____