

Vehicle Inspection Form

Inventory ID:		Asset Number: 3920184		Fair Market Value: \$22,000	
Short Description: Year 2023 Make FORD Model Maverick XLT SuperCrew					
VIN: 3FTTW8F99PRA12416		Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other			
Odometer: 111		<input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown			
Long Description: This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs/Drivable <input checked="" type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: 4-2.0 L, V4 <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: Repairs needed to rear passenger side door, bed and rear/tailgate This vehicle was maintained every N/A <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles/Kilometers Date Removed from Service: 12/12/2025 Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual ____ Speed Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition Repairs Needed: We believe transmission is still good. Will drive onto your trailer. Drivetrain: <input type="checkbox"/> 2 Wheel Drive <input checked="" type="checkbox"/> 4 Wheel Drive Condition: _____ Exterior: Color: Gray Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked Minor: <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Good Tread: Good #Flat 0 Hubcaps # 4 Major Damage to: Rear Passenger door, bed and rear/tailgate Additional Damage: Unknown Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input type="checkbox"/> Have been Removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes Interior: Color Gray <input type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: None Damage to Dash/Floor: None Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input checked="" type="checkbox"/> Cruise Control <input type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input type="checkbox"/> Seats Additional Equipment: N/A Manufacturer _____ Model _____ Serial # _____ <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand _____ <input type="checkbox"/> Hitch: Type _____ Location of Asset: 3131 Wyandotte St, Kansas City, MO 64111					