

Vehicle Inspection Form

101

Inventory ID: _____ Asset Number: 4910466 Fair Market Value: _____

Short Description:
 Year _____ Make DODGE Model DURANGO AWD

VIN: C4RDJA69EC570866 Title: Clean Title Salvage Title No Title
 Court Documents Only SF97 Form Other

Odometer: _____ Miles Kilometers Hours Odometer Accurate? Yes No Unknown

Long Description:
 This Vehicle: Starts Starts with a Boost & Runs/Drivable Engine Runs Does Not Run For Parts Only
 Engine- Type: _____ L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid
 Engine Condition: Runs Needs repair is in unknown condition

Repairs needed: _____

This vehicle was maintained every _____ Days Hours Miles/Kilometers

Date Removed from Service: _____ Maintenance Records: Available Not Available For Inspection

Transmission: Automatic Manual _____ Speed Condition: Operable Needs repair Is Unknown Condition

Repairs Needed: _____

Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition: AWD

Exterior: Color: Gray Windows: No Cracked Glass Cracked
 Minor: Dents Scratches Dings Tire Condition: _____ Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to: FRONT

Additional Damage: _____

Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No impressions

Emergency equip: None Has been removed & There are holes in the exterior There are no holes

Interior: Color _____ Cloth Vinyl Leather

Damage to Seats: NO

Damage to Dash/Floor: NO

Radio: Stock or Brand & Model: _____ AM AM/FM AM/FM Cassette AM/FM CD

AC Condition: Cold Unknown No AC Air Bags: Driver's Side Dual

Cruise Control Tilt Steering Remote Mirrors Climate Control

Power: Steering Windows Door Locks Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

Tool Box Light Bar Ladder Rack Utility Body: Brand _____ Hitch: Type _____

Location of Asset: _____