

Vehicle Inspection Form

Inventory ID: 3910379	Asset Number: 3910379	Fair Market Value:
------------------------------	------------------------------	---------------------------

Short Description:
 Year 2013 Make Dodge Model Durango AWD

VIN:

1	C	4	S	D	J	F	T	9	D	C	6	7	0	3	9	5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

 Title Restriction: ☐ Y ☒ N

Odometer:

1	3	8	1	9	7
---	---	---	---	---	---

☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____

Long Description:
 This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only
Engine- Type: 5.7 L, V 8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid
 Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition
 Repairs needed: _____
 This vehicle was maintained every 180 ☒ Days ☐ Hours ☐ Miles
 Date Removed From Service: 1/25 Maintenance Records: ☐ Available ☒ Not Available For Inspection
Transmission: ☒ Automatic ☐ Manual ___ Speed Condition: ☒ Operable ☒ Needs repair ☐ Is Unknown Condition
 Repairs Needed: _____
Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: needs repairs

Exterior: Color: Black Windows: ☒ No Cracked Glass ☐ Cracked _____
 Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: good Tread: _____ #Flat _____ Hubcaps # _____
 Major Damage to: _____
 Additional Damage: _____
 Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions
 Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color _____ ☒ Cloth ☐ Vinyl ☐ Leather
 Damage to Seats: dirty
 Damage to Dash/Floor: dirty
 Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD
☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual
☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control
 Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment: _____
 Manufacturer _____ Model _____ Serial # _____
☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: 1530 Greensmark dr Houston TX 77067
For more information contact: 281-8750246 Cesar Flores
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.