

Heavy Equipment Inspection Form

Inventory ID: _____	Asset Number <u>0610144</u>	Fair Market Value: _____
Short Description: Year <u>2020</u> Manufacturer <u>International</u> Model <u>HU613 SBA</u>		
Long Description: Equipment Serial # <u>1H5ERT2RLH357438</u> [Required for all Marketing]		
This Equipment: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Is Operable <input checked="" type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only Engine: <u>1244L, V</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel engine Engine: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles <u>342,321</u> This vehicle was maintained every <u>13 weeks</u> <input type="checkbox"/> Hours		
Engine Manufacture: <u>International</u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Engine Repairs needed: <u>Engine should be Operable</u>		
Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Speed _____ Transmission: <input type="checkbox"/> Hours _____ <input type="checkbox"/> Miles _____ Transmission Manufacture: <u>Allison</u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown Transmission Repairs Needed: _____		
Drivetrain: <input type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: _____ Date Removed From Service: _____ Maintenance Records: <input type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Exterior: Color <u>white</u> Windows: <input checked="" type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked _____ Minor <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <u>0</u> <input type="checkbox"/> Flat <u>0</u> Damage to: <u>Front end + possible frame Damage</u> Additional Damage to: _____		
# Of Wheels _____ # Of Axles _____ # Of Tracks _____ Dimensions: _____ Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions		
Interior: Color <u>grey</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>Interior dirty but no Tears</u> Damage to Dash/ Floor: _____ Radio: Brand <u>Stock Radio</u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input checked="" type="checkbox"/> Cruise Control Power: <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats AC <input checked="" type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown		
Additional Equipment: Manufacturer _____ Model _____ Serial # _____ Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Description: _____ _____		
Location of Asset: _____ For more information contact: _____		