

Vehicle Inspection Form

115

Inventory ID:

Asset Number:

Fair Market Value:

6914725

Short Description:

Year 05

Make Ford

Model Taurus

SE

VIN: 1FAHP532X6A118123

Title:

☐ Clean Title

☐ Salvage Title

☐ No Title

☐ Court Documents Only

☐ SF97 Form

☐ Other

Odometer: 258787

☒ Miles

☐ Kilometers

☐ Hours

Odometer Accurate?

☐ Yes

☐ No

☐ Unknown

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: ☐ L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed:

This vehicle was maintained every ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual ☐ Speed Condition: ☐ Operable ☐ Needs repair ☒ Is Unknown Condition

Repairs Needed:

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior:

Color: white

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings

Tire Condition: Tread: #Flat Hubcaps #

Major Damage to:

Additional Damage: paint

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color: Brown

☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: NO

Damage to Dash/Floor: NO

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☐ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats

Additional Equipment:

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand Hitch: Type

Location of Asset: