

Work Order 109301 (FLEET) SERVICE>TRANS FILTER/FLUSH & FUEL,DOOR
CHIME STAYS ON AFTER KEY PULLED

Status Closed

Scheduled Start Date 09/24/2007
Scheduled End Date 09/24/2007
WO Type CM



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C) PARK

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/25/2007

Estimated Hours 2

Estimated Cost 0.00

Actual Cost 309.43

Date Completed 09/25/2007

Work Order Comments

GHUDSPETH [09/25/2007 15:45]:

CK. LIST ON FILE,DG>INSTALL FRT. PADS (ROTOR TURN NOT NEEDED)CKED REAR BRAKES & R&R BAD CONNECTION ON CHIME SWITCH,TRANS FLUSH. MJM>SERVICE,LIGHTS,FUEL.OIL & TRANS FILTER.

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	2	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donnie Gittins	09/25/2007	N	3	32.00	96.00
		Mike Manning	09/25/2007	N	3.5	32.00	112.00
						Subtotal	208.00
						Total	208.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
	CMF	F06020121 (FLEET)	TRANSMISSION FLUSH KIT WYNN 10212	EACH	1	13.60	13.60
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	5	1.25	6.27
	CMF	F0358968 (FLEET)	TRANS FILTER 58968	EACH	1	14.55	14.55
	CMF	F0333595 (FLEET)	FUEL FILTER 33595	EACH	1	5.32	5.32
	CMF	ATF (FLEET)	DEXTRON (QT)	QT	12	1.16	13.96
	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	2.73	2.73
	CMF	F0333595 (FLEET)	FUEL FILTER 33595	EACH	-1	5.32	-5.32
	CMF	F0333296 (FLEET)	FUEL FILTER 33296	EACH	1	4.89	4.89
	CMF	F10020197 (FLEET)	BRAKE PAD MX756	EACH	1	40.92	40.92

Work Order 109301 (FLEET) SERVICE>TRANS FILTER/FLUSH & FUEL,DOOR
CHIME STAYS ON AFTER KEY PULLED
Status Closed

Scheduled Start Date 09/24/2007
Scheduled End Date 09/24/2007
WO Type CM



10	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT QT)
----	-----	--------------	---------------------------------------

2	1.25	2.51
Subtotal	<hr/>	
	101.43	
Total	<hr/>	
	101.43	

Work Order 110655 (FLEET) FLUSH PUMP,CK.
OPERATION,LEAKS,LIGHTS,CRACKS,ETC.
Status Closed

Scheduled Start Date 10/22/2007
Scheduled End Date 10/22/2007
WO Type CM



Parent Work Order
Department PARK PARKS DEPT
PM Code
Cost Code GENERAL GENERAL BUDGET
Problem Code
Reported By
Project
Standard WO

Class FT-ANN
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location PARK (FLEET-C) PARK
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 10/22/2007

Estimated Hours 1
Estimated Cost 0.00
Actual Cost 54.71
Date Completed 10/22/2007

Work Order Comments

MHUEBNER [10/22/2007 13:09]:
10/22/07 - (DLM) Flush pump & cylinders/add oil to fill/check operation/check lights/no cracks found.

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	10/22/2007	N	1.5	32.00	48.00
						Subtotal	48.00
						Total	48.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F0315619 (FLEET)	MEYER PLOW FILTER 15619	EACH	1	3.24	3.24
	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	1	3.47	3.47
						Subtotal	6.71
						Total	6.71

Work Order 130793 (FLEET) ABS LIGHT ON

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/07/2008

Scheduled Start Date 05/07/2008

Scheduled End Date 05/07/2008

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1.5

Estimated Cost 0.00

Actual Cost 118.79

Date Completed 05/08/2008

Work Order Custom Fields

Write current Meter Value 25864

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1.5	1		
----	------	-----	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	05/07/2008	N	2.5	32.00	80.00
						Subtotal	80.00
						Total	80.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N13252 (FLEET)	F81Z2C205AD ABS SENSOR	EA	1	38.79	38.79
						Subtotal	38.79
						Total	38.79

Work Order 162566 (FLEET) SC JUMP START NEB AVE & 35ST

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/09/2008

Scheduled Start Date 07/09/2008

Scheduled End Date 07/09/2008

WO Type CM

Class FT-SC

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 113.69

Date Completed 07/09/2008

Work Order Comments

MHUEBNER [07/09/2008 11:17]:

7/9/08 (MJM) Replaced battery.

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Mike Manning	07/09/2008	N	1	33.00	33.00
						Subtotal	33.00
						Total	33.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02110015 (FLEET)	GROUP 65 BATTERY AC DELCO 65FLEET	EACH	1	80.69	80.69
						Subtotal	80.69
						Total	80.69

Work Order 178428 (FLEET) FLUSH PUMP,CK.OPERATION,BIT,CRACKS ETC.

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 10/17/2008

Scheduled End Date 10/17/2008

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 79.42

Date Completed 10/17/2008

Work Order Comments

MHUEBNER [10/17/2008 13:53]:

10/17/08 (BA) Taped wires. Changed 2 fuses. Added plow oil.

Work Order Custom Fields

Write current Meter Value 27026

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Harry "Butch" Albright	10/17/2008	N	2	33.00	66.00
						Subtotal	66.00
						Total	66.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02060042 (FLEET)	FUSE ATM-10	EACH	1	0.59	0.59
	CMF	F02060043 (FLEET)	FUSE ATM-15	EACH	1	0.60	0.60
	CMF	F02010183 (FLEET)	LIGHT BULB BP1210/H4	EACH	1	8.18	8.18
	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	1.5	2.69	4.04
						Subtotal	13.42
						Total	13.42

Work Order 178498 (FLEET) L/REAR B/LIGHT INOPP.

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 10/20/2008

Scheduled End Date 10/20/2008

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 0.5

Estimated Cost 0.00

Actual Cost 9.11

Date Completed 10/20/2008

Work Order Custom Fields

Write current Meter Value 27045

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	0.5	1		
----	------	-----	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Harry "Butch" Albright	10/20/2008	N	0.25	33.00	8.25
						Subtotal	8.25
						Total	8.25

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02010291 (FLEET)	BULB 3357	EACH	1	0.86	0.86
						Subtotal	0.86
						Total	0.86

Work Order 179905 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/24/2008

Scheduled Start Date 11/20/2008

Scheduled End Date 11/20/2008

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1.5

Estimated Cost 0.00

Actual Cost 68.31

Date Completed 11/24/2008

Work Order Comments

MHUEBNER [11/24/2008 12:19]:

11/24/08 (RT) Brakes: front 6/32; rear 6/32.

Replaced both upper & lower ball joints.

Front rotors: rust pits on braking surface. Replaced rotors.

Work Order Custom Fields

Write current Meter Value 27306

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1.5	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	11/24/2008	N	1.5	33.00	49.50
						Subtotal	49.50
						Total	49.50

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	3.79	3.79
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	1.86	13.02
						Subtotal	18.81
						Total	18.81

Work Order 179933 (FLEET) R&R ALL B/JOINTS,FRT. PADS/ROTORS

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/24/2008

Scheduled Start Date 11/21/2008

Scheduled End Date 11/21/2008

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 3

Estimated Cost 0.00

Actual Cost 492.70

Date Completed 11/24/2008

Work Order Comments

MHUEBNER [11/24/2008 12:17]:

11/24/08 (RT) Replaced all 4 ball joints & repacked wheel bearings. Replaced front rotors.

Work Order Custom Fields

Write current Meter Value 27306

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	3	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	11/24/2008	N	4	33.00	132.00
						Subtotal	132.00
						Total	132.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N11852 (FLEET)	F5UZ3V049AA BALL JT	EA	2	43.67	87.34
	CMF	N11851 (FLEET)	F6TZ3V050DA BALL JT	EA	2	62.20	124.40
	CMF	N14815 (FLEET)	81-125651 FRT ROTORS	EA	2	74.48	148.96
						Subtotal	360.70
						Total	360.70

Work Order 181864 (FLEET) SPINNER INOP./CHAIN BROKEN

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/19/2008

Scheduled Start Date 12/19/2008

Scheduled End Date 12/19/2008

WO Type CM

Class SNOW

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1.5

Estimated Cost 0.00

Actual Cost 33.00

Date Completed 12/19/2008

Work Order Comments

MHUEBNER [12/22/2008 09:43]:

12/19/08 (DLM) Inspect spinner drive - lower chain - fell off.
 Removed shield for access/inspect chain - good - no damage.
 Loosen drive/reinstall chain/retighten.
 Check for proper operation.

Work Order Custom Fields

Write current Meter Value 27531

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1.5	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	12/19/2008	N	1	33.00	33.00
						Subtotal	33.00
						Total	33.00

Work Order 183088 (FLEET) s/c to fairmont lodge, stuck, blade won't raise

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 01/12/2009

Scheduled End Date 01/12/2009

WO Type CM

Class SNOW

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 145.24

Date Completed 01/12/2009

Work Order Comments

MHUEBNER [01/13/2009 08:53]:

1/12/08 (DG) Replaced o-ring for solenoid valve: o-ring split & was blocking oil passage. Clean filter & top off fluid. Installed weather pack connector on solenoid harness.

Work Order Custom Fields

Write current Meter Value 27740 miles

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donnie Gittins	01/12/2009	N	3	34.00	102.00
		Harold Orth	01/12/2009	N	1	34.00	34.00
						Subtotal	136.00
						Total	136.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02020058 (FLEET)	WEATHERPACK HOUSING 9H3MW	EACH	1	1.16	1.16
	CMF	F02030044 (FLEET)	FEMALE PIN SOCKET 91416FW	EACH	3	0.31	0.93
	CMF	F02020056 (FLEET)	WEATHERPACK HOUSING 9H3FW	EACH	1	1.85	1.85
	CMF	F10080226 (FLEET)	SEAL 9SGN	EACH	6	0.30	1.80
	CMF	F02030045 (FLEET)	MALE PIN 91416MW	EACH	3	0.31	0.93
	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	1	2.57	2.57
							Subtotal



Work Order 183088 (FLEET) s/c to fairmont lodge, stuck, blade won't raise

Status Closed

Scheduled Start Date 01/12/2009

Scheduled End Date 01/12/2009

WO Type CM



Total

 9.24

Work Order 185688 (FLEET) PLOW WONT ANGLE LEFT OR RIGHT/PLOW LIGHT COVER BROKEN
Status Closed

Scheduled Start Date 02/14/2009
Scheduled End Date 02/14/2009
WO Type CM



Parent Work Order
Department PARK PARKS DEPT
PM Code
Cost Code GENERAL GENERAL BUDGET
Problem Code
Reported By
Project
Standard WO

Class SNOW
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location PARK (FLEET-C) PARK
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started

Estimated Hours 1
Estimated Cost 0.00
Actual Cost 230.64
Date Completed 02/19/2009

Work Order Comments

MHUEBNER [02/19/2009 16:09]:
 2/19/09 (SR / MJM) Replaced right valve.
 Replaced plow light bulb.

Work Order Custom Fields

Write current Meter Value 28063

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Mike Manning	02/19/2009	N	2	34.00	68.00
		Steve Ross	02/19/2009	N	1	34.00	34.00
						Subtotal	102.00
						Total	102.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N15387 (FLEET)	1306065 C VALVE	EA	1	100.00	100.00
	CMF	F02080151 (FLEET)	COIL GREEN WIRE 15430	EACH	1	18.58	18.58
	CMF	F02010183 (FLEET)	LIGHT BULB BP1210/H4	EACH	1	10.06	10.06
						Subtotal	128.64
						Total	128.64

Work Order 194095 (FLEET) FLAT TIRE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 06/24/2009

Scheduled End Date 06/24/2009

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 20.22

Date Completed 06/24/2009

Work Order Custom Fields

Write current Meter Value 29115

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Rocco Marcantonio	06/24/2009	N	0.5	34.00	17.00
						Subtotal	17.00
						Total	17.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F05090027 (FLEET)	1.25" TR-416 TUBELESS CLAMP- IN VALVE STEM 90-416	EACH	1	3.22	3.22
						Subtotal	3.22
						Total	3.22

Work Order 196039 (FLEET) NO BRAKES FOR TRAILER (ELECT.)

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/11/2009

Scheduled Start Date 08/11/2009

Scheduled End Date 08/11/2009

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 62.53

Date Completed 08/12/2009

Work Order Comments

DMCDERMOTT [08/12/2009 06:45]:

LH 8/10 Replaced brake away switch and blown fuse in engine compartment. Had bad connection at trailer plug.

Work Order Custom Fields

Write current Meter Value 29950

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	08/11/2009	N	1.5	35.00	52.50
						Subtotal	52.50
						Total	52.50

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F031182236 (FLEET)	OIL FILTER 1182236 WIX 57035	EACH	1	1.57	1.57
	CMF	F02060042 (FLEET)	FUSE ATM-10	EACH	1	0.58	0.58
	CMF	F02040206 (FLEET)	TRAILER BREAKAWAY SWITCH 89102	EACH	1	7.88	7.88
						Subtotal	10.03
						Total	10.03

Work Order 196706 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 08/31/2009

Scheduled End Date 08/31/2009

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1.5

Estimated Cost 0.00

Actual Cost 65.42

Date Completed 08/31/2009

Work Order Custom Fields

Write current Meter Value 30325

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1.5 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Rocco Marcantonio	08/31/2009	N	1	35.00	35.00
						Subtotal	35.00
						Total	35.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	3.79	3.79
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	1.90	13.31
	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
	CMF	F0346418 (FLEET)	AIR FILTER 46418	EACH	1	11.33	11.33
						Subtotal	30.42
						Total	30.42

Work Order 196764 (FLEET) REPLACE TIRES, CHECK EXHAUST LEAK

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/31/2009

Scheduled Start Date 08/31/2009

Scheduled End Date 08/31/2009

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety Y

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 4,497.63

Date Completed 09/17/2009

Work Order Comments

MHUEBNER [09/17/2009 13:50]:

R&R rear tires.

Replaced exhaust manifolds.

Had to remove engine to fix exhaust leak.

Still unable to close this workorder due to problems with closing PO# 13665. (Glenda has talked to Pat about this PO)

Work Order Custom Fields

Write current Meter Value 30325

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	09/10/2009	N	2	35.00	70.00
		Lynn Hammermeister	09/11/2009	N	2	35.00	70.00
		Lynn Hammermeister	09/16/2009	N	2	35.00	70.00
		Lynn Hammermeister	09/17/2009	N	2	35.00	70.00
		Rocco Marcantonio	09/10/2009	N	1	35.00	35.00
		Rocco Marcantonio	09/17/2009	N	1	35.00	35.00
		Steve Ross	08/31/2009	N	1	35.00	35.00
		Steve Ross	08/31/2009	N	1	35.00	35.00
		Steve Ross	09/07/2009	N	4	35.00	140.00
		Steve Ross	09/08/2009	N	7	35.00	245.00
		Steve Ross	09/09/2009	N	4	35.00	140.00
		Steve Ross	09/10/2009	N	4	35.00	140.00
		Steve Ross	09/10/2009	N	7	35.00	245.00
		Steve Ross	09/11/2009	N	3	35.00	105.00
		Steve Ross	09/14/2009	N	7	35.00	245.00
		Steve Ross	09/15/2009	N	4	35.00	140.00
Steve Ross	09/16/2009	N	7	35.00	245.00		
Steve Ross	09/17/2009	N	3	35.00	105.00		

Work Order 196764 (FLEET) REPLACE TIRES, CHECK EXHAUST LEAK

Status Closed

Scheduled Start Date 08/31/2009

Scheduled End Date 08/31/2009

WO Type CM



Subtotal	2,170.00
Total	2,170.00

Actual Parts							
Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N10077 (FLEET)	LT215/85R16 FS TRANSFORCE AT	EA	4	91.15	364.60
	CMF	N16683 (FLEET)	YC2Z9430AA RH EXH MANIFOLD	EA	1	477.49	477.49
	CMF	N13301 (FLEET)	W705374S901 STUD	EA	4	8.63	34.52
	CMF	N16684 (FLEET)	YC2Z9431BA EXH MANIFOLD	EA	1	574.99	574.99
	CMF	N11175 (FLEET)	YC2Z9448A EXH MANIFOLD GASKET	EA	2	24.60	49.20
	CMF	N16682 (FLEET)	F6TZ5C226BA EXH PIPE GASKET	EA	1	4.23	4.23
	CMF	N11177 (FLEET)	W701706S2 NUT	EA	20	1.31	26.20
	CMF	N11175 (FLEET)	YC2Z9448A EXH MANIFOLD GASKET	EA	2	15.98	31.96
	CMF	N11069 (FLEET)	N811313S431 STUDS	EA	20	1.68	33.60
	CMF	F040400C2 (FLEET)	3/8-16 UNC HEX NUT TUFF-TORQ A102	EACH	8	0.12	0.95
	CMF	N14271 (FLEET)	F75Z6020CA VALVE COVER GASKET	EA	1	3.93	3.93
	CMF	N16721 (FLEET)	4C2Z9461AA GASKET	EA	1	13.53	13.53
	CMF	N14270 (FLEET)	F75Z6020AA VALVE COVER GASKET	EA	1	4.46	4.46
	CMF	N14272 (FLEET)	F75Z6020BA GASKET	EA	1	4.30	4.30
	CMF	N14276 (FLEET)	3L3Z6065AA HEAD BOLTS	EA	12	4.60	55.20
	CMF	F02050054 (FLEET)	SPARK PLUG SP-479 AGSF22WM	EACH	10	4.79	47.90
	CMF	N14275 (FLEET)	F7TZ12A402AA BOOT	EA	10	9.75	97.50
	CMF	N16719 (FLEET)	4C3Z6051AA HEAD GASKET	EA	1	48.36	48.36
	CMF	N16720 (FLEET)	1C2Z9439AAEXH MANIFOLD	EA	4	9.75	39.00
	CMF	12797 (FLEET)	OUTSIDE LABOR	EACH	1	95.00	95.00
	CMF	F05010078 (FLEET)	P195/60R15 TIRE	EACH	2	65.00	130.00
	CMF	N16743 (FLEET)	6651310 RETAINER	EA	1	4.49	4.49
	CMF	F05010078 (FLEET)	P195/60R15 TIRE	EACH	-2	65.00	-130.00
	CMF	N14271 (FLEET)	F75Z6020CA VALVE COVER GASKET	EA	1	4.91	4.91
	CMF	F02050054 (FLEET)	SPARK PLUG SP-479 AGSF22WM	EACH	10	4.79	47.90
	CMF	N16720 (FLEET)	1C2Z9439AAEXH MANIFOLD	EA	4	9.75	39.00
	CMF	N16719 (FLEET)	4C3Z6051AA HEAD GASKET	EA	1	48.36	48.36
	CMF	N14275 (FLEET)	F7TZ12A402AA BOOT	EA	10	9.75	97.50
	CMF	N14270 (FLEET)	F75Z6020AA VALVE COVER GASKET	EA	1	4.91	4.91
	CMF	N14272 (FLEET)	F75Z6020BA GASKET	EA	1	4.91	4.91
	CMF	N14276 (FLEET)	3L3Z6065AA HEAD BOLTS	EA	12	4.60	55.20
	CMF	N16721 (FLEET)	4C2Z9461AA GASKET	EA	1	13.53	13.53
			Subtotal				2,327.63
			Total				2,327.63

Work Order 197627 (FLEET) REPAIR DAMAGE FROM ACCIDENT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 09/17/2009

Scheduled End Date 09/17/2009

WO Type CM

Class FT-DAM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 315.20

Date Completed 09/25/2009

Work Order Comments

DGITTINS [09/25/2009 11:21]:

DAMAGE TO LF FENDER FROM LETTING HOIST DOWN ON CREEPER. REPAIRED BY CUSTOM AUTO

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N10511 (FLEET)	BODY REPAIRS	EA	1	315.20	315.20
						Subtotal	315.20
						Total	315.20

Work Order 197909 (FLEET) LF TIRE IS FLAT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/24/2009

Scheduled Start Date 09/24/2009

Scheduled End Date 09/24/2009

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 0.5

Estimated Cost 0.00

Actual Cost 35.24

Date Completed 09/24/2009

Work Order Comments

MHUEBNER [09/24/2009 12:11]:

9/24/09 (DLM) pull wheel. rim rusted at seal - cleaned up - patched hole where indicated - remount. Check for rim leak - sealed at this time.

Work Order Custom Fields

Write current Meter Value 30434

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	0.5	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	09/24/2009	N	1	35.00	35.00
						Subtotal	35.00
						Total	35.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F05090079 (FLEET)	HAMILTON DURALAST 8" WHEEL USED 5VJ82	EACH	1	0.24	0.24
						Subtotal	0.24
						Total	0.24

Work Order 208936 (FLEET) SHIFTER WONT GO INTO PARK

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/29/2010

Scheduled Start Date 03/29/2010

Scheduled End Date 03/29/2010

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 35.00

Date Completed 03/30/2010

Work Order Comments

DMCDERMOTT [03/30/2010 08:06]:

LH 3/29 BOLTS CAME LOOSE ON BOTTOM OF SHIFT COLLAR. PUT LOCK TIGHT ON BLOLTS AND TIGHTEN THEM UP.

Work Order Custom Fields

Write current Meter Value 32956

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	03/29/2010	N	1	35.00	35.00
						Subtotal	35.00
						Total	35.00

Work Order 212316 (FLEET) SERVICE, TRANS FLUSH, REPLACE FUEL FILTER

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/15/2010

Scheduled Start Date 06/14/2010

Scheduled End Date 06/14/2010

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 2

Estimated Cost 0.00

Actual Cost 135.17

Date Completed 06/15/2010

Work Order Comments

DGITTINS [06/15/2010 08:48]:

INSP. SHEET COMPLETED AND ON FILE

Work Order Custom Fields

Write current Meter Value 34352

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	2	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ryan Lincoln	06/15/2010	N	2	35.00	70.00
						Subtotal	70.00
						Total	70.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	3.21	3.21
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	1.75	12.28
	CMF	F06020121 (FLEET)	TRANSMISSION FLUSH KIT WYNN 10212	EACH	1	14.35	14.35
	CMF	ATF (FLEET)	DEXTRON (QT)	QT	15	1.76	26.39
	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
	CMF	F0333296 (FLEET)	FUEL FILTER 33296	EACH	1	6.94	6.94
						Subtotal	65.17
						Total	65.17

Work Order 212319 (FLEET) RH RUNNING BOARD LOOSE, RUNS REAL ROUGH, RH SEATBELT WONT RELEASE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/16/2010

Scheduled Start Date 06/14/2010

Scheduled End Date 06/14/2010

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 459.98

Date Completed 06/16/2010

Work Order Comments

DGITTINS [06/16/2010 10:20]:

REPAIRED RUNNING BOARD, REPLACED IGN. COIL, SPARK PLUGS AND MASS AIR FLOW SENSOR

Work Order Custom Fields

Write current Meter Value 34352

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Harold Orth	06/16/2010	N	1	35.00	35.00
		Robert Tacke	06/16/2010	N	1	35.00	35.00
					Subtotal		70.00
					Total		70.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F04 (FLEET)	MISC HARDWARE - bolts, wire, connectors, fasteners, welding supply	EACH	1	104.07	104.07
	CMF	F02010134 (FLEET)	RED MARKER LIGHT ROUND 50-10202R3	EACH	1	1.55	1.55
	CMF	F09020001 (FLEET)	NUMBERS - ASSET DECAL	EACH	5	0.46	2.32
	CMF	F02050054 (FLEET)	SPARK PLUG SP-479 AGSF22WM	EACH	10	3.63	36.27
	FLEET MAIN	N17374 (FLEET)	YC2Z12B579BBRM MAFS	EA	1	176.33	176.33
	FLEET MAIN	F02050079 (FLEET)	IGNITION COIL 3W7Z12029AA	EACH	1	69.44	69.44



Work Order 212319 (FLEET) RH RUNNING BOARD LOOSE, RUNS REAL ROUGH,
RH SEATBELT WONT RELEASE

Status Closed

Scheduled Start Date 06/14/2010

Scheduled End Date 06/14/2010

WO Type CM



Subtotal	<hr/>	389.98
Total	<hr/>	389.98

Work Order 214986 (FLEET) VIBRATION IN STEERING WHEEL AT 30MPH

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/08/2010

Scheduled Start Date 09/07/2010

Scheduled End Date 09/07/2010

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 92.66

Date Completed 09/08/2010

Work Order Comments

DGITTINS [09/08/2010 08:49]:

REPLACED REAR U-JOINT FOR IT WAS RUSTED OUT

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	09/08/2010	N	2	37.00	74.00
						Subtotal	74.00
						Total	74.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F10070103 (FLEET)	U-JOINT 331	EACH	1	14.50	14.50
	CMF	F10070103 (FLEET)	U-JOINT 331	EACH	-1	14.94	-14.94
	CMF	F10070102 (FLEET)	U-JOINT 330	EACH	1	19.10	19.10
						Subtotal	18.66
						Total	18.66

Work Order 219331 (FLEET) CHECK OVER FOR WINTER TIRE CHAINS

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/23/2010

Scheduled Start Date 11/23/2010

Scheduled End Date 11/23/2010

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 356.28

Date Completed 11/30/2010

Work Order Comments

JSTOTTS [11/30/2010 14:58]:

RIGHT PLOW LIGHT INOP (PARTS ORDERED); CHECKED OVER FOR WINTER; CHECK & R&R SWITCH FOR SPREADER & CHANGED OIL IN PUMP

Work Order Custom Fields

Write current Meter Value 37869

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Winters	11/23/2010	N	1	37.00	37.00
						Subtotal	37.00
						Total	37.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	2	2.44	4.89
	CMF	F02040087 (FLEET)	TOGGLE SWITCH TG6260	EACH	1	5.55	5.55
	CMF	F04030086 (FLEET)	TIRE CHAIN 2819QC	EACH	1	113.99	113.99
	CMF	F02010570 (FLEET)	BOSS PLOW RH HEADLIGHT 07224	EA	1	194.85	194.85
						Subtotal	319.28
						Total	319.28

Work Order 221397 (FLEET) PLOW LIGHT BULB/CUTTING EDGE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 01/14/2011

Scheduled End Date 01/14/2011

WO Type CM

Class FT-PARTS

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 0

Estimated Cost 0.00

Actual Cost 202.16

Date Completed 01/31/2011

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	PARTS	0	1		
----	-------	---	---	--	--



Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02010183 (FLEET)	LIGHT BULB BP1210/H4	EACH	2	10.06	20.11
	CMF	F02010089 (FLEET)	MARKER LIGHT BULB 3157NA	EACH	2	1.03	2.05
	CMF	F08090028 (FLEET)	8 FT BIT FOR MEYERS POLY PLOW 09133	EACH	1	179.99	179.99
						Subtotal	202.16
						Total	202.16

Work Order 221797 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/24/2011

Scheduled Start Date 01/24/2011

Scheduled End Date 01/24/2011

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 53.11

Date Completed 01/31/2011

Work Order Comments

DMCDERMOTT [01/31/2011 10:00]:

1/24 RL Service replace plow bit, rebuild plow pump. Inspection sheet on file.

Work Order Custom Fields

Write current Meter Value 38751

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ryan Lincoln	01/24/2011	N	1	37.00	37.00
						Subtotal	37.00
						Total	37.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	1.54	10.76
	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	3.34	3.34
	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
						Subtotal	16.11
						Total	16.11

Work Order 223377 (FLEET) LIGHT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 02/16/2011

Scheduled End Date 02/16/2011

WO Type CM

Class FT-PARTS

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 0

Estimated Cost 0.00

Actual Cost 1.38

Date Completed 02/16/2011

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	PARTS	0	1		
----	-------	---	---	--	--



Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02010291 (FLEET)	BULB 3357	EACH	1	1.38	1.38
						Subtotal	1.38
						Total	1.38

Work Order 232113 (FLEET) TRAILER BRAKES INOP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/08/2011

Scheduled Start Date 04/08/2011

Scheduled End Date 04/08/2011

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 111.00

Date Completed 04/13/2011

Work Order Comments

JSTOTTS [04/13/2011 13:43]:

REPLACED TRAILER PLUG & ALSO FOUND BAD GROUND ON TRAILER

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	04/08/2011	N	3	37.00	111.00
						Subtotal	111.00
						Total	111.00

Work Order 235745 (FLEET) GAS CAP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 06/16/2011

Scheduled End Date 06/16/2011

WO Type CM

Class FT-PARTS

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 0

Estimated Cost 0.00

Actual Cost 11.38

Date Completed 06/21/2011

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	PARTS	0	1		
					
Note					

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F10090056 (FLEET)	GAS CAP 2000 FORD 703-1718	EACH	1	11.38	11.38
						Subtotal	11.38
						Total	11.38

Work Order 237827 (FLEET) LR TAILLIGHT INOP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/01/2011

Scheduled Start Date 08/01/2011

Scheduled End Date 08/01/2011

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 10.52

Date Completed 08/01/2011

Work Order Comments

DGITTINS [08/01/2011 14:39]:

REPLACED LR BULB

Work Order Custom Fields

Write current Meter Value 41305

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	08/01/2011	N	0.25	38.00	9.50
						Subtotal	9.50
						Total	9.50

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02010290 (FLEET)	BULB 3157	EACH	1	1.02	1.02
						Subtotal	1.02
						Total	1.02

Work Order 239978 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/12/2011

Scheduled Start Date 09/12/2011

Scheduled End Date 09/12/2011

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 88.87

Date Completed 09/15/2011

Work Order Comments

JSTOTTS [09/15/2011 08:37]:
INSPECTION REPORT ON FILE

Work Order Custom Fields

Write current Meter Value 42856

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	09/12/2011	N	1.5	38.00	57.00
						Subtotal	57.00
						Total	57.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	4.03	4.03
	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	6	1.85	11.12
	CMF	F02010134 (FLEET)	RED MARKER LIGHT ROUND 50-10202R3	EACH	1	1.40	1.40
	CMF	F0346418 (FLEET)	AIR FILTER 46418	EACH	1	13.32	13.32
						Subtotal	31.87
						Total	31.87

Work Order 244908 (FLEET) HYD LEAK PLOW FITTING

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/05/2011

Scheduled Start Date 12/05/2011

Scheduled End Date 12/05/2011

WO Type CM

Class FT-PARTS

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 0

Estimated Cost 0.00

Actual Cost 52.87

Date Completed 12/29/2011

Work Order Comments

DGITTINS [12/29/2011 14:28]:

REPLACED HYD FITTING ON PLOW

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	PARTS	0	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Harold Orth	12/05/2011	N	1	40.00	40.00
						Subtotal	40.00
						Total	40.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	2	2.44	4.88
	CMF	F04010558 (FLEET)	90 ANGLE FITTING 21855 1304055	EACH	1	7.99	7.99
						Subtotal	12.87
						Total	12.87

Work Order 248418 (FLEET) SPINNER WONT TURN, SEAT BELT BUZZER KEEPS GOING OFF
Status Closed

Scheduled Start Date 02/08/2012
Scheduled End Date 02/08/2012
WO Type CM



Parent Work Order
Department PARK PARKS DEPT
PM Code
Cost Code GENERAL GENERAL BUDGET
Problem Code
Reported By DGITTINS Donnie Gittins

Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By

Project
Standard WO
Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location PARK (FLEET-C) PARK
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 02/08/2012

Estimated Hours 1
Estimated Cost 0.00
Actual Cost 289.55
Date Completed 02/22/2012

Work Order Comments

JSTOTTS [02/22/2012 08:14]:
 FOUND BAD SPOT IN SPINNER WIRING; REPLACED SEAT BELT; INSTALLED A HAND THROTTLE CABLE & START BUTTON ON REAR OF SPREADER

Work Order Custom Fields

Write current Meter Value 45383

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	02/08/2012	N	3	38.00	114.00
		Ryan Lincoln	02/08/2012	N	2	38.00	76.00
		Steve Ross	02/08/2012	N	2	38.00	76.00
						Subtotal	266.00
						Total	266.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N22197 (FLEET)	786101 SW	EA	1	3.95	3.95
	CMF	N22198 (FLEET)	786106 SW	EA	1	4.19	4.19
	CMF	N22196 (FLEET)	731-1110 CABLE	EA	1	13.55	13.55
	CMF	F02050044 (FLEET)	SPARK PLUG CJ14	EACH	1	1.86	1.86
						Subtotal	23.55
						Total	23.55

Work Order 251967 (FLEET) RH OUTSIDE DUAL FLAT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/19/2012

Scheduled Start Date 04/19/2012

Scheduled End Date 04/19/2012

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 40.45

Date Completed 04/23/2012

Work Order Comments

JSTOTTS [04/23/2012 11:52]:

REPAIRED FLAT

Work Order Custom Fields

Write current Meter Value 46507

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ryan Lincoln	04/19/2012	N	1	38.00	38.00
						Subtotal	38.00
						Total	38.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F05090001 (FLEET)	TIRE PATCH - MISC ALL SIZES	EA	1	2.45	2.45
						Subtotal	2.45
						Total	2.45

Work Order 252977 (FLEET) SERVICE, LR TIRE FLAT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/08/2012

Scheduled Start Date 05/08/2012

Scheduled End Date 05/08/2012

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 76.19

Date Completed 05/11/2012

Work Order Comments

JSTOTTS [05/11/2012 14:29]:
INSPECTION REPORT ON FILE

Work Order Custom Fields

Write current Meter Value 46967

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	05/08/2012	N	1.5	38.00	57.00
						Subtotal	57.00
						Total	57.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	4.11	4.11
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	1.87	13.08
	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
						Subtotal	19.19
						Total	19.19

Work Order 252998 (FLEET) REPLACE REAR BRAKES, TIRES

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/09/2012

Scheduled Start Date 05/09/2012

Scheduled End Date 05/09/2012

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 220.22

Date Completed 05/11/2012

Work Order Comments

JSTOTTS [05/11/2012 14:26]:

VIEW DOCUMENTS FOR COMMENTS

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	05/09/2012	N	3	38.00	114.00
						Subtotal	114.00
						Total	114.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	N20721 (FLEET)	0757 20 PADS	EA	1	49.53	49.53
	CMF	F06090021 (FLEET)	SIL-GLYDE LUBRICANT 4OZ 765-1351	EACH	1	5.49	5.49
	CMF	N15739 (FLEET)	MX756 FRT PADS	EA	1	42.68	42.68
	CMF	N22789 (FLEET)	H5072 PIN KIT	EA	2	4.26	8.52
						Subtotal	106.22
						Total	106.22

Work Order 254034 (FLEET) UJOINTS MAKING NOISE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/31/2012

Scheduled Start Date 05/31/2012

Scheduled End Date 05/31/2012

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 115.60

Date Completed 06/05/2012

Work Order Comments

TSCHMITT [06/05/2012 12:03]:

replaced u joints 330

Work Order Custom Fields

Write current Meter Value 47515

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Harold Orth	05/31/2012	N	2	38.00	76.00
						Subtotal	76.00
						Total	76.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F10070102 (FLEET)	U-JOINT 330	EACH	2	19.80	39.60
						Subtotal	39.60
						Total	39.60

Work Order 256097 (FLEET) S/C WILL NOT START

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C) PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/09/2012

Scheduled Start Date 07/09/2012

Scheduled End Date 07/09/2012

WO Type CM

Class FT-SC

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 158.41

Date Completed 07/09/2012

Work Order Comments

DGITTINS [07/09/2012 15:27]:
REPLACED BATTERY

Work Order Custom Fields

Write current Meter Value 48335

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		DAN RING	07/09/2012	N	1	39.00	39.00
						Subtotal	39.00
						Total	39.00

Tools Used

Activity	Equipment	Tool	Description	Department	Date Used	Quantity Used	Hours Used	Rate	Line Total
10	AR414RT1	TKUTL	8805 Truck Utility Repair 1 3/4 ton Traffic	FLEET	07/09/2012	1	1	30.00	30.00
								Subtotal	30.00
								Total	30.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02110015 (FLEET)	GROUP 65 BATTERY AC DELCO 65FLEET	EACH	1	89.41	89.41
						Subtotal	89.41

Work Order 260935 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/04/2012

Scheduled Start Date 10/04/2012

Scheduled End Date 10/04/2012

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 99.52

Date Completed 10/09/2012

Work Order Comments

JSTOTTS [10/09/2012 09:32]:

REPAIRED FRONT LIGHTS & IGN BUZZER; INSPECTION REPORT ON FILE

Work Order Custom Fields

Write current Meter Value 50979

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	10/04/2012	N	2	39.00	78.00
						Subtotal	78.00
						Total	78.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	4.11	4.11
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	1.87	13.08
	CMF	F02010089 (FLEET)	MARKER LIGHT BULB 3157NA	EACH	2	1.16	2.33
						Subtotal	21.52
						Total	21.52

Work Order 262565 (FLEET) CHECK OVER FOR WINTER

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/05/2012

Scheduled Start Date 11/05/2012

Scheduled End Date 11/05/2012

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 43.88

Date Completed 11/27/2012

Work Order Comments

JSTOTTS [11/13/2012 08:44]:

SERVICED PLOW

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Harold Orth	11/05/2012	N	1	39.00	39.00
						Subtotal	39.00
						Total	39.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	2	2.44	4.88
						Subtotal	4.88
						Total	4.88

Work Order 264379 (FLEET) RR TAILLIGHT INOP, CHECK OVER SPREADER

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/07/2012

Scheduled Start Date 12/07/2012

Scheduled End Date 12/07/2012

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 83.29

Date Completed 12/12/2012

Work Order Comments

JSTOTTS [12/12/2012 14:55]:

REPLACED RIGHT TAIL LIGHT BUL & CHECKED SPREADER FOR WINTER

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	12/07/2012	N	2	39.00	78.00
						Subtotal	78.00
						Total	78.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F02010291 (FLEET)	BULB 3357	EACH	1	1.38	1.38
	CMF	F06020035 (FLEET)	30W HEAVY DUTY OIL 1QT NAPA 75-110	QT	1	3.91	3.91
						Subtotal	5.29
						Total	5.29

Work Order 270679 (FLEET) PLOW WILL NOT TURN LEFT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 02/22/2013

Scheduled Start Date 02/22/2013

Scheduled End Date 02/22/2013

WO Type CM

Class SNOW

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 408.98

Date Completed 02/26/2013

Work Order Comments

TSCHMITT [02/26/2013 11:30]:

check system, replaced and fixed solenoid and plunger on hyd. control check all for proper operation replaced bit, cylinders

Work Order Custom Fields

Write current Meter Value 53167

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	02/22/2013	N	2	39.00	78.00
		Harold Orth	02/22/2013	N	3	39.00	117.00
						Subtotal	195.00
						Total	195.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12686 (FLEET)	1304010 MEYER ANGLE CYL	EACH	2	106.99	213.98
						Subtotal	213.98
						Total	213.98

Work Order 279552 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/11/2013

Scheduled Start Date 06/11/2013

Scheduled End Date 06/11/2013

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 77.48

Date Completed 06/12/2013

Work Order Custom Fields

Write current Meter Value 55067

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	06/11/2013	N	1.5	39.00	58.50
						Subtotal	58.50
						Total	58.50

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F0351372 (FLEET)	OIL FILTER 51372	EACH	1	2.99	2.99
	CMF	5-30 (FLEET)	5W30 OIL RE-REFINED (BULK - QT)	QT	7	2.00	13.99
	CMF	F06 (FLEET)	SHOP SUPPLIES - Misc. use of grease, antifreeze, fluids.	EACH	1	2.00	2.00
						Subtotal	18.98
						Total	18.98

Work Order 279575 (FLEET) E-BRAKE WON'T SET

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code GENERAL GENERAL BUDGET

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/11/2013

Scheduled Start Date 06/11/2013

Scheduled End Date 06/11/2013

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 78.00

Date Completed 06/12/2013

Work Order Comments

AWILMORE [06/12/2013 10:39]:

Removed emergency brake assembly, cleaned & lubed.

Work Order Custom Fields

Write current Meter Value

55067 MILES

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	06/11/2013	N	2	39.00	78.00
						Subtotal	78.00
						Total	78.00

Work Order 289156 (FLEET) CHECK OVER FOR WINTER

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/19/2013

Scheduled Start Date 11/19/2013

Scheduled End Date 11/19/2013

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 469.27

Date Completed 11/21/2013

Work Order Comments

AWILMORE [11/21/2013 15:06]:

Check unit out for winter. Change oil, grease, change gas, replaced muffler, repair connector, change oil in plow pump, adjust down on pump, check gear lube in gear box on spreader.

Work Order Custom Fields

Write current Meter Value 58183

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	11/19/2013	N	11	41.00	451.00
						Subtotal	451.00
						Total	451.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F06020040 (FLEET)	PLOW OIL WHITE BOTTLE 1QT 15135	EACH	1	2.73	2.73
	CMF	F07010257 (FLEET)	MUFFLER SM ENG 89966	EACH	1	15.54	15.54
						Subtotal	18.27
						Total	18.27

Work Order 290363 (FLEET) QUICK COUPLER ON PLOW LEAKING

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/06/2013

Scheduled Start Date 12/06/2013

Scheduled End Date 12/06/2013

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 100.91

Date Completed 12/16/2013

Work Order Comments

TSCHMITT [12/16/2013 14:33]:

replace quick coupler battery

Work Order Custom Fields

Write current Meter Value 58275

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		DAN RING	12/06/2013	N	1	41.00	41.00
						Subtotal	41.00
						Total	41.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	F04010822 (FLEET)	MEYER COUPLER 15741	EACH	1	42.60	42.60
	CMF	14479 (FLEET)	MALE 1304028 COUPLER	EACH	1	17.31	17.31
						Subtotal	59.91
						Total	59.91

Work Order 299900 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/29/2014

Scheduled Start Date 04/29/2014

Scheduled End Date 04/29/2014

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 120.53

Date Completed 05/02/2014

Work Order Comments

AWILMORE [05/02/2014 12:26]:

Air filter is dirty. Round trio bulb out (red).
Front brakes - 5/32 - ok. Rear brakes - 8/32 - ok.

Work Order Custom Fields

Write current Meter Value 59098

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	04/29/2014	N	2	41.00	82.00
						Subtotal	82.00
						Total	82.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	10020050	OIL FILTER 51372	EA	1	2.99	2.99
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.68	11.78
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	08010189	RED LED LIGHT ROUND G1032	EA	1	7.51	7.51
	CMF	10010114	AIR FILTER 46418	EA	1	11.25	11.25
						Subtotal	38.53
						Total	38.53

Work Order 299978 (FLEET) REPLACE FRONT SWAYBAR END LINKS

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/29/2014

Scheduled Start Date 04/29/2014

Scheduled End Date 04/29/2014

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 80.10

Date Completed 05/02/2014

Work Order Comments

AWILMORE [05/02/2014 12:27]:

sway bar link kits bad, needs replaced

Work Order Custom Fields

Write current Meter Value 59098

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	04/29/2014	N	1	41.00	41.00
						Subtotal	41.00
						Total	41.00

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070250	SWAYBAR K80043	EA	2	19.55	39.10
						Subtotal	39.10
						Total	39.10

Work Order 302500 (FLEET) RR OUTER TIRE FLAT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/20/2014

Scheduled Start Date 06/20/2014

Scheduled End Date 06/20/2014

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 20.50

Date Completed 06/25/2014

Work Order Comments

TSCHMITT [06/25/2014 14:14]:

repaired tire

Work Order Custom Fields

Write current Meter Value 60099

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ben Cain	06/20/2014	N	0.5	41.00	20.50
						Subtotal	20.50
						Total	20.50

Work Order 302881 (FLEET) ENGINE RUNS ROUGH AND CLUNK IN FRONT END

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/27/2014

Scheduled Start Date 06/27/2014

Scheduled End Date 06/27/2014

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 426.69

Date Completed 06/30/2014

Work Order Comments

TSCHMITT [06/30/2014 14:59]:

clunk is coming from sway bar link kits both upper and lower ball joints have play, not enough to replace now, spark plug fouled, need replaced coil on plug bad, and inj 1 and 2 inj ends bad broken wire

Work Order Custom Fields

Write current Meter Value 60240

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	06/27/2014	N	6.5	41.00	266.50
						Subtotal	266.50
						Total	266.50

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SERVICE	SERVICE / OUTSIDE LABOR	EACH	1	13.50	13.50
	CMF	08050076	IGNITION COIL 3W7Z12029AA	EA	1	47.91	47.91
	CMF	08050053	SPARK PLUG SP-479	EA	1	3.54	3.54
	CMF	16070260	MOTORCRAFT AGSF22WM	EA	1	39.28	39.28
	CMF	16070260	NON-STOCK	EA	1	39.28	39.28
	CMF	16070260	ENGINE/DRIVETRAIN PART	EA	1	55.96	55.96
	CMF	16070260	NON-STOCK	EA	1	55.96	55.96
	CMF	16070260	ENGINE/DRIVETRAIN PART	EA	1	55.96	55.96
						Subtotal	160.19
						Total	160.19

Work Order 308904 (FLEET) check over for winter

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/24/2014

Scheduled Start Date 10/24/2014

Scheduled End Date 10/24/2014

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 199.14

Date Completed 10/30/2014

Work Order Comments

TSCHMITT [10/30/2014 14:32]:

check over for winter, r/r battery, change oil in plow, fix wire connections, antifreeze 20 degree

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	10/24/2014	N	3	40.22	120.66
						Subtotal	120.66
						Total	120.66

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08110014	GROUP 65 BATTERY AC DELCO 65FLEET	EA	1	75.75	75.75
	CMF	13020058	PLOW OIL 1QT BOSS HYD01835	EA	1	2.73	2.73
						Subtotal	78.48
						Total	78.48

Work Order 311214 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/01/2014

Scheduled Start Date 12/01/2014

Scheduled End Date 12/01/2014

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 151.99

Date Completed 12/03/2014

Work Order Comments

TSCHMITT [12/03/2014 15:28]:

inspection on file

Work Order Custom Fields

Write current Meter Value 63084

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	12/01/2014	N	3	40.22	120.66
						Subtotal	120.66
						Total	120.66

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.66	11.61
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10020050	OIL FILTER 51372	EA	1	3.47	3.47
	CMF	10010114	AIR FILTER 46418	EA	1	11.25	11.25
						Subtotal	31.33
						Total	31.33

Work Order 311215 (FLEET) REPLACE WIPERS,STROBE INOP,HYD HOSE ON PLOW LEAKING,CHECK PLOW BIT,REPLACE TIRES

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/01/2014

Scheduled Start Date 12/01/2014

Scheduled End Date 12/01/2014

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 1,670.78

Date Completed 12/03/2014

Work Order Comments

TSCHMITT [12/03/2014 15:29]:

replaced wipers, replaced left turn cyl hose on plow, replaced rear tires, rewired dingy light

Work Order Custom Fields

Write current Meter Value 63084

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	12/01/2014	N	4	40.22	160.88
						Subtotal	160.88
						Total	160.88

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12090030	TR600HP TOPSEAL SNAP-IN VALVE STEM 2-417	EA	4	0.89	3.56
	CMF	12010074	LT215/85R16 TIRE	EA	4	175.00	700.00
	CMF	07020006	PLOW HYDRAULIC HOSE 21856	EA	1	18.25	18.25
	CMF	16010019	20" SUMMER WIPER BLADE 31-20	EA	2	5.67	11.34
	CMF	13010070	KWIK-START STARTING FLUID 11OZ LAWSON 81030	EA	1	4.39	4.39
	CMF	08060098	MINI ATM FUSE ADD-A-CIRCUIT 782-2226 - PICO 0956PT	EA	1	7.19	7.19
	CMF	12010020	225/70R19.5 TIRE, DRIVE TIRE	EA	2	252.72	505.44
	CMF	12010020	225/70R19.5 TIRE, DRIVE TIRE	EA	1	259.74	259.74
						Subtotal	1,509.90



Work Order 311215 (FLEET) REPLACE WIPERS,STROBE INOP,HYD HOSE ON
PLOW LEAKING,CHECK PLOW BIT,REPLACE TIRES
Status Closed

Scheduled Start Date 12/01/2014
Scheduled End Date 12/01/2014
WO Type CM



Total

 1,509.90

Work Order 312981 (FLEET) HYD FITTING LEAKING ON PLOW, CHECK BIT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/08/2015

Scheduled Start Date 01/08/2015

Scheduled End Date 01/08/2015

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 362.95

Date Completed 01/13/2015

Work Order Comments

AWILMORE [01/13/2015 12:07]:

Replace female coupler, male coupler order. Replaced plow bit, topped off hydraulic oil in plow.

Work Order Custom Fields

Write current Meter Value 63364

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	01/08/2015	N	3	40.22	120.66
						Subtotal	120.66
						Total	120.66

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	15010098	8 FT BIT FOR MEYERS POLY PLOW 09133	EA	1	182.00	182.00
	CMF	15010078	PLOW QUICK COUPLER 1304025	EA	1	12.99	12.99
	CMF	07020441	HYDRAULIC COUPLER MEYERS 1304029C	EA	1	47.30	47.30
						Subtotal	242.29
						Total	242.29

Work Order 314458 (FLEET) SPINNER STOPPED TURNING

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 02/02/2015

Scheduled Start Date 02/02/2015

Scheduled End Date 02/02/2015

WO Type CM

Class SNOW

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 40.22

Date Completed 02/04/2015

Work Order Comments

TSCHMITT [02/04/2015 14:11]:

reinstalled keyway and tightened set screw

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Mike Manning	02/02/2015	N	1	40.22	40.22
						Subtotal	40.22
						Total	40.22

Work Order 327173 (FLEET) POPPING NOISE FROM REAR
Status Closed

Parent Work Order
Department PARK PARKS DEPT
PM Code
Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair
Problem Code
Reported By DGITTINS Donnie Gittins
Project
Standard WO
Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location PARK (FLEET-C) PARK
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 08/25/2015

Scheduled Start Date 08/25/2015
Scheduled End Date 08/25/2015
WO Type CM
Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By
Estimated Hours 1
Estimated Cost 0.00
Actual Cost 516.95
Date Completed 09/01/2015

Work Order Comments

TSCHMITT [09/01/2015 15:41]:
 REPLACED REAR UJOINT, TAKE HOLD DOWN STRAPS AND BOLTS, FRONT SHOCKS, FRONT SWAY BAR LINKS, REE UP RR CALIPER PINS

Work Order Custom Fields

Write current Meter Value 66569

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	08/25/2015	N	6.5	41.34	268.71
						Subtotal	268.71
						Total	268.71

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	11020051	U-JOINT CLAMP 331-10	EA	1	6.94	6.94
	CMF	16070097	U-JOINT 331 SPICER 5-178X	EA	1	13.09	13.09
	CMF	16070097	U-JOINT 331 SPICER 5-178X	EA	-1	13.09	-13.09
	CMF	16070096	U-JOINT 330	EA	1	18.39	18.39
	CMF	16070255	SWAY BAR END LINK	EA	2	23.70	47.40
	CMF	16070336	SHOCK / STRUT / SPRING	EA	2	53.83	107.66
	CMF	17020016	NITRILE GLOVES XL 100/BOX	EA	1	7.85	7.85
	CMF	SERVICE	SERVICE / OUTSIDE LABOR	EACH	1	60.00	60.00
						Subtotal	248.24
						Total	248.24

Work Order 331847 (FLEET) CHECK OVER FOR WINTER
Status Closed

Parent Work Order
Department PARK PARKS DEPT
PM Code
Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair
Problem Code
Reported By DGITTINS Donnie Gittins
Project
Standard WO
Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location PARK (FLEET-C) PARK
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 11/18/2015

Scheduled Start Date 11/18/2015
Scheduled End Date 11/18/2015
WO Type CM
Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By
Estimated Hours 1
Estimated Cost 0.00
Actual Cost 250.77
Date Completed 11/25/2015

Work Order Comments

TSCHMITT [11/25/2015 15:20]:

check out plow and salt dog for winter, changed oil in plow, welded up broke frame, repair bad wire for right angle solenoid, change engine oil and angle drive gear box oil, replaced air filter, greased up all bearings, tightened and lubed chains

Work Order Custom Fields

Write current Meter Value 67895

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	11/18/2015	N	5	41.34	206.70
						Subtotal	206.70
						Total	206.70

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	13020034	30W HEAVY DUTY OIL 1QT AUTO VALUE 5159	QT	1	3.98	3.98
	CMF	13060021	MOLY GREASE TUBE	EA	1	2.80	2.80
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	18.49	18.49
	CMF	13020264	PLOW OIL 1GAL LUBRIPLATE L0767-057	EA	1	18.80	18.80
						Subtotal	44.07
						Total	44.07

Work Order 333310 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/07/2015

Scheduled Start Date 12/07/2015

Scheduled End Date 12/07/2015

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 122.69

Date Completed 12/11/2015

Work Order Comments

TSCHMITT [12/11/2015 13:54]:

inspection on file

Work Order Custom Fields

Write current Meter Value 68040

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	12/07/2015	N	2	41.34	82.68
						Subtotal	82.68
						Total	82.68

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.52	10.65
	CMF	10020050	OIL FILTER 51372	EA	1	3.06	3.06
	CMF	10030048	FUEL FILTER 33296	EA	1	5.94	5.94
	CMF	10050021	TRANS FILTER 58968	EA	1	15.36	15.36
						Subtotal	40.01
						Total	40.01

Work Order 333317 (FLEET) REPLACE REAR BRAKES

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/07/2015

Scheduled Start Date 12/07/2015

Scheduled End Date 12/07/2015

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 672.33

Date Completed 12/11/2015

Work Order Comments

TSCHMITT [12/11/2015 13:53]:

replaced both rear rotors and bake pads seal leaking around caliper piston replaced caliper, bleed brakes took for test drive stops ok check for leaks no leaks

Work Order Custom Fields

Write current Meter Value 68040

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	12/07/2015	N	2	41.34	82.68
		Ron Nixon	12/07/2015	N	2	41.34	82.68
		Ron Nixon	12/08/2015	N	4	41.34	165.36
Subtotal							330.72
Total							330.72

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16020148	WAGNER BRAKE PAD MX757	EA	1	28.95	28.95
	CMF	16020293	BRAKE ROTOR	EA	2	44.93	89.86
	CMF	16080092	SEAL BG951 NATIONAL1962	EA	2	41.96	83.92
	CMF	16080592	GASKET FLANGE	EA	1	8.94	8.94
	CMF	16080092	SEAL BG951 NATIONAL1962	EA	-2	0.00	0.00
	CMF	16080040	SEAL 28720	EA	2	5.80	11.60
	CMF	16080040	SEAL 28720	EA	-2	5.80	-11.60
	CMF	16080042	WHEEL SEAL 28754	EA	2	12.30	24.60
	CMF	16020198	BRAKE CALIPER	EA	1	63.34	63.34
	CMF	CORE	CORE CHARGE	EACH	1	42.00	42.00



Work Order 333317 (FLEET) REPLACE REAR BRAKES

Status Closed



Scheduled Start Date 12/07/2015

Scheduled End Date 12/07/2015

WO Type CM

Subtotal 341.61

Total 341.61

Work Order 335354 (FLEET) rf tire has a screw in it

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/06/2016

Scheduled Start Date 01/06/2016

Scheduled End Date 01/06/2016

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 41.34

Date Completed 01/07/2016

Work Order Comments

AWILMORE [01/07/2016 14:41]:

Plugged tire.

Work Order Custom Fields

Write current Meter Value 68401

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Mike Manning	01/06/2016	N	1	41.34	41.34
						Subtotal	41.34
						Total	41.34

Work Order 338409 (FLEET) REAR AXLE HUB SEALS LEAKING

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/29/2016

Scheduled Start Date 01/29/2016

Scheduled End Date 01/29/2016

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 478.46

Date Completed 02/02/2016

Work Order Comments

AWILMORE [02/02/2016 12:24]:

Removed rear hubs and cleaned parts. Replaced wheel seals, brake pads, and cleaned parking brake shoes as instructed. Also topped off rear diff. Repaired loose and bent running board mount.

Work Order Custom Fields

Write current Meter Value 68965

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ben Cain	01/29/2016	N	4	41.34	165.36
		Lynn Hammermeister	01/29/2016	N	4	41.34	165.36
		Ron Nixon	01/29/2016	N	2	41.34	82.68
						Subtotal	413.40
						Total	413.40

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	07030056	1/4" FUEL LINE H175 (FT)	A FT	6	0.89	5.34
	CMF	11080006	2" ROLOC BROWN BUFFING DISK COARSE 3M 07480	EA	6	1.17	7.03
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	16080056	SEAL 9864S	EA	2	8.37	16.74
	CMF	16020294	BRAKE PAD	EA	1	30.95	30.95
						Subtotal	65.06

Work Order 344619 (FLEET) replace trailer plug

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/28/2016

Scheduled Start Date 03/28/2016

Scheduled End Date 03/28/2016

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 51.53

Date Completed 03/30/2016

Work Order Comments

TSCHMITT [03/30/2016 14:20]:

installed 7 way trailer plug

Work Order Custom Fields

Write current Meter Value 69323

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	03/28/2016	N	1	41.34	41.34
						Subtotal	41.34
						Total	41.34

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08030101	7-WIRE FEMALE TRAILER PLUG 755-1526	EA	1	10.19	10.19
						Subtotal	10.19
						Total	10.19

Work Order 352914 (FLEET) WILL NOT SHIFT FROM PARK

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/05/2016

Scheduled Start Date 07/05/2016

Scheduled End Date 07/05/2016

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 235.12

Date Completed 07/12/2016

Work Order Comments

TEDDY [07/07/2016 08:37]:

NON-STOCK - \$64.40:
Shifter Tube F57Z-7212-A
PLUNGER F7DZ-7R264-AA
BUSHING F3TZ-7L278-A

TSCHMITT [07/12/2016 13:24]:

THE SHIFT TUBE IS BROKEN NEEDS REPLACED

Work Order Custom Fields

Write current Meter Value 70947

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	07/05/2016	N	4	42.68	170.72
						Subtotal	170.72
						Total	170.72

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	64.40	64.40
						Subtotal	64.40
						Total	64.40

Work Order 360305 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/13/2016

Scheduled Start Date 09/13/2016

Scheduled End Date 09/13/2016

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 2

Estimated Cost 0.00

Actual Cost 110.21

Date Completed 09/19/2016

Work Order Comments

TSCHMITT [09/19/2016 14:02]:

inspec on file, left rear box light out, fixed front brakes 3/32 ok rear brakes 6/32 ok,. both front tire at 4/32 will need to be changed next service

Work Order Custom Fields

Write current Meter Value 72081

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	2	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	09/13/2016	N	2	42.68	85.36
						Subtotal	85.36
						Total	85.36

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10020050	OIL FILTER 51372	EA	1	3.55	3.55
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.45	10.16
	CMF	08010189	RED LED LIGHT ROUND G1032	EA	1	6.14	6.14
						Subtotal	24.85
						Total	24.85

Work Order	362150 (FLEET) CHECK OVER TRUCK AND SPREADER FOR WINTER	Scheduled Start Date	10/11/2016
Status	Closed	Scheduled End Date	10/11/2016
		WO Type	CM
Parent Work Order		Class	FT-CM
Department	PARK PARKS DEPT	Priority	
PM Code		Warranty	N
Cost Code	A16800-633200 GenEquipMaint-Vehicle&Equip Repair	Safety	N
Problem Code		Equip Criticality	
Reported By	DGITTINS Donnie Gittins	Assigned To	
Project		Assigned By	
Standard WO			
Equipment	AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed		
Location	PARK (FLEET-C) PARK		
Equipment Manufacturer	FORD	Estimated Hours	1
Equipment Model	F-350	Estimated Cost	0.00
Equipment Serial Number	1FDWF36S91EB12055	Actual Cost	972.10
Date Started	10/11/2016	Date Completed	10/27/2016

Work Order Comments

AWILMORE [10/27/2016 14:19]:

Check lights - repair & replace as needed. Change oil in plow pump, repair wiring at pump solenoids, replace damaged coupler at pump. Front tires both at less than 3/32 - replace front tires. Change oil in spreader motor. Replace spark plug. Order air filter. Remove throttle linkage plate - fire up & lube linkage pivots - reinstall. Operate engine & adjust as needed. Tighten & align upper drive chain.

Work Order Custom Fields

Write current Meter Value 72607

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		
					

Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	10/11/2016	N	7.5	42.68	320.10
		Darrell Marean	10/12/2016	N	3.5	42.68	149.38
						Subtotal	469.48
						Total	469.48

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010129	LED AMBER MARKER LIGHT ROUND TRUCKLITE 50-10202Y-3	EA	1	3.15	3.15
	CMF	08050029	SPARK PLUG CHAMPION RC12YC 71	EA	1	1.95	1.95
	CMF	13020034	30W HEAVY DUTY OIL 1QT AUTO VALUE 5159	QT	2	3.87	7.74
	CMF	12010074	LT215/85R16 TIRE	EA	2	195.00	390.00
	CMF	07020441	HYDRAULIC COUPLER MEYERS 1304029C	EA	1	71.10	71.10

Work Order 362150 (FLEET) CHECK OVER TRUCK AND SPREADER FOR WINTER
Status Closed

Scheduled Start Date 10/11/2016
Scheduled End Date 10/11/2016
WO Type CM



10	CMF	10010101	AIR FILTER SUBARU 2793260717 DG174	EA	1	15.03	15.03
	CMF	08010284	AUTOMOTIVE LAMP BULB 3157	EA	1	1.15	1.15
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	13020058	PLOW OIL 1QT BOSS HYD01835	EA	1	7.50	7.50
						Subtotal	502.62
						Total	502.62

Work Order 365977 (FLEET) LH PLOW LIGHT INOP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/12/2016

Scheduled Start Date 12/12/2016

Scheduled End Date 12/12/2016

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 75.19

Date Completed 12/21/2016

Work Order Comments

TSCHMITT [12/21/2016 11:10]:

the left head light on plow does not work will need a pig tail and bulb

Work Order Custom Fields

Write current Meter Value 72626

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	12/12/2016	N	1.5	42.68	64.02
						Subtotal	64.02
						Total	64.02

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08020013	HEADLIGHT PLUG LS6235 - S844	EA	1	3.03	3.03
	CMF	08010177	HEADLIGHTLIGHT BULB BP1210/H4	EA	1	8.14	8.14
						Subtotal	11.17
						Total	11.17

Work Order 366322 (FLEET) PLOW WILL NOT GO UP OR DOWN

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C)

PARK

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/19/2016

Scheduled Start Date 12/19/2016

Scheduled End Date 12/19/2016

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 106.70

Date Completed 12/21/2016

Work Order Comments

AWILMORE [12/21/2016 11:45]:

Found poor connection on pump solenoid.

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	12/19/2016	N	2.5	42.68	106.70
						Subtotal	106.70
						Total	106.70

Work Order 370812 (FLEET) BRAKE LIGHTS INOP,PLOW CUTS OUT
INTERMITTENTLY,CHECK POW BIT

Status Closed

Scheduled Start Date 01/30/2017
Scheduled End Date 01/30/2017
WO Type CM



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code A16800-633200 GenEquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PARK (FLEET-C) PARK

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/30/2017

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 106.70

Date Completed 02/06/2017

Work Order Comments

TSCHMITT [02/06/2017 11:03]:
found loose a coil cartridge tightened it problem went away - replaced burnt bulb

Work Order Custom Fields

Write current Meter Value 73288

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Mike Manning	01/30/2017	N	2.5	42.68	106.70
						Subtotal	106.70
						Total	106.70

Work Order 456806 (FLEET) MOUNT EQUIPMENT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/01/2017

Scheduled Start Date 06/01/2017

Scheduled End Date 06/01/2017

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 48.84

Date Completed 06/16/2017

Work Order Comments

TSCHMITT [06/16/2017 08:23]:

install numbers

Work Order Custom Fields

Write current Meter Value 73751

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Donald Todd	06/01/2017	N	1	42.68	42.68
						Subtotal	42.68
						Total	42.68

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16120001	NUMBERS - ASSET DECAL	EA	15	0.41	6.16
						Subtotal	6.16
						Total	6.16

Work Order 472027 (FLEET) BEARING GROWL NOISE FROM FRONT END

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/19/2017

Scheduled Start Date 07/19/2017

Scheduled End Date 07/19/2017

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 141.03

Date Completed 07/24/2017

Work Order Comments

AWILMORE [07/24/2017 13:48]:

Replaced rear u-joint. Adjusted right door.

Work Order Custom Fields

Write current Meter Value 74227

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	07/19/2017	N	2.5	45.59	113.98
						Subtotal	113.98
						Total	113.98

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	11070118	U-JOINT STRAP KIT 351-10	EA	1	6.09	6.09
	CMF	16070044	U-JOINT SPICER 5-170X AM37184	EA	1	20.96	20.96
						Subtotal	27.05
						Total	27.05

Work Order 472789 (FLEET) BRAKE PEDAL GOES TO FLOOR

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/27/2017

Scheduled Start Date 07/27/2017

Scheduled End Date 07/27/2017

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 374.48

Date Completed 08/14/2017

Work Order Comments

TEDDY [07/28/2017 12:31]:

BRAKE HOSE 609 - \$18.64 - RR BRAKE HOSE

CENTER BRAKE HOSE

1/4" BRAKE LINE

2 BRAKE LINE COUPLERS

2 BRAKE LINE ENDS

TSCHMITT [08/14/2017 15:30]:

pedal goes to floow will need to put in flud and see if front brakes work - rear line is broken, will have to replace, it almost to master cyl will have to brake all bleeders loose and will need 2 rubber hose rear and hose rr hose

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Robert Tacke	07/27/2017	N	6	45.59	273.55
						Subtotal	273.55
						Total	273.55

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	13010005	ZEP 45 NC LUBRICANT 15OZ ZEP 374357	EA	1	11.50	11.50
	CMF	07030031	BRAKE HOSE 609	EA	1	19.65	19.65
	CMF	16020076	1/4"X60" BRAKE LINE 813-1225	EA	1	33.00	33.00
	CMF	13020037	BRAKE FLUID DOT 3 32 OZ PS332	EA	2	6.57	13.14
	CMF	07030031	BRAKE HOSE 609	EA	1	18.64	18.64
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS,	EACH	1	5.00	5.00



Work Order 472789 (FLEET) BRAKE PEDAL GOES TO FLOOR

Status Closed

Scheduled Start Date 07/27/2017

Scheduled End Date 07/27/2017

WO Type CM



10

HARDWARE

Subtotal	<hr/>	100.93
Total	<hr/>	100.93

Work Order 483405 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/22/2017

Scheduled Start Date 11/27/2017

Scheduled End Date 11/27/2017

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 86.50

Date Completed 12/05/2017

Work Order Custom Fields

Write current Meter Value 76147

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	11/22/2017	N	1	39.18	39.18
		Ron Nixon	11/27/2017	N	0.5	39.18	19.59
						Subtotal	58.76
						Total	58.76

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.30	9.12
	CMF	10020050	OIL FILTER 51372	EA	1	3.19	3.19
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10010114	AIR FILTER 46418	EA	1	10.43	10.43
						Subtotal	27.74
						Total	27.74

Work Order 483419 (FLEET) MUFFLER IS RUSTED OUT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By DGITTINS Donnie Gittins

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/27/2017

Scheduled Start Date 11/27/2017

Scheduled End Date 11/27/2017

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 963.43

Date Completed 12/05/2017

Work Order Comments

AWILMORE [12/05/2017 14:20]:

Replaced exhaust (custom fit). Nothing fit, all had to be fabricated.

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	11/27/2017	N	8	39.18	313.40
		Scott Pope	11/27/2017	N	5	40.49	202.47
		Scott Pope	11/28/2017	N	5	40.49	202.47
						Subtotal	718.35
						Total	718.35

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	34.05	34.05
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	206.03	206.03
	CMF	16040046	EXHAUST HANGER 35103	EA	1	7.25	7.25
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	16040046	EXHAUST HANGER 35103	EA	-1	7.25	-7.25
						Subtotal	245.08
						Total	245.08

Work Order 499785 (FLEET) MARKER LIGHT OUT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 02/28/2018

Scheduled Start Date 02/28/2018

Scheduled End Date 02/28/2018

WO Type CM

Class FT-SETUP

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 52.82

Date Completed 03/02/2018

Work Order Comments

TSCHMITT [03/02/2018 13:59]:
REPLACED RR MARKER LIGHT

Work Order Custom Fields

Write current Meter Value 77366

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	02/28/2018	N	1	45.59	45.59
						Subtotal	45.59
						Total	45.59

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010189	RED LED LIGHT ROUND G1032	EA	1	7.23	7.23
						Subtotal	7.23
						Total	7.23

Work Order 505678 (FLEET) BRAKES GRINDING

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/13/2018

Scheduled Start Date 04/13/2018

Scheduled End Date 04/13/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 213.53

Date Completed 04/19/2018

Work Order Comments

TSCHMITT [04/19/2018 14:01]:

FRONT BRAKES GUIDING - pulled hub assembly off to turn rotors - put both hub assembly back on - put new brake pads on - took for test drive - stops fine - no noise

Work Order Custom Fields

Write current Meter Value 78210

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	04/13/2018	N	4.5	39.18	176.29
						Subtotal	176.29
						Total	176.29

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16020294	BRAKE PAD	EA	1	37.24	37.24
						Subtotal	37.24
						Total	37.24

Work Order 506394 (FLEET) STROBE LIGHT INOP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/18/2018

Scheduled Start Date 04/18/2018

Scheduled End Date 04/18/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 66.73

Date Completed 04/27/2018

Work Order Comments

TSCHMITT [04/27/2018 10:49]:

STROBE LIGHT INOP, CHECKED ALL wiring from light to engine bay, two bad 10 amp fuses at switch / fuse panel, replaced fuses and checked operation

Work Order Custom Fields

Write current Meter Value 78250

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	04/18/2018	N	1.5	43.84	65.76
						Subtotal	65.76
						Total	65.76

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08060042	FUSE ATM-10	EA	2	0.48	0.97
						Subtotal	0.97
						Total	0.97

Work Order 511376 (FLEET) RIGHT REAR OUTSIDE DUAL FLAT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/14/2018

Scheduled Start Date 05/14/2018

Scheduled End Date 05/14/2018

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 39.18

Date Completed 05/17/2018

Work Order Comments

TSCHMITT [05/17/2018 13:53]:

RIGHT REAR FAT, REMOVED TIRE AND PATCHED

Work Order Custom Fields

Write current Meter Value 78657

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	05/14/2018	N	1	39.18	39.18
						Subtotal	39.18
						Total	39.18

Work Order 513460 (FLEET) dingy light inop

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/08/2018

Scheduled Start Date 06/08/2018

Scheduled End Date 06/08/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 166.15

Date Completed 06/14/2018

Work Order Custom Fields

Write current Meter Value 79087

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	06/08/2018	N	1	43.84	43.84
						Subtotal	43.84
						Total	43.84

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010589	AMBER STROBE LIGHT, LED DINGHY LIGHT 7965A	EA	1	116.34	116.34
	CMF	08060042	FUSE ATM-10	EA	2	0.49	0.97
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	122.31
						Total	122.31

Work Order 514801 (FLEET) RIGHT REAR OUTSIDE TIRE FLAT

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/27/2018

Scheduled Start Date 06/27/2018

Scheduled End Date 06/27/2018

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 45.49

Date Completed 07/10/2018

Work Order Comments

TSCHMITT [07/10/2018 13:57]:

REPAIRED RIGHT REAR OUTSIDE TIRE

Work Order Custom Fields

Write current Meter Value 79397

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	06/27/2018	N	1	40.49	40.49
						Subtotal	40.49
						Total	40.49

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	45.00	45.00
		16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	-1	45.00	-45.00
						Subtotal	5.00
						Total	5.00

Work Order 515332 (FLEET) GLOVE BOX, BACK UP ALARM, TRAILER PLUG

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/05/2018

Scheduled Start Date 07/05/2018

Scheduled End Date 07/05/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 241.81

Date Completed 07/10/2018

Work Order Comments

TEDDY [07/09/2018 09:21]:

NON-STOCK - \$45 - USED GLOVE BOX

TSCHMITT [07/10/2018 11:18]:

replaced glove box, trailr plug and back up alarm

Work Order Custom Fields

Write current Meter Value 79489

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	07/05/2018	N	3.5	44.11	154.38
						Subtotal	154.38
						Total	154.38

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08030101	7-WIRE FEMALE TRAILER PLUG 755-1526	EA	1	10.96	10.96
	CMF	08090053	BACK-UP ALARM ECCO 520	EA	1	26.47	26.47
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	45.00	45.00
						Subtotal	87.43
						Total	87.43

Work Order 518834 (FLEET) BACK UP ALARM INOP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C) S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/14/2018

Scheduled Start Date 08/14/2018

Scheduled End Date 08/14/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 27.05

Date Completed 08/23/2018

Work Order Comments

TSCHMITT [08/23/2018 14:31]:

MAKE A GROUND WIRE FOR ALARM

Work Order Custom Fields

Write current Meter Value 80012

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	08/14/2018	N	0.5	44.11	22.05
						Subtotal	22.05
						Total	22.05

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	5.00
						Total	5.00

Work Order 519348 (FLEET) FLASHERS INOP

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/20/2018

Scheduled Start Date 08/20/2018

Scheduled End Date 08/20/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 68.12

Date Completed 08/24/2018

Work Order Comments

TSCHMITT [08/24/2018 13:40]:

REPLACED FLASHER

Work Order Custom Fields

Write current Meter Value 80091

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	08/20/2018	N	1	47.29	47.29
						Subtotal	47.29
						Total	47.29

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08040247	FLASHER RELAY MOTORCRAFT 5C3Z13350AA	EA	1	20.83	20.83
						Subtotal	20.83
						Total	20.83

Work Order 519981 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/28/2018

Scheduled Start Date 08/28/2018

Scheduled End Date 08/28/2018

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 92.33

Date Completed 09/05/2018

Work Order Comments

TSCHMITT [09/05/2018 14:37]:

LOF SERVICE, REPLACED AIR FILTER AND WIPERS

Work Order Custom Fields

Write current Meter Value 80191

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	08/28/2018	N	1.5	37.90	56.85
						Subtotal	56.85
						Total	56.85

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10020050	OIL FILTER 51372	EA	1	3.08	3.08
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.30	9.10
	CMF	10010114	AIR FILTER 46418	EA	1	9.96	9.96
	CMF	16010020	22" SUMMER WIPER BLADE 31-22	EA	2	4.17	8.35
						Subtotal	35.48
						Total	35.48

Work Order 520830 (FLEET) OIL LIGHT ON

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/10/2018

Scheduled Start Date 09/10/2018

Scheduled End Date 09/10/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 94.58

Date Completed 09/12/2018

Work Order Comments

TSCHMITT [09/12/2018 13:52]:

CHECK OIL, IT WAS FULL, CHECK CODES AND NO ENGINE CODES, TEST DROVE COULDN'T DUPLICATE PROBLEM

Work Order Custom Fields

Write current Meter Value 80293

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	09/10/2018	N	2	47.29	94.58
						Subtotal	94.58
						Total	94.58

Work Order 524290 (FLEET) BRAKE NOISE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/03/2018

Scheduled Start Date 10/03/2018

Scheduled End Date 10/03/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 38.79

Date Completed 10/05/2018

Work Order Comments

AWILMORE [10/05/2018 13:59]:

Checked for brake noise and could not duplicate. Checked front and rear brakes (no problems). Put on hoist and checked e-brake (no problems).

Work Order Custom Fields

Write current Meter Value 80500

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	10/03/2018	N	1	38.79	38.79
						Subtotal	38.79
						Total	38.79

Work Order 527321 (FLEET) S/C WON'T START

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/06/2018

Scheduled Start Date 11/06/2018

Scheduled End Date 11/06/2018

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 149.79

Date Completed 11/14/2018

Work Order Comments

TSCHMITT [11/14/2018 14:27]:

SERVICE CALL JUMP START BROUGHT BACK R+R BATT HCECK CHARGING SYSTEM

Work Order Custom Fields

Write current Meter Value 81010

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ben Cain	11/06/2018	N	1	47.29	47.29
						Subtotal	47.29
						Total	47.29

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08110014	GROUP 65 BATTERY AC DELCO 65FLEET	EA	1	97.50	97.50
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	102.50
						Total	102.50

Work Order 548881 (FLEET) pass rear outside tire flat

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/13/2019

Scheduled Start Date 05/13/2019

Scheduled End Date 05/13/2019

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 23.65

Date Completed 08/08/2019

Work Order Custom Fields

Write current Meter Value 83416

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	05/13/2019	N	0.5	47.29	23.65
						Subtotal	23.65
						Total	23.65

Work Order 551754 (FLEET) SHIFTER LINKAGE BAD

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/17/2019

Scheduled Start Date 06/17/2019

Scheduled End Date 06/17/2019

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 220.63

Date Completed 06/26/2019

Work Order Comments

TEDDY [06/18/2019 09:36]:

NON-STOCK -\$71.58 - GEAR SHIFTER

TSCHMITT [06/26/2019 12:12]:

REPAIRED SHIFTER

Work Order Custom Fields

Write current Meter Value 83850

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	06/17/2019	N	0.5	38.79	19.39
		Tim Bain	06/18/2019	N	1.5	38.79	58.18
						Subtotal	77.58
						Total	77.58

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16100042	TRANSMISSION SHIFT TUBE COLLAR / BUSHING F3TZ7L278A	EA	1	71.47	71.47
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	71.58	71.58
						Subtotal	143.05
						Total	143.05

Work Order 555025 (FLEET) service

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/29/2019

Scheduled Start Date 07/29/2019

Scheduled End Date 07/29/2019

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 122.05

Date Completed 08/01/2019

Work Order Comments

TSCHMITT [08/01/2019 14:35]:
SERVICE REPLACE AIR FILTER

Work Order Custom Fields

Write current Meter Value 84234

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	07/29/2019	N	2	45.97	91.94
						Subtotal	91.94
						Total	91.94

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	10020050	OIL FILTER 51372	EA	1	3.62	3.62
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.30	9.10
	CMF	10010114	AIR FILTER 46418	EA	1	12.39	12.39
						Subtotal	30.11
						Total	30.11

Work Order 555098 (FLEET) NEW BUMPER FOR FRONT AXLE

Status Closed



Parent Work Order

Department PARK PARKS DEPT

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/29/2019

Scheduled Start Date 07/29/2019

Scheduled End Date 07/29/2019

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 230.19

Date Completed 08/12/2019

Work Order Comments

AWILMORE [08/12/2019 13:45]:

Install new front axle bumper kit. Had to cut and drill out broken mounts.

Work Order Custom Fields

Write current Meter Value 84234

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	07/29/2019	N	4	45.97	183.88
						Subtotal	183.88
						Total	183.88

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050275	NON-STOCK VEHICLE BODY/INTERIOR PART	EA	1	16.66	16.66
	CMF	14010053	RUBBER BUMPER M141205	EA	1	16.66	16.66
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	12.99	12.99
						Subtotal	46.31
						Total	46.31

Work Order 560751 (FLEET) RRO DUAL TIRE FLAT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/01/2019

Scheduled Start Date 10/01/2019

Scheduled End Date 10/01/2019

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 52.81

Date Completed 10/07/2019

Work Order Comments

AWILMORE [10/07/2019 14:45]:

Repaired tire.

Work Order Custom Fields

Write current Meter Value 84985

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	10/01/2019	N	1	47.81	47.81
						Subtotal	47.81
						Total	47.81

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	5.00
						Total	5.00

Work Order 564165 (FLEET) RIGHT REAR OUTSIDE FLAT TIRE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/13/2019

Scheduled Start Date 11/13/2019

Scheduled End Date 11/13/2019

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 38.32

Date Completed 12/11/2019

Work Order Comments

AWILMORE [12/11/2019 13:24]:

Patched tire.

Work Order Custom Fields

Write current Meter Value 85500

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	11/13/2019	N	1	38.32	38.32
						Subtotal	38.32
						Total	38.32

Work Order 569584 (FLEET) glove box latch and right rear outside tire flat

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/14/2020

Scheduled Start Date 01/14/2020

Scheduled End Date 01/14/2020

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 63.79

Date Completed 01/16/2020

Work Order Comments

TSCHMITT [01/16/2020 14:30]:

repaired rro tire, need to replace next time it comes in flat, 4 patches and 1 plug, replaced glove box latch due to being broken

Work Order Custom Fields

Write current Meter Value 86421

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	01/14/2020	N	1	41.08	41.08
						Subtotal	41.08
						Total	41.08

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050016	DOOR LATCH	EA	1	17.71	17.71
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	22.71
						Total	22.71

Work Order	571082 (FLEET) OIL PRESSURE	UBOLT BROKE REATTACH MUDFLAP AND READS NO	Scheduled Start Date	01/30/2020
Status	Closed		Scheduled End Date	01/30/2020
			WO Type	CM
Parent Work Order			Class	FT-CM
Department	PW PUBLIC WORKS		Priority	
PM Code			Warranty	N
Cost Code	C06800-633200	EquipMaint-Vehicle&Equip Repair	Safety	N
Problem Code			Equip Criticality	
Reported By			Assigned To	
Project			Assigned By	
Standard WO				
Equipment	AR414RT1 (FLEET-C)	2001 Ford F-350 Chassis Cab / Flatbed	Estimated Hours	1
Location	S A 1301 (FLEET-C)	S A 1301	Estimated Cost	0.00
Equipment Manufacturer	FORD		Actual Cost	333.65
Equipment Model	F-350		Date Completed	02/12/2020
Equipment Serial Number	1FDWF36S91EB12055			
Date Started	01/30/2020			

Work Order Comments

TSCHMITT [02/12/2020 07:32]:
REPLACED UBOLTS, NUTS AND REINSTALL MUDFLAP

Work Order Custom Fields

Write current Meter Value 86631

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		
					

Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	01/30/2020	N	3	39.68	119.04
		Tim Bain	01/31/2020	N	4	39.68	158.73
					Subtotal		277.77
					Total		277.77

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	11050155	U BOLT, U-BOLT	EA	2	13.94	27.88
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	281,394.48	281,394.48
		11050155	U BOLT, U-BOLT	EA	-2	13.94	-27.88
		16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	-1	281,394.48	-281,394.48
	CMF	11050155	U BOLT, U-BOLT	EA	2	13.94	27.88
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	28.00	28.00
					Subtotal		55.88
					Total		55.88

Work Order 575453 (FLEET) muffler back exhaust is bad, trailer plug hanging and shifter hard to shift
Status Closed

Scheduled Start Date 03/18/2020
Scheduled End Date 03/18/2020
WO Type CM



Parent Work Order
Department PW PUBLIC WORKS
PM Code
Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair
Problem Code
Reported By
Project
Standard WO
Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location S A 1301 (FLEET-C) S A 1301
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 03/14/2020

Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By

Estimated Hours 1
Estimated Cost 0.00
Actual Cost 352.86
Date Completed 03/24/2020

Work Order Comments

DRING [03/24/2020 08:02]:
 MUFFLER 18887
DRING [03/24/2020 08:02]:
 mounted trailer plug, installed new muffler and reused tail pipe

Work Order Custom Fields

Write current Meter Value 87490

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	03/14/2020	N	4	38.32	153.26
						Subtotal	153.26
						Total	153.26

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	11.70	11.70
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	107.77	107.77
	CMF	16070260	NON-STOCK ENGINE/DRIVETRAIN PART	EA	1	57.72	57.72
	CMF	11080005	2" ROLOC GREEN 36G GRINDING DISC 3M 01397	EA	4	1.48	5.93
	CMF	16040046	EXHAUST HANGER 35103	EA	1	8.69	8.69
	CMF	16040015	3 " EXHAUST CLAMP 733-5794	EA	1	4.29	4.29
	CMF	16010020	22" SUMMER WIPER BLADE	EA	1	3.50	3.50

Work Order 575453 (FLEET) muffler back exhaust is bad, trailer plug hanging and
shifter hard to shift
Status Closed

Scheduled Start Date 03/18/2020
Scheduled End Date 03/18/2020
WO Type CM



10

31-22

Subtotal	<hr/>	199.60
Total	<hr/>	199.60

Work Order 576907 (FLEET) S/C TOWED IN STARTER OUT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/02/2020

Scheduled Start Date 04/02/2020

Scheduled End Date 04/02/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 179.37

Date Completed 04/03/2020

Work Order Comments

DRING [04/03/2020 13:06]:

went to bucky's on madison was unable to get started arrow towed to shop installed new starter

Work Order Custom Fields

Write current Meter Value 87774

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	04/02/2020	N	1	38.32	38.32
						Subtotal	38.32
						Total	38.32

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070229	STARTER	EA	1	141.05	141.05
						Subtotal	141.05
						Total	141.05

Work Order 579900 (FLEET) INSTALL WIDER MIRRORS

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/04/2020

Scheduled Start Date 05/04/2020

Scheduled End Date 05/04/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 128.73

Date Completed 05/19/2020

Work Order Comments

DRING [05/19/2020 13:26]:

INSTALLED TOW MIRRORS TO BETTER SEE AROUND HEADACHE RACK

Work Order Custom Fields

Write current Meter Value 88289

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	05/04/2020	N	1	38.32	38.32
						Subtotal	38.32
						Total	38.32

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050059	MIRROR	EA	1	90.41	90.41
						Subtotal	90.41
						Total	90.41

Work Order 579901 (FLEET) service

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/04/2020

Scheduled Start Date 05/04/2020

Scheduled End Date 05/04/2020

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 94.61

Date Completed 05/19/2020

Work Order Custom Fields

Write current Meter Value 88289

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	05/04/2020	N	1.5	38.32	57.47
						Subtotal	57.47
						Total	57.47

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	10020050	OIL FILTER 51372	EA	1	3.62	3.62
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.58	11.09
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10010114	AIR FILTER 46418	EA	1	10.43	10.43
	CMF	16010020	22" SUMMER WIPER BLADE 31-22	EA	2	3.50	7.00
						Subtotal	37.14
						Total	37.14

Work Order 580097 (FLEET) NEW REAR BRAKE PADS, RIGHT REAR CALIPER

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/05/2020

Scheduled Start Date 05/05/2020

Scheduled End Date 05/05/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 177.65

Date Completed 05/19/2020

Work Order Comments

DRING [05/19/2020 13:24]:

INSTALLED NEW REAR BRAKE PADS, INSTALLED NEW RR CALIPER.NEW CALIPER BRACKET ON LEFT REAR

Work Order Custom Fields

Write current Meter Value 88289

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	05/05/2020	N	2	38.32	76.63
						Subtotal	76.63
						Total	76.63

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16020198	BRAKE CALIPER	EA	1	55.07	55.07
	CMF	16020148	WAGNER BRAKE PAD MX757	EA	1	38.95	38.95
	CMF	16010020	22" SUMMER WIPER BLADE 31-22	EA	2	3.50	7.00
						Subtotal	101.02
						Total	101.02

Work Order 581346 (FLEET) marker lights and cab lights inop, dies at an idle

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/21/2020

Scheduled Start Date 05/21/2020

Scheduled End Date 05/21/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 233.27

Date Completed 05/22/2020

Work Order Comments

DRING [05/22/2020 12:53]:

repaired wire on rear of truck, replaced bulbs on cab lights and cleaned throttle body

Work Order Custom Fields

Write current Meter Value 88522

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	05/21/2020	N	3.5	47.81	167.32
		Tim Bain	05/21/2020	N	1.5	39.68	59.52
						Subtotal	226.85
						Total	226.85

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010129	LED AMBER MARKER LIGHT ROUND TRUCKLITE 50-10202Y-3	EA	1	1.26	1.26
	CMF	08010273	AUTOMOTIVE LAMP BULB 194	EA	1	1.29	1.29
	CMF	08010273	AUTOMOTIVE LAMP BULB 194	EA	3	1.29	3.87
						Subtotal	6.42
						Total	6.42

Work Order 583278 (FLEET) TOW - BUCKY TO CITY GARAGE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By TEDDY Tanner Eddy

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 06/15/2020

Scheduled End Date 06/15/2020

WO Type CM

Class FT-CONT

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 45.00

Date Completed 06/15/2020

Work Order Custom Fields

Write current Meter Value 88522

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	TOW	TOW CHARGE	EACH	1	45.00	45.00
						Subtotal	45.00
						Total	45.00

Work Order 583336 (FLEET) REPAIR HOSE AND PUMP ON RELEASE AGENT TANK, REPAIR MUDFLAP
Status Closed

Scheduled Start Date 06/16/2020
Scheduled End Date 06/16/2020
WO Type CM



Parent Work Order
Department PW PUBLIC WORKS
PM Code
Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair
Problem Code
Reported By
Project
Standard WO

Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location S A 1301 (FLEET-C) S A 1301
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 06/16/2020

Estimated Hours 1
Estimated Cost 0.00
Actual Cost 214.19
Date Completed 07/09/2020

Work Order Comments

DRING [07/09/2020 08:24]:
 FABRICATED BRACKET FOR PUMP AND INSTALLED NEW HOSE

Work Order Custom Fields

Write current Meter Value 89053

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	06/16/2020	N	3.5	38.32	134.10
						Subtotal	134.10
						Total	134.10

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050074	MUD FLAP 24X30	EA	1	15.80	15.80
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	11060085	1/4" SHANK WIRE BRUSH 72727	EA	1	3.49	3.49
	CMF	07030058	3/8" TRANS HOSE H1937- 27059	FT	15	3.72	55.80
						Subtotal	80.09
						Total	80.09

Work Order 587231 (FLEET) REPLACE MARINE BATTERY FOR SPRAYER

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By TEDDY Tanner Eddy

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/07/2020

Scheduled Start Date 08/07/2020

Scheduled End Date 08/07/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 141.34

Date Completed 08/17/2020

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	08/07/2020	N	0.5	49.03	24.52
						Subtotal	24.52
						Total	24.52

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08110015	GROUP 24M MARINE BATTERY AC DELCO M24MF	EA	1	116.82	116.82
						Subtotal	116.82
						Total	116.82

Work Order 590033 (FLEET) NO POWER WHILE PULLING A LOAD

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/15/2020

Scheduled Start Date 09/14/2020

Scheduled End Date 09/14/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 1,347.41

Date Completed 11/23/2020

Work Order Comments

DRING [11/23/2020 09:45]:

REPLACED PLUGS BOOTS 2COILS INTAKE GASKETS AND KNOCK SENSOR, NEW PCV VALVE AND HOSE

Work Order Custom Fields

Write current Meter Value 90415

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	09/15/2020	N	2	42.13	84.26
		Tim Bain	09/16/2020	N	2	42.13	84.26
		Tim Bain	11/06/2020	N	8	42.13	337.04
		Tim Bain	11/09/2020	N	8	42.13	337.04
		Tim Bain	11/10/2020	N	8	42.13	337.04
						Subtotal	1,179.65
						Total	1,179.65

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08050084	SPARK PLUG WIRE, SPARK PLUG BOOT	EA	8	8.76	70.08
	CMF	08050075	IGNITION COIL	EA	2	30.39	60.78
	CMF	08050001	SPARK PLUG	EA	2	3.69	7.38
	CMF	08050001	SPARK PLUG	EA	8	3.69	29.52
						Subtotal	167.76
						Total	167.76

Work Order 594181 (FLEET) runs rough intake gaskets and knock sensor

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/27/2020

Scheduled Start Date 10/28/2020

Scheduled End Date 10/28/2020

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 304.08

Date Completed 11/23/2020

Work Order Comments

DRING [11/23/2020 09:50]:

REPLACED INTAKE GASKETS AND PCV TUBE

Work Order Custom Fields

Write current Meter Value 90620

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	10/27/2020	N	4.5	42.13	189.59
						Subtotal	189.59
						Total	189.59

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08040625	KNOCK SENSOR	EA	1	21.93	21.93
	CMF	16080284	INTAKE GASKET	EA	1	66.09	66.09
	CMF	16070160	VEHICLE THERMOSTAT	EA	1	6.52	6.52
	CMF	11100055	PCV VALVE	EA	1	19.95	19.95
						Subtotal	114.49
						Total	114.49

Work Order 594324 (FLEET) S/C TO S/A TO START

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/29/2020

Scheduled Start Date 10/29/2020

Scheduled End Date 10/29/2020

WO Type CM

Class FT-SC

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 144.65

Date Completed 11/04/2020

Work Order Comments

DRING [11/04/2020 10:57]:

S/C JUMP STARTED BRAOUGHT TO SHOP TESTED BATTERY AND REPLACED

Work Order Custom Fields

Write current Meter Value 90,640 MILES

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	10/29/2020	N	1	47.15	47.15
						Subtotal	47.15
						Total	47.15

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08110014	GROUP 65 BATTERY AC DELCO 65FLEET	EA	1	97.50	97.50
						Subtotal	97.50
						Total	97.50

Work Order 595561 (FLEET) BENCH SEAT REPAIR - ALVARADO

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By TEDDY Tanner Eddy

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 11/16/2020

Scheduled End Date 11/16/2020

WO Type CM

Class FT-CONT

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 375.00

Date Completed 11/23/2020

Work Order Custom Fields

Write current Meter Value 90620

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16060067	REPLACEMENT SEAT OR SEAT REPAIR	EA	1	375.00	375.00
						Subtotal	375.00
						Total	375.00

Work Order 607021 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/18/2021

Scheduled Start Date 03/18/2021

Scheduled End Date 03/18/2021

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 93.94

Date Completed 03/18/2021

Work Order Comments

TBAIN [03/18/2021 13:09]:

serviced

Work Order Custom Fields

Write current Meter Value 92366

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	03/18/2021	N	1.5	42.13	63.20
						Subtotal	63.20
						Total	63.20

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	10020050	OIL FILTER 51372	EA	1	4.30	4.30
	CMF	13030012	5W30 OIL 5-30 (BULK - QT)	QT	7	1.57	11.01
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10010114	AIR FILTER 46418	EA	1	10.43	10.43
						Subtotal	30.74
						Total	30.74

Work Order 607024 (FLEET) TRAILER WIRING INOP

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/18/2021

Scheduled Start Date 03/18/2021

Scheduled End Date 03/18/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 90.95

Date Completed 03/18/2021

Work Order Comments

TBAIN [03/18/2021 13:11]:

cleaned and reconnected wires to 7 way plug all work good now

Work Order Custom Fields

Write current Meter Value 92366

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	03/18/2021	N	2	42.13	84.26
						Subtotal	84.26
						Total	84.26

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	13010012	BATTERY CLEANER 11OZ CRC 05023	EA	1	6.69	6.69
						Subtotal	6.69
						Total	6.69

Work Order 607536 (FLEET) RUNS ROUGH

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/19/2021

Scheduled Start Date 03/24/2021

Scheduled End Date 03/24/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 98.81

Date Completed 03/25/2021

Work Order Comments

TBAIN [03/25/2021 13:10]:

ran diagnostics and found no codes stored at this time and truck is running good. did find bad oil pressure sending unit and replaced it

Work Order Custom Fields

Write current Meter Value 92460

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	03/19/2021	N	2	42.13	84.26
						Subtotal	84.26
						Total	84.26

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08040206	OIL PRESSURE SWITCH / OIL PRESSURE SENSOR	EA	1	14.55	14.55
						Subtotal	14.55
						Total	14.55

Work Order 607839 (FLEET) RUNS ROUGH FUEL ISSUE
Status Closed

Parent Work Order
Department PW PUBLIC WORKS
PM Code
Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair
Problem Code
Reported By
Project
Standard WO
Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location S A 1301 (FLEET-C) S A 1301
Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 03/26/2021

Scheduled Start Date 03/26/2021
Scheduled End Date 03/26/2021
WO Type CM
Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To
Assigned By
Estimated Hours 1
Estimated Cost 0.00
Actual Cost 2,207.94
Date Completed 03/30/2021

Work Order Comments

TBAIN [03/30/2021 08:42]:
 diagnosed runnability problem. found intermittent fuel pressure drop off. trouble shoot down to fuel pump. replaced fuel pump truck runs good.

Work Order Custom Fields

Write current Meter Value 92496

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	03/26/2021	N	45	42.13	1,895.87
						Subtotal	1,895.87
						Total	1,895.87

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070215	FUEL PUMP	EA	1	98.64	98.64
	CMF	16070425	FUEL MODULE	EA	1	213.43	213.43
						Subtotal	312.07
						Total	312.07

Work Order 610044 (FLEET) TRAILER PLUG HAD LOOSE WIRES

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/15/2021

Scheduled Start Date 04/14/2021

Scheduled End Date 04/14/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 47.13

Date Completed 04/16/2021

Work Order Comments

TBAIN [04/16/2021 12:51]:

repaired loose wires on trailer connector

Work Order Custom Fields

Write current Meter Value 92790

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	04/15/2021	N	1	42.13	42.13
						Subtotal	42.13
						Total	42.13

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	5.00
						Total	5.00

Work Order 611631 (FLEET) FAN ONLY WORKS ON HIGH

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/23/2021

Scheduled Start Date 04/23/2021

Scheduled End Date 04/23/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 78.73

Date Completed 04/27/2021

Work Order Comments

TBAIN [04/27/2021 09:19]:
replaced blower motor resistor
TBAIN [04/27/2021 09:19]:
and resistor pigtail

Work Order Custom Fields

Write current Meter Value 92997

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	04/23/2021	N	1	42.13	42.13
						Subtotal	42.13
						Total	42.13

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	11070003	BLACK ELECTRICAL TAPE 3M SUPER 33+	EA	1	3.97	3.97
	CMF	08020027	PIGTAIL	EA	1	9.50	9.50
	CMF	08090077	BLOWER FAN / BLOWER MOTOR RESISTOR	EA	1	23.13	23.13
						Subtotal	36.60
						Total	36.60

Work Order 611910 (FLEET) GAS LEAK FROM TANK

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/03/2021

Scheduled Start Date 04/27/2021

Scheduled End Date 04/27/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 564.25

Date Completed 05/04/2021

Work Order Comments

TBAIN [05/04/2021 09:22]:

replaced fuel tank

Work Order Custom Fields

Write current Meter Value 93021

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	05/03/2021	N	4	42.13	168.52
						Subtotal	168.52
						Total	168.52

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	15020431	FUEL TANK	EA	1	395.73	395.73
						Subtotal	395.73
						Total	395.73

Work Order 613532 (FLEET) WIRING BAD IN REAR OF FLAT BED

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/18/2021

Scheduled Start Date 05/18/2021

Scheduled End Date 05/18/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 117.66

Date Completed 05/20/2021

Work Order Comments

CSOUSA [05/20/2021 08:18]:

Found fault in wiring for the three marker lights on flat bed of truck. Found all three pigtails and lights corroded. Cleaned contacts on one light, replaced two lights and repaired wiring harness.

Work Order Custom Fields

Write current Meter Value 93153

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	05/18/2021	N	2	49.03	98.06
						Subtotal	98.06
						Total	98.06

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08020030	2-WIRE PIGTAIL NAPA 50-94902-3	EA	2	1.16	2.32
	CMF	08010189	RED LED LIGHT ROUND G1032	EA	1	8.06	8.06
	CMF	08010189	RED LED LIGHT ROUND G1032	EA	1	8.06	8.06
	CMF	08020030	2-WIRE PIGTAIL NAPA 50-94902-3	EA	1	1.16	1.16
						Subtotal	19.60
						Total	19.60

Work Order	615934 (FLEET) BRAKES MADE BAD SQUEELING NOISE THEN WENT AWAY	Scheduled Start Date	06/17/2021
Status	Closed	Scheduled End Date	06/17/2021
		WO Type	CM
Parent Work Order		Class	FT-CM
Department	PW PUBLIC WORKS	Priority	
PM Code		Warranty	N
Cost Code	C06800-633200 EquipMaint-Vehicle&Equip Repair	Safety	N
Problem Code		Equip Criticality	
Reported By		Assigned To	KEITHRODENBURG
Project		Assigned By	RG
Standard WO			
Equipment	AR414RT1 (FLEET-C)	2001 Ford F-350 Chassis Cab / Flatbed	
Location	S A 1301 (FLEET-C)	S A 1301	
Equipment Manufacturer	FORD	Estimated Hours	1
Equipment Model	F-350	Estimated Cost	0.00
Equipment Serial Number	1FDWF36S91EB12055	Actual Cost	21.07
Date Started	06/18/2021	Date Completed	06/18/2021

Work Order Comments

KTRODENBURG [06/18/2021 10:53]:

Test drove truck to verify complaint and could not duplicate problem. Put truck on lift and inspected brake pads but they were above spec. Double checked brake fluid was at proper level and returned truck back into service due to not being able to duplicate issue.

Work Order Custom Fields

Write current Meter Value 93639

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		
					

Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	06/18/2021	N	0.5	42.13	21.07
						Subtotal	21.07
						Total	21.07

Work Order 622134 (FLEET) Flat tire

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/07/2021

Scheduled Start Date 09/07/2021

Scheduled End Date 09/07/2021

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 521.97

Date Completed 09/09/2021

Work Order Comments

SPOPE [09/07/2021 13:48]:

Service call, take one duel off and put on front to get truck back to shop and order new steer tire.

KTRODENBURG [09/09/2021 08:01]:

Replaced steer tire with new, and swapped wheel back to left rear.

SPOPE [09/09/2021 12:37]:

Replaced left front steer tire (new tire, had to order in).

Work Order Custom Fields

Write current Meter Value 94760

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	09/09/2021	N	0.5	45.73	22.87
		Scott Pope	09/07/2021	N	1.5	51.49	77.23
		Scott Pope	09/08/2021	N	1	51.49	51.49
						Subtotal	151.58
						Total	151.58

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12010074	LT215/85R16 TIRE	EA	2	185.00	370.00
	CMF	12010074	LT215/85R16 TIRE	EA	-1	195.00	-195.00
	CMF	12090030	TR600HP TOPSEAL SNAP-IN VALVE STEM 2-417	EA	1	0.39	0.39
	CMF	12010074	LT215/85R16 TIRE	EA	1	195.00	195.00
						Subtotal	370.39

Work Order 622469 (FLEET) BRAKE LIGHT OUT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/13/2021

Scheduled Start Date 09/13/2021

Scheduled End Date 09/13/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To RNIXON

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 26.68

Date Completed 09/13/2021

Work Order Comments

RNIXON [09/13/2021 10:35]:

replaced light bulb

Work Order Custom Fields

Write current Meter Value 94868

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	09/13/2021	N	0.5	51.49	25.74
						Subtotal	25.74
						Total	25.74

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010284	AUTOMOTIVE LAMP BULB 3157	EA	1	0.94	0.94
						Subtotal	0.94
						Total	0.94

Work Order 623164 (FLEET) check cause of trans wont go into gear

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/22/2021

Scheduled Start Date 09/22/2021

Scheduled End Date 09/22/2021

WO Type CM

Class FT-MISC

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 469.58

Date Completed 10/07/2021

Work Order Comments

CSOUSA [10/07/2021 14:45]:

Found shift tube broken and trans shift cable hard to move. Replaced shift tube and cable.

Replaced shift indicator in cluster.

Fixed broken wires under dash for turn signals.

Work Order Custom Fields

Write current Meter Value 95110

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	09/22/2021	N	2	44.24	88.48
		Chase Sousa	10/26/2021	N	4	44.24	176.96
						Subtotal	265.44
						Total	265.44

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16100041	FORD STEERING COLUMN BEARING F3TZ3517A	EA	1	78.20	78.20
	CMF	16070012	SHIFTER CABLE	EA	1	65.37	65.37
	CMF	16070433	SHIFT INDICATOR	EA	1	41.94	41.94
	CMF	11100055	PCV VALVE	EA	1	18.63	18.63
						Subtotal	204.14
						Total	204.14

Work Order 626182 (FLEET) DINGY LIGHT INOP AND WIPERS BAD

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/27/2021

Scheduled Start Date 10/27/2021

Scheduled End Date 10/27/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To RNIXON

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 25.74

Date Completed 10/28/2021

Work Order Comments

RNIXON [10/28/2021 14:07]:

dingy light INOP. wire going to dingy light switch rub through repair wire .light is know working

Work Order Custom Fields

Write current Meter Value 95623

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	10/27/2021	N	0.5	51.49	25.74
						Subtotal	25.74
						Total	25.74

Work Order 626472 (FLEET) towed in belt came off

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/29/2021

Scheduled Start Date 10/28/2021

Scheduled End Date 10/28/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 377.52

Date Completed 01/11/2022

Work Order Comments

CSOUSA [11/05/2021 15:20]:

Replaced belt tensioner assembly, idler pulley, and drivebelt.

Work Order Custom Fields

Write current Meter Value 95662

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

10

MECH

1

1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	09/29/2021	N	2	44.24	88.48
						Subtotal	88.48
						Total	88.48

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070317	BELT TENSIONER	EA	1	76.55	76.55
	CMF	16070361	IDLER PULLEY	EA	1	40.79	40.79
	CMF	07010126	SERP BELT 25-080806	EA	1	21.57	21.57
	CMF	16070317	BELT TENSIONER	EA	1	57.19	57.19
	CMF	16070361	IDLER PULLEY	EA	1	22.94	22.94
	CMF	TOW	TOW CHARGE	EACH	1	70.00	70.00
						Subtotal	289.04
						Total	289.04

Work Order 628387 (FLEET) PULLS TO THE RIGHT WHEN BRAKING

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/22/2021

Scheduled Start Date 11/22/2021

Scheduled End Date 11/22/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 310.23

Date Completed 11/24/2021

Work Order Comments

CSOUSA [11/24/2021 08:31]:

Found caliper slide pin on drivers front brake assembly seized. Replaced caliper, caliper bracket, and brake hose.

Work Order Custom Fields

Write current Meter Value 95991

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	11/22/2021	N	3	44.24	132.72
		Chase Sousa	11/23/2021	N	2	44.24	88.48
						Subtotal	221.20
						Total	221.20

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16020198	BRAKE CALIPER	EA	1	68.04	68.04
	CMF	07030031	BRAKE HOSE 609	EA	1	20.99	20.99
						Subtotal	89.03
						Total	89.03

Work Order 628992 (FLEET) RIGHT FRONT MAKING NOISE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/01/2021

Scheduled Start Date 12/01/2021

Scheduled End Date 12/01/2021

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SROSS

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 102.97

Date Completed 12/02/2021

Work Order Comments

SROSS [12/02/2021 12:01]:

Pulled right front wheel inspected brakes found anti rattle clip bent removed clip cured problem.

Work Order Custom Fields

Write current Meter Value 96143

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Steve Ross	12/01/2021	N	1	51.49	51.49
		Steve Ross	12/02/2021	N	1	51.49	51.49
						Subtotal	102.97
						Total	102.97

Work Order 630528 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location S A 1301 (FLEET-C)

S A 1301

Equipment FORD

Manufacturer

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/17/2021

Scheduled Start Date 12/17/2021

Scheduled End Date 12/17/2021

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TBAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 103.65

Date Completed 12/21/2021

Work Order Comments

TBAIN [12/21/2021 11:56]:

revised

Work Order Custom Fields

Write current Meter Value 96548

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	12/17/2021	N	1.5	45.73	68.60
						Subtotal	68.60
						Total	68.60

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	10020050	OIL FILTER 51372	EA	1	3.69	3.69
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	13030033	5W30 FULL SYNTHETIC OIL DEXOS APPROVED 5-30 (BULK - QT)	QT	7	2.63	18.40
	CMF	10010114	AIR FILTER 46418	EA	1	7.96	7.96
						Subtotal	35.05
						Total	35.05

Work Order 636331 (FLEET) REPLACE BRAKE CONTROLLER

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 02/16/2022

Scheduled Start Date 02/16/2022

Scheduled End Date 02/16/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 161.76

Date Completed 02/16/2022

Work Order Comments

SPOPE [02/16/2022 10:15]:

Check out and wire in new brake controller.

Work Order Custom Fields

Write current Meter Value 97505

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	02/16/2022	N	2	51.49	102.97
						Subtotal	102.97
						Total	102.97

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16020045	TRAILER BRAKE CONTROL 5100 - NAPA 755-2062	EA	1	58.79	58.79
						Subtotal	58.79
						Total	58.79

Work Order 636608 (FLEET) DINGY LIGHT SWITCH BROKE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 02/18/2022

Scheduled Start Date 02/18/2022

Scheduled End Date 02/18/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 33.95

Date Completed 02/18/2022

Work Order Comments

SPOPE [02/18/2022 10:03]:

Replaced switch for strobe light.

Work Order Custom Fields

Write current Meter Value 95750

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	02/18/2022	N	0.5	51.49	25.74
						Subtotal	25.74
						Total	25.74

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08040079	TOGGLE SWITCH TG6039	EA	1	8.21	8.21
						Subtotal	8.21
						Total	8.21

Work Order 637425 (FLEET) RIGHT TRAILER TURN SIGNAL OUT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/01/2022

Scheduled Start Date 03/01/2022

Scheduled End Date 03/01/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 60.87

Date Completed 03/02/2022

Work Order Comments

CSOUSA [03/02/2022 12:50]:

Found bad pins in connector. Replaced connector

Work Order Custom Fields

Write current Meter Value 97687

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	03/01/2022	N	1	44.24	44.24
						Subtotal	44.24
						Total	44.24

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08030101	7-WIRE FEMALE TRAILER PLUG 755-1526	EA	1	11.63	11.63
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	16.63
						Total	16.63

Work Order 640236 (FLEET) SHIFTER CABLE BROKEN

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/25/2022

Scheduled Start Date 03/25/2022

Scheduled End Date 03/25/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 123.45

Date Completed 03/29/2022

Work Order Comments

CSOUSA [03/29/2022 09:53]:

Replaced shifter cable

Work Order Custom Fields

Write current Meter Value 98065

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	03/25/2022	N	1.5	44.24	66.36
						Subtotal	66.36
						Total	66.36

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070012	SHIFTER CABLE	EA	1	57.09	57.09
						Subtotal	57.09
						Total	57.09

Work Order 642049 (FLEET) BATTERY - BATTERY BOXES

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 04/14/2022

Scheduled End Date 04/14/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 147.34

Date Completed 04/15/2022

Work Order Custom Fields

Write current Meter Value 98065

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08110149	GROUP 27MF MARINE BATTERY AC DELCO M27M750	EA	1	103.32	103.32
	CMF	16050360	BATTERY BOX COVER	EA	1	22.01	22.01
	CMF	16050360	BATTERY BOX COVER	EA	1	22.01	22.01
						Subtotal	147.34
						Total	147.34

Work Order 642089 (FLEET) MARKER LIGHT OUT ON BOX

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/15/2022

Scheduled Start Date 04/15/2022

Scheduled End Date 04/15/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To RNIXON

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 34.82

Date Completed 04/15/2022

Work Order Comments

RNIXON [04/15/2022 12:24]:
replaced left side marker light

Work Order Custom Fields

Write current Meter Value 98413

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	04/15/2022	N	0.5	51.49	25.74
						Subtotal	25.74
						Total	25.74

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010189	RED LED LIGHT ROUND G1032	EA	1	9.08	9.08
						Subtotal	9.08
						Total	9.08

Work Order 643778 (FLEET) REPLACE TIRES

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/03/2022

Scheduled Start Date 05/03/2022

Scheduled End Date 05/03/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To RNIXON

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 585.13

Date Completed 05/06/2022

Work Order Comments

RNIXON [05/06/2022 10:06]:

replaced tire

Work Order Custom Fields

Write current Meter Value 98413

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ron Nixon	05/03/2022	N	1	51.49	51.49
						Subtotal	51.49
						Total	51.49

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12010074	LT215/85R16 TIRE	EA	4	133.41	533.64
						Subtotal	533.64
						Total	533.64

Work Order 644781 (FLEET) REWORK HEADACHE RACK AND RATTLE IN RIGHT DOOR
Status Closed

Scheduled Start Date 05/11/2022
Scheduled End Date 05/11/2022
WO Type CM



Parent Work Order
Department PW PUBLIC WORKS
PM Code
Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair
Problem Code
Reported By
Project
Standard WO

Class FT-CM
Priority
Warranty N
Safety N
Equip Criticality
Assigned To SVOLFF
Assigned By

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed
Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD
Equipment Model F-350
Equipment Serial Number 1FDWF36S91EB12055
Date Started 05/10/2022

Estimated Hours 1
Estimated Cost 0.00
Actual Cost 199.99
Date Completed 05/11/2022

Work Order Comments

SVOLFF [05/11/2022 11:54]:

cut out , re-weld for re shaping of headache rack also replace windshield wipers , battery cable ends and weld driver side outside step bracket

Work Order Custom Fields

Write current Meter Value 98413

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Volff	05/10/2022	N	3	36.66	109.97
		Scott Volff	05/11/2022	N	2	36.66	73.31
					Subtotal		183.29
					Total		183.29

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	16010019	20" SUMMER WIPER BLADE 31-20	EA	2	5.85	11.70
					Subtotal		16.70
					Total		16.70

Work Order 645160 (FLEET) FLAT TIRE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/13/2022

Scheduled Start Date 05/13/2022

Scheduled End Date 05/13/2022

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To BCAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 108.36

Date Completed 05/20/2022

Work Order Comments

BCAIN [05/20/2022 10:17]:

service call to omaha removed inside dual , brought back to shop repaired tire

Work Order Custom Fields

Write current Meter Value 98942

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ben Cain	05/13/2022	N	2	51.49	102.97
						Subtotal	102.97
						Total	102.97

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12090030	TR600HP TOPSEAL SNAP-IN VALVE STEM 2-417	EA	1	0.39	0.39
	CMF	12090115	TIRE PATCH - FOR WORK ORDERS	EA	1	5.00	5.00
						Subtotal	5.39
						Total	5.39

Work Order 646400 (FLEET) LEFT LOWER BRAKE LIGHT OUT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/31/2022

Scheduled Start Date 05/31/2022

Scheduled End Date 05/31/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 44.45

Date Completed 05/31/2022

Work Order Comments

SPOPE [05/31/2022 08:19]:

Repair left rear tail light and add 2 qts of oil.

Work Order Custom Fields

Write current Meter Value 99314

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	05/31/2022	N	0.5	51.49	25.74
						Subtotal	25.74
						Total	25.74

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010284	AUTOMOTIVE LAMP BULB 3157	EA	1	0.94	0.94
	CMF	13020030	10W30 OIL 10-30 1QT	EA	2	8.88	17.77
						Subtotal	18.71
						Total	18.71

Work Order 649840 (FLEET) DEAD BATTERY AT 1301

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/11/2022

Scheduled Start Date 07/11/2022

Scheduled End Date 07/11/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To LHAMMERMEISTER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 51.49

Date Completed 07/12/2022

Work Order Comments

LHAMMERMEISTER [07/12/2022 08:50]:

S/C to jump start.

Work Order Custom Fields

Write current Meter Value 100010

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10	MECH	1	1		
----	------	---	---	--	--



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	07/11/2022	N	1	51.49	51.49
						Subtotal	51.49
						Total	51.49

Work Order 650116 (FLEET) REPLACE BATTERY AND REPAIR HOSE ON SPRAY

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/14/2022

Scheduled Start Date 07/14/2022

Scheduled End Date 07/14/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To DMAREAN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 281.66

Date Completed 07/18/2022

Work Order Comments

DMAREAN [07/18/2022 12:57]:

load check batt failed intall new batt check for propper charge replace damaged liquid hose on rear pump assembly

Work Order Custom Fields

Write current Meter Value 100018

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Darrell Marean	07/14/2022	N	2	51.49	102.97
						Subtotal	102.97
						Total	102.97

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08110014	GROUP 65 BATTERY AC DELCO 65FLEET	EA	1	97.50	97.50
	CMF	07030067	1/2" CLEAR HOSE, TUBING TF4 (FT)	EA	20	0.82	16.45
	CMF	08090028	FLOJET PUMP FJG5700	EA	1	64.74	64.74
						Subtotal	178.69
						Total	178.69

Work Order 652533 (FLEET) LINE BROKEN ON SPRAY TANK

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/17/2022

Scheduled Start Date 08/17/2022

Scheduled End Date 08/17/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To LHAMMERMEISTER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 33.01

Date Completed 08/22/2022

Work Order Comments

LHAMMERMEISTER [08/22/2022 09:52]:

Replaced hose on spray tank.

Work Order Custom Fields

Write current Meter Value 100299

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Lynn Hammermeister	08/17/2022	N	0.5	49.59	24.79
						Subtotal	24.79
						Total	24.79

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	07030067	1/2" CLEAR HOSE, TUBING TF4 (FT)	EA	10	0.82	8.22
	CMF	07030067	1/2" CLEAR HOSE, TUBING TF4 (FT)	EA	7	0.82	5.76
	CMF	07030067	1/2" CLEAR HOSE, TUBING TF4 (FT)	EA	-7	0.82	-5.76
						Subtotal	8.22
						Total	8.22

Work Order 653154 (FLEET) repair right front tire

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/25/2022

Scheduled Start Date 08/25/2022

Scheduled End Date 08/25/2022

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To KEITHRODENBURG

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 33.13

Date Completed 08/25/2022

Work Order Comments

KTRODENBURG [08/25/2022 11:59]:

Repaired right front tire with patch.

Work Order Custom Fields

Write current Meter Value 100395

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	08/25/2022	N	0.5	46.25	23.13
						Subtotal	23.13
						Total	23.13

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12090115	TIRE PATCH - FOR WORK ORDERS	EA	1	5.00	5.00
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
						Subtotal	10.00
						Total	10.00

Work Order 655850 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/26/2022

Scheduled Start Date 09/26/2022

Scheduled End Date 09/26/2022

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TBAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 111.66

Date Completed 10/19/2022

Work Order Comments

TBAIN [10/19/2022 11:45]:
serviced

Work Order Custom Fields

Write current Meter Value 100815

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	09/26/2022	N	1.5	46.25	69.38
						Subtotal	69.38
						Total	69.38

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	10020050	OIL FILTER 51372	EA	1	4.44	4.44
	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	13030033	5W30 FULL SYNTHETIC OIL DEXOS APPROVED 5-30 (BULK - QT)	QT	7	3.11	21.74
	CMF	10010114	AIR FILTER 46418	EA	1	11.10	11.10
						Subtotal	42.28
						Total	42.28

Work Order 655851 (FLEET) RIGHT REAR SPRING U BOLT PLATE BROKEN

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/26/2022

Scheduled Start Date 09/26/2022

Scheduled End Date 09/26/2022

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TBAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 102.86

Date Completed 10/19/2022

Work Order Comments

TBAIN [10/19/2022 11:47]:

replaced right side spring u bolts and plate.

Work Order Custom Fields

Write current Meter Value 100815

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	09/26/2022	N	1	46.25	46.25
						Subtotal	46.25
						Total	46.25

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	11050155	U BOLT, U-BOLT	EA	1	56.61	56.61
						Subtotal	56.61
						Total	56.61

Work Order 657132 (FLEET) LEFT REAR OUTSIDE TIRE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 10/10/2022

Scheduled Start Date 10/10/2022

Scheduled End Date 10/10/2022

WO Type CM

Class FT-TIRE

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 54.59

Date Completed 10/10/2022

Work Order Comments

SPOPE [10/10/2022 14:45]:
Repaired left rear outside tire.

Work Order Custom Fields

Write current Meter Value 100917

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	10/10/2022	N	1	49.59	49.59
						Subtotal	49.59
						Total	49.59

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12090115	TIRE PATCH - FOR WORK ORDERS	EA	1	5.00	5.00
						Subtotal	5.00
						Total	5.00

Work Order 664560 (FLEET) TURN SIGNAL OUT AND NO TRAILER LIGHTS

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 01/10/2023

Scheduled Start Date 01/06/2023

Scheduled End Date 01/06/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 26.19

Date Completed 01/11/2023

Work Order Comments

SPOPE [01/11/2023 12:41]:

Replaced fuse.

Work Order Custom Fields

Write current Meter Value 101840

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	01/10/2023	N	0.5	49.59	24.79
						Subtotal	24.79
						Total	24.79

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010284	AUTOMOTIVE LAMP BULB 3157	EA	1	0.94	0.94
	CMF	08060044	FUSE ATM-20	EA	1	0.46	0.46
						Subtotal	1.40
						Total	1.40

Work Order 670139 (FLEET) HOOD LATCH BROKEN

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/03/2023

Scheduled Start Date 03/03/2023

Scheduled End Date 03/03/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SPOPE

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 53.07

Date Completed 03/03/2023

Work Order Comments

SPOPE [03/03/2023 12:53]:

Repair hood latch, found broken spring in latch assembly.

Work Order Custom Fields

Write current Meter Value 102755

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Pope	03/03/2023	N	1	49.59	49.59
						Subtotal	49.59
						Total	49.59

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	HARDWARE	MISC HARDWARE STORE PURCHASE - MENARDS / ACE / HOME DEPOT / ETC	EACH	1	3.48	3.48
						Subtotal	3.48
						Total	3.48

Work Order 671035 (FLEET) TRAILER LIGHTS DON'T WORK

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/10/2023

Scheduled Start Date 03/10/2023

Scheduled End Date 03/10/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SVOLFF

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 20.33

Date Completed 03/13/2023

Work Order Comments

SVOLFF [03/13/2023 07:12]:

replaced trailer fuse on truck side .. cleaned and greased trailer plug

Work Order Custom Fields

Write current Meter Value 102871

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Volf	03/10/2023	N	0.5	39.74	19.87
						Subtotal	19.87
						Total	19.87

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08060044	FUSE ATM-20	EA	1	0.46	0.46
						Subtotal	0.46
						Total	0.46

Work Order 671127 (FLEET) TRAILER MARKER LIGHTS INOP

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/13/2023

Scheduled Start Date 03/13/2023

Scheduled End Date 03/13/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To CSOUSA

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 22.02

Date Completed 03/24/2023

Work Order Comments

CSOUSA [03/24/2023 07:28]:

Replaced fuse in truck box for trailer parking lights

Work Order Custom Fields

Write current Meter Value 102897

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Chase Sousa	03/13/2023	N	0.5	44.05	22.02
						Subtotal	22.02
						Total	22.02

Work Order 672075 (FLEET) TURN SIGNALS INOP.

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 03/21/2023

Scheduled Start Date 03/21/2023

Scheduled End Date 03/21/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TTORGERSON

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 79.57

Date Completed 03/22/2023

Work Order Comments

TTORGERSON [03/22/2023 11:36]:

diagnose and replace inop flasher

Work Order Custom Fields

Write current Meter Value 103043

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Troy Torgerson	03/21/2023	N	1.5	39.74	59.62
						Subtotal	59.62
						Total	59.62

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08040247	FLASHER RELAY MOTORCRAFT 5C3Z13350AA	EA	1	19.95	19.95
						Subtotal	19.95
						Total	19.95

Work Order 674883 (FLEET) RUNS POORLY

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/19/2023

Scheduled Start Date 04/19/2023

Scheduled End Date 04/19/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TBAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 223.24

Date Completed 04/26/2023

Work Order Comments

TBAIN [04/26/2023 14:57]:

found o2 ciruit shorted to power . repaired short to power and installed new fuse. truck runs good now.

Work Order Custom Fields

Write current Meter Value 103434

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	04/19/2023	N	4.5	46.25	208.13
						Subtotal	208.13
						Total	208.13

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08050053	SPARK PLUG SP-479 MOTORCRAFT AGSF22WM	EA	1	15.11	15.11
						Subtotal	15.11
						Total	15.11

Work Order 676439 (FLEET) LEFT FRONT TIRE GOES FLAT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/08/2023

Scheduled Start Date 05/08/2023

Scheduled End Date 05/08/2023

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To KEITHRODENBURG

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 28.13

Date Completed 05/09/2023

Work Order Comments

KTRODENBURG [05/09/2023 07:50]:

Repaired left front tire with patch.

Work Order Custom Fields

Write current Meter Value 103626

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		
					
Note					

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	05/08/2023	N	0.5	46.25	23.13
						Subtotal	23.13
						Total	23.13

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	12090115	TIRE PATCH - FOR WORK ORDERS	EA	1	5.00	5.00
						Subtotal	5.00
						Total	5.00

Work Order 682222 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/19/2023

Scheduled Start Date 07/19/2023

Scheduled End Date 07/19/2023

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 68.34

Date Completed 07/24/2023

Work Order Comments

PMEYER [07/24/2023 11:49]:
performed service

Work Order Custom Fields

Write current Meter Value 104953

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Philip Meyer	07/19/2023	N	0.5	40.84	20.42
						Subtotal	20.42
						Total	20.42

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	10020050	OIL FILTER 51372	EA	1	4.44	4.44
	CMF	13030033	5W30 FULL SYNTHETIC OIL DEXOS APPROVED 5-30 (BULK - QT)	QT	7	3.24	22.65
	CMF	10010114	AIR FILTER 46418	EA	1	15.83	15.83
						Subtotal	47.92
						Total	47.92

Work Order 682236 (FLEET) REPLACE FRONT BRAKE PADS

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/19/2023

Scheduled Start Date 07/19/2023

Scheduled End Date 07/19/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 119.39

Date Completed 07/24/2023

Work Order Comments

PMEYER [07/24/2023 11:49]:
replaced front brake pads

Work Order Custom Fields

Write current Meter Value 104953

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Philip Meyer	07/19/2023	N	1	40.84	40.84
						Subtotal	40.84
						Total	40.84

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16020294	BRAKE PAD	EA	1	19.95	19.95
	CMF	16040092	CLAMP CL7004432	EA	1	58.60	58.60
						Subtotal	78.55
						Total	78.55

Work Order 683124 (FLEET) EXHAUST LEAK IN CAB

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 07/31/2023

Scheduled Start Date 07/31/2023

Scheduled End Date 07/31/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TGOCHANOUR

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 435.71

Date Completed 08/10/2023

Work Order Comments

TGOCHANOUR [08/10/2023 12:33]:
install 10 plug 1 coil an number 6 injector

Work Order Custom Fields

Write current Meter Value 104973

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Todd Gochanour	07/31/2023	N	3	41.44	124.31
						Subtotal	124.31
						Total	124.31

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08050053	SPARK PLUG SP-479	EA	8	7.09	56.72
	CMF	08050084	MOTORCRAFT AGSF22WM	EA	8	4.89	39.12
	CMF	08050053	SPARK PLUG WIRE, SPARK PLUG BOOT	EA	2	3.69	7.38
	CMF	08050075	MOTORCRAFT AGSF22WM	EA	2	104.09	208.18
						Subtotal	311.40
						Total	311.40

Work Order 684966 (FLEET) FITTING BROKE ON SPRAY TANK

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 08/24/2023

Scheduled Start Date 08/24/2023

Scheduled End Date 08/24/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TBAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 49.71

Date Completed 10/03/2023

Work Order Comments

TBAIN [10/03/2023 11:25]:
repaired fitting.

Work Order Custom Fields

Write current Meter Value 105100

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Tim Bain	08/24/2023	N	1	49.71	49.71
						Subtotal	49.71
						Total	49.71

Work Order 686998 (FLEET) HAS MARKER LIGHT OUT ON BOX

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 09/20/2023

Scheduled Start Date 09/20/2023

Scheduled End Date 09/20/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To KEITHRODENBURG

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 24.86

Date Completed 09/26/2023

Work Order Comments

KTRODENBURG [09/21/2023 14:48]:

Installed new marker light but did not work. Did not repair at this time because they had to go get mix.

Work Order Custom Fields

Write current Meter Value 105657

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		
					
Note					

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Keith Rodenburg	09/20/2023	N	0.5	49.71	24.86
						Subtotal	24.86
						Total	24.86

Work Order 690385 (FLEET) PUMP FOR LIQUID ASPHALT RELEASE IS BAD

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 11/01/2023

Scheduled End Date 11/01/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TGOCHANOUR

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 59.99

Date Completed 12/22/2023

Work Order Custom Fields

Write current Meter Value 106567

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08090032	REPLACEMENT MOTOR, ELECTRIC MOTOR	EA	1	59.99	59.99
						Subtotal	59.99
						Total	59.99

Work Order 693628 (FLEET) MARKER LIGHT OUT ON BOX

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/07/2023

Scheduled Start Date 12/07/2023

Scheduled End Date 12/07/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To TTORGERSON

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 43.02

Date Completed 12/11/2023

Work Order Comments

TTORGERSON [12/11/2023 09:33]:

replace right box marker light repair wiring to right rear marker light

Work Order Custom Fields

Write current Meter Value 107070

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Troy Torgerson	12/07/2023	N	1	41.44	41.44
						Subtotal	41.44
						Total	41.44

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08010129	LED AMBER MARKER LIGHT ROUND TRUCKLITE 50-10202Y-3	EA	1	1.58	1.58
						Subtotal	1.58
						Total	1.58

Work Order 694259 (FLEET) COOLANT & TRANS. FLUID LEAK

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 12/13/2023

Scheduled Start Date 12/13/2023

Scheduled End Date 12/13/2023

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 126.55

Date Completed 12/20/2023

Work Order Comments

PMEYER [12/13/2023 15:13]:

replaced thermostat and tranny cooler lines.

Work Order Custom Fields

Write current Meter Value 107148

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Philip Meyer	12/13/2023	N	1.5	41.44	62.15
						Subtotal	62.15
						Total	62.15

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070160	VEHICLE THERMOSTAT	EA	1	11.26	11.26
	CMF	16070315	TRANSMISSION COOLER TUBE	EA	1	53.14	53.14
			FORD YC3Z7A031CA				
						Subtotal	64.40
						Total	64.40

Work Order 699013 (FLEET) REPLACE WINDSHIELD - GLASS DOCTOR

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By TEDDY Tanner Eddy

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started

Scheduled Start Date 02/07/2024

Scheduled End Date 02/07/2024

WO Type CM

Class FT-CONT

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 413.88

Date Completed 02/07/2024

Work Order Custom Fields

Write current Meter Value 107148

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		

Note

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050327	WINDSHIELD REPLACEMENT / GLASS REPLACEMENT	EA	1	413.88	413.88
						Subtotal	413.88
						Total	413.88

Work Order 707353 (FLEET) SERVICE

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/23/2024

Scheduled Start Date 04/23/2024

Scheduled End Date 04/23/2024

WO Type CM

Class FT-PM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 65.28

Date Completed 04/23/2024

Work Order Comments

PMEYER [04/23/2024 14:35]:
performed service.

Work Order Custom Fields

Write current Meter Value 109084

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Philip Meyer	04/23/2024	N	0.5	41.44	20.72
						Subtotal	20.72
						Total	20.72

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	SHOP FEE	SHOP SUPPLIES - MISC USE OF GREASE, RAGS, FLUIDS, HARDWARE	EACH	1	5.00	5.00
	CMF	13030033	5W30 FULL SYNTHETIC OIL DEXOS APPROVED 5-30 (BULK - QT)	QT	7	3.11	21.79
	CMF	10020050	OIL FILTER 51372	EA	1	4.44	4.44
	CMF	10010114	AIR FILTER 46418	EA	1	13.33	13.33
						Subtotal	44.56
						Total	44.56

Work Order 709041 (FLEET) TRACK ROD RUSTED OUT

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/10/2024

Scheduled Start Date 05/13/2024

Scheduled End Date 05/13/2024

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 162.14

Date Completed 05/16/2024

Work Order Comments

PMEYER [05/16/2024 10:44]:
replaced tracking arm brackets.

Work Order Custom Fields

Write current Meter Value 109804

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Philip Meyer	05/10/2024	N	1.5	41.44	62.15
						Subtotal	62.15
						Total	62.15

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050275	NON-STOCK VEHICLE BODY/INTERIOR PART	EA	1	99.99	99.99
						Subtotal	99.99
						Total	99.99

Work Order 709666 (FLEET) DRIVERS MIRROR DAMAGED

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By TEDDY Tanner Eddy

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 05/21/2024

Scheduled Start Date 05/21/2024

Scheduled End Date 05/21/2024

WO Type CM

Class FT-DAM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To BCAIN

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 165.44

Date Completed 11/08/2024

Work Order Comments

BCAIN [11/08/2024 14:10]:

replaced mirror assemble

Work Order Custom Fields

Write current Meter Value 109289

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
----------	-------	------------	-------------	-----------	-------------

10 MECH 1 1



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Ben Cain	05/21/2024	N	2	51.70	103.40
						Subtotal	103.40
						Total	103.40

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16050059	MIRROR	EA	1	62.04	62.04
						Subtotal	62.04
						Total	62.04

Work Order 711034 (FLEET) TRANS NOT SHIFTING CORRECTLY

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 06/07/2024

Scheduled Start Date 06/07/2024

Scheduled End Date 06/07/2024

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To PMEYER

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 139.38

Date Completed 06/10/2024

Work Order Comments

PMEYER [06/10/2024 11:22]:
replaced both oxygen sensors.

Work Order Custom Fields

Write current Meter Value 109609

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Philip Meyer	06/07/2024	N	1	41.44	41.44
						Subtotal	41.44
						Total	41.44

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	16070204	OXYGEN SENSOR	EA	-1	86.72	-86.72
	CMF	16070204	OXYGEN SENSOR	EA	2	92.33	184.66
						Subtotal	97.94
						Total	97.94

Work Order 723715 (FLEET) REPAIR HOSE ON SPRAY TANK

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C) 2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C) Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 11/12/2024

Scheduled Start Date 11/12/2024

Scheduled End Date 11/12/2024

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To BTILLEY

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 116.30

Date Completed 12/17/2024

Work Order Comments

BTILLEY [12/09/2024 12:52]:

fixed hose that was leaking

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Brian Tilley	11/12/2024	N	2	0.00	0.00
		Brian Tilley	11/12/2024	N	2	49.10	98.20
					Subtotal		98.20
					Total		98.20

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	07030053	1/2" HEATER HOSE H156 (FT)	EA	10	1.81	18.10
					Subtotal		18.10
					Total		18.10

Work Order 738350 (FLEET) REPLACE DINGY LIGHT SWITCH

Status Closed



Parent Work Order

Department PW PUBLIC WORKS

PM Code

Cost Code C06800-633200 EquipMaint-Vehicle&Equip Repair

Problem Code

Reported By

Project

Standard WO

Equipment AR414RT1 (FLEET-C)

2001 Ford F-350 Chassis Cab / Flatbed

Location PUBLIC WORKS OPERATIONS (FAC-C)

Public Works Operations

Equipment Manufacturer FORD

Equipment Model F-350

Equipment Serial Number 1FDWF36S91EB12055

Date Started 04/08/2025

Scheduled Start Date 04/08/2025

Scheduled End Date 04/08/2025

WO Type CM

Class FT-CM

Priority

Warranty N

Safety N

Equip Criticality

Assigned To SVOLFF

Assigned By

Estimated Hours 1

Estimated Cost 0.00

Actual Cost 33.36

Date Completed 04/08/2025

Work Order Comments

SVOLFF [04/08/2025 12:19]:

dash switch for dingy light brock replace switch

Work Order Custom Fields

Write current Meter Value 112506

Activities

Activity	Trade	Est. Hours	People Req.	Task Plan	Description
10	MECH	1	1		



Note

WO Actual Labor Hours

Activity	Task Plan	Employee	Start Date	Type	Hours	Rate	Line Total
10		Scott Volf	04/08/2025	N	0.5	50.74	25.37
						Subtotal	25.37
						Total	25.37

Actual Parts

Activity	Store	Part	Description	UOM	Quantity	Price	Line Total
10	CMF	08040544	2 WIRE ON/OFF TOGGLE SWITCH 786106	EA	1	7.99	7.99
						Subtotal	7.99
						Total	7.99