

Vehicle Inspection Form

Inventory ID:	Asset Number: B5377	Fair Market Value:
Short Description: Year <u>2023</u> Make <u>TOYOTA</u> Model <u>CAMRY LE SEDAN</u>		
VIN: 4 T 1 C 1 1 A K 5 P U 8 1 2 3 2 7		
Odometer: 3 9 0 3 6 <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers Odometer Accurate <input checked="" type="checkbox"/> Y <input type="checkbox"/> N: _____		
Long Description: This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs/Driveable <input type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u>2.5L, V4</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> is in unknown condition Repairs needed: <u>FLOODED</u> This vehicle was maintained every <u>5000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles Date Removed From Service: <u>5/07/2025</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual ___Speed Condition: <input type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is Unknown Condition Repairs Needed: _____ Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: _____		
Exterior: Color: _____ Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked _____ Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <u>FAIR</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: <u>FLOODED</u> Additional Damage: <u>FLOODED</u> Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Emergency equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Interior: Color _____ <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>FLOODED</u> Damage to Dash/Floor: <u>FLOODED</u> Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: _____ <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input checked="" type="checkbox"/> AC (Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown) <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual <input type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Windows <input type="checkbox"/> Door Locks <input type="checkbox"/> Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand _____ <input type="checkbox"/> Hitch: Type _____		
Location of Asset: _____ For more information contact: _____ Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		