Vehicle Inspection Form

| Inventory ID: | Asset Number: 0KB1212 | Fair Market Value: |
|---|-----------------------|--------------------|
| Short Description: Year 2007 Make CHEVY Model MALIBU | | |
| VIN: 1 G 1 Z S 5 7 F 3 7 F 2 8 4 7 6 5 Title Restriction: | | |
| Long Description: This Vehicle: ■ Starts □ Starts with a Boost & ■ Runs/Driveable □ Engine Runs □ Does Not Run □ For Parts Only Engine- Type: 2.2 L, V 4 ■ Gas □ Diesel Engine □ Propane/Natural Gas □ Gas/Electric Hybrid Engine Condition: ■ Runs □ Needs repair □ is in unknown condition | | |
| Repairs needed: | | |
| Exterior: Color: White Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Poor Tread: #Flat Hubcaps #_ Major Damage to: | | |
| Interior: Color Grey Cloth Vinyl Leather Damage to Seats: Dirty and stained. Damage to Dash/Floor: Dirty and stained. Radio: Stock or Brand & Model: AM/FM AM/FM Cassette AM/FM CD AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual Cruise Control Tilt Steering Remote Mirrors Climate Control Power: Steering Windows Door Locks Seats | | |
| Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand | | |
| Location of Asset: For more information contact: Division of Fleet Management - Annie Smith 502-782-0094 Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes. | | |