

Vehicle Inspection Form

Inventory ID:	Asset Number: OKB1201	Fair Market Value:																	
Short Description: Year <u>2007</u> Make <u>Chevy</u> Model <u>Malibu</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 600px;"> <tr> <td>1</td><td>G</td><td>1</td><td>Z</td><td>S</td><td>5</td><td>7</td><td>F</td><td>X</td><td>7</td><td>F</td><td>2</td><td>8</td><td>6</td><td>0</td><td>5</td><td>8</td> </tr> </table> Title Restriction: ☐ Y ☒ N			1	G	1	Z	S	5	7	F	X	7	F	2	8	6	0	5	8
1	G	1	Z	S	5	7	F	X	7	F	2	8	6	0	5	8			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr> <td>1</td><td>5</td><td>8</td><td>4</td><td>9</td><td>3</td> </tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	5	8	4	9	3											
1	5	8	4	9	3														
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>2.2L, V4</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every <u>5000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>7/8/2025</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>Speed</u> Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____																			
Exterior: Color: _____ Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>Fair</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: <u>Rust rings on the roof and paint chipping.</u> Additional Damage: <u>Rusted and missing cas cap.</u> Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>Tan</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: <u>Dirty</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats																			
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: _____ For more information contact: <u>Division of Fleet Management - Annie Smith 502-782-0094</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			