## **Vehicle Inspection Form**

Inventory ID: 6799	Asset Number:	Fair Market Value:
Short Description: Year 2013 Make CHEVY Model MPALA		
VIN: 291WF5E35D1240799 Title Restriction: DY NON Odometer: 97185 Miles Kilometers Odometer Accurate DY N:		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine-Type: 3.61, V ( Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed:		
This vehicle was maintained every Days Days Miles		
Date Removed From Service: Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:		
Exterior: Color: BLACK Windows: No Cracked Glass Cracked  Minor: Dents Scratches Dings Tire Condition: 660 Tread #Flat Hubcaps #_  Major Damage to:		
Additional Damage:		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions  Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color BLACK   Cloth   Vinyl   Leather  Damage to Seats:		
Damage to Dash/Floor: SMALL HOLES DIT EQUIP MOUNT		
Radio: Stock or Brand & Model:  AC (Condition: Cold Unknow Cruise Control Tilt Steering Power: Steering Windows	n) No AC Remote Mirrors Climate Conf	AM/FM AM/FM Cassette AM/FM CD Air Bags: Driver's Side Dual
Additional Equipment:		
Manufacturer Mo	del Serial #	
☐ Tool Box ☐ Light Bar ☐ Ladder Ra	ck Utility Body: Brand	☐ Hitch: Type
Location of Asset:		
For more information contact:	radio a Ualida.	311.1
OI OF CHOSE RELIES ON OF SUITO	manug a monday, on ruday nights, o	r Weekends. Stagger closing times by 10 minutes.