## Vehicle Inspection Form

Inventory ID: 6922	Asset Number:	Fair Market Value:
Short Description: Year 2016 Make DODGE Model CHARGER		
VIN: 2C3CDXAG8G4Z86311 Title Restriction: DY ZN		
Odometer: 220904 Miles   Kilometers Odometer Accurate   Y   N:		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine-Type: 3.4L, V 6 Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed:		
This vehicle was maintained every Days Days Miles		
Date Removed From Service: Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
Drivetrain: 2 Wheel Drive 14 Wheel Drive Condition:		
Exterior: Color: BLUE Windows: No Cracked Glass Cracked		
Minor: Dents Scratches Dings Tire Condition: GOOD Tread: #Flat Hubcaps #_		
Major Damage to:		
Additional Damage:		
Decais: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color BLACL Coloth Vinyl Leather		
Damage to Seats:		
Damage to Dash/Floor: DASH PANELS REMOVED DIT FQUIP. TRIM MISSING/LOOSE		
Radio: Stock or Brand & Model: DAM AM/FM AM/FM Cassette AM/FM CD		
AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Mod	elSerial #	
☐ Tool Box ☐ Light Bar ☐ Ladder Rac	k ☐ Utility Body: Brand	Hitch: Type
Location of Asset:		
For more information contact:  Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		