

Vehicle Inspection Form

Inventory ID: 6847

Asset Number:

Fair Market Value:

Short Description:

Year 2014

Make TOYOTA

Model CAMRY

VIN: 4T1BF1FKXEU444438

Title Restriction: ☐ Y ☒ N

Odometer: 11557316

☒ Miles ☐ Kilometers

Odometer Accurate ☐ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine-Type: 2.5L V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed:

This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles

Date Removed From Service:

Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior: Color: GRAY

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings

Tire Condition: GOOD Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to:

Additional Damage:

Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior: Color GRAY ☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: STAINS

Damage to Dash/Floor: RADIO SCREEN BROKEN, HOLES D/T EQUIP MOUNT

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats

Additional Equipment:

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.