Vehicle Inspection Form

Inventory ID:	Asset Number: 913	Fair Market Value:
		CHARGER
VIN: 2030DXAG8GH259593 Title Restriction: DY NO Odometer: 219854 Miles Kilometers Odometer Accurate Y N:		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only Engine-Type: 10 L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed:		
This vehicle was maintained every Days Days Miles Date Removed From Service: Maintenance Records: Available Not Available For Inspection Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:		
Drivetrain:		
Additional Damage: Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Cloth Vinyl Leather Damage to Seats:		
Damage to Dash/Floor: HOLES DIT EQUIP MOUNTS Radio: Stock or Brand & Model: DAM AM/FM Cassette AM/FM CD AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual Cruise Control Tilt Steering Remote Mirrors Climate Control Power: Steering Windows Door Locks Seats		
Additional Equipment: Manufacturer Model Serial # Tool Box		
Location of Asset: For more information contact: Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		