Vehicle Inspection Form

Inventory ID: Asset Number: 2028 Fair Market Value:
Short Description: Year 2019 Make DODGE Model CHARGER
VIN: 203CDXAG5KH434223 Title Restriction: DY ON
Odometer: 126264 Miles Kilometers Odometer Accurate Y J.N:
Long Description:
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only Engine-Type: 6 L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid
Engine Condition: Runs Needs repair is in unknown condition
Repairs needed:
This vehicle was maintained every Days Hours Miles
Date Removed From Service: Maintenance Records: Available Not Available For Inspection
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition
Repairs Needed:
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:
Exterior: Color: Scuer Windows: No Cracked Glass Cracked
Minor: Dents Scratches Dings Tire Condition: Tread: #Flat Hubcaps #_
Major Damage to:
Additional Damage:
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions
Emergency equip: None Has been removed & There are holes in the exterior There are no holes
Interior: Color BLACY Cloth Vinyl Leather
Damage to Seats:
Damage to Dash/Floor: HOLES DIT EQUIP MOUNT
Radio: Stock or Brand & Model: AM/FM AM/FM AM/FM Cassette AM/FM CD
AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual
Cruise Control Tilt Steering Remote Mirrors Climate Control
Power: Steering Windows Door Locks Seats
Additional Equipment:
Manufacturer Model Serial #
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type
Location of Asset:
For more information contact: Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.