Vehicle Inspection Form

Inventory ID:	Asset Number: 6819	Fair Market Value:
Short Description: Year 2014 Make DODGE Model CHARGER		
VIN: 2C3CDXAG9EH344890 Title Restriction: DY IN		
Odometer: 118922 Miles Kilometers Odometer Accurate Y VN:		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine-Type 3.4 L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed:		
This vehicle was maintained every Days Days Miles		
Date Removed From Service: Maintenance Records: Available I Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
Drivetrain: 2 Wheel Drive 4 Wheel Drive Condition:		
Exterior: Color: BLACK Windows: No Cracked Glass Cracked		
Minor: Dents Scratches Dings Tire Condition: Tread:#Flat Hubcaps #		
Major Damage to:		
Additional Damage:		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color BLACK Cloth Vinyl Leather		
Damage to Seats:		
Damage to Dash/Floor: House Dr Eque your		
Radio: Stock or Brand & Model: AM/FM AM/FM AM/FM Cassette AM/FM CD		
AC (Condition: Cold Unknown) No AC Air Bags: Driver's Side Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Moo	del Serial #	
☐ Tool Box ☐ Light Bar ☐ Ladder Rac		
Location of Asset:		
For more information contact:		
Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.		