

Vehicle Inspection Form

Inventory ID:

Asset Number:

Fair Market Value:

Short Description:

Year 2013

Make CHEVY

Model IMPALA

VIN:

2G1WF5E31D1240623

Title Restriction: ☐ Y ☒ N

Odometer:

118270

☒ Miles

☐ Kilometers

Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 3.6L V6 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed:

This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles

Date Removed From Service:

Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior:

Color: BLACK

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings

Tire Condition: GOOD

Tread: _____ #Flat _____ Hubcaps # _____

Major Damage to:

Additional Damage:

Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior:

Color: BLACK

☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats:

Damage to Dash/Floor: SMALL HOLES D/T EQUIP MOUNT

Radio: ☒ Stock or ☐ Brand & Model:

☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats

Additional Equipment:

Manufacturer

Model

Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand

☐ Hitch: Type

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.