

Vehicle Inspection Form

Inventory ID:

Asset Number:

16713

Fair Market Value:

Short Description:

Year 2011

Make FORD

Model TAURUS

VIN: 1FAHP2DW0B9130269

Title Restriction: ☐ Y ☒ N

Odometer:

185126

☒ Miles

☐ Kilometers

Odometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine-Type: 3.5 L, V 6 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed:

This vehicle was maintained every ☐ Days ☐ Hours ☐ Miles

Date Removed From Service:

Maintenance Records: ☐ Available ☐ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed:

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior:

Color: SILVER

Windows: ☐ No Cracked Glass

☒ Cracked WINDSHIELD

Minor: ☐ Dents ☒ Scratches ☒ Dings

Tire Condition: GOOD

Tread: #Flat Hubcaps #

Major Damage to:

Additional Damage:

Decals: ☒ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes

Interior:

Color TAN

☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: STAINS

Damage to Dash/Floor: HOLES D/T EQUIP MOUNT

Radio: ☒ Stock or ☐ Brand & Model:

☐ AM

☐ AM/FM

☐ AM/FM Cassette

☒ AM/FM CD

☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment:

Manufacturer

Model

Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand

☐ Hitch: Type

Location of Asset:

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Slagger closing times by 10 minutes.