Vehicle Inspection Form

Inventory ID:		Asset Number: 4523	Fair Ma	ket Value:
Short Description: Year 2016	Make Furt	Model	Explore	
VIN: 1 F 71 Odometer: 1 6	5 K B A	R 4 6 6 C 6 I	L/ 5	7 Title Restriction: □Y ØN
Engine Condition: Repairs needed: This vehicle was maintain Date Removed From Series	v6 V_I Gauns □ Needs repaired every	ir is in unknown condition Days Hours Mil	ne/Natural (
Drivetrain: ☐ 2 Wheel Exterior: Color: _ Minor: ☐ Dents ☐ Scra	tches Dings	Windows: No Cracked Tire Condition:	d Gloss 🔲	Cracked
Additional Damage: Decals: None Ha Emergency equip: N Interior: Color	ive Been Sprayed		☐ Impress	ons Remain No Impressions
Damage to Seats: Damage to Dash/Floor: Radio: Stock or Bra AC (Condition: Co Cruise Control Tilt: Power: Steering	nd & Model: ld Unknown) Steering Ren	□ No AC Ai note Mirrors	Page T	AM/FM Cassette AM/FM CD Driver's Side Dual
Additional Equipment:	Model	Serial #		
ocation of Asset:	antect:	ng a Holiday, on Friday nights, or W		gger closing times by 10 minutes