Vehicle Inspection Form

Inventory ID:	Asset Number: 2029	Fair Market Value:
Short Description: Year 2019 Make DO	DGE Model	Charger
VIN: 2C3CDXAGOKH729558 Title Restriction: DY ZN		
Odometer: U5 3041 Miles Kilometers Odometer Accurate Y N:		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine-Type: 3.6 L, V Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed:		
This vehicle was maintained every Days D Hours Miles		
Date Removed From Service: Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:		
Drivetrain: 2 Wheel Drive Condition:		
Exterior: Color: BLACK Windows: No Cracked Glass Cracked WINDSHED Minor: Dents Scratches Dings Tire Condition: Tread #Flat Hubcaps #_ Major Damage to:		
Additional Damage:		
Decals: None Have Been Sprayed or Have been Removed & Impress ons Remain No Impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color BCAC Cloth Vinyl Leather Damage to Seats:		
Damage to Dash/Floor: Houses I	OF SOUR MENT	5
Radio: Stock or Brand & Model:		
AC (Condition: Cold Unknown)		AM/FM AM/FM Cassette AM/FM CD ir Bags: Driver's Side Dual
Cruise Control Tilt Steering Re	mote Mirrors DClimate Contro	a Dags: Driver's Side Dual
Power: Steering Windows Door Locks Seats		
Additional Equipment:		
Manufacturer Model		
☐ Tool Box ☐ Light Bar ☐ Ladder Rack	Utility Body: Brand	☐ Hitch: Type
Location of Asset:		
For more information contact:		
Reminder: Do not close items on or surround	ing a Holiday, on Friday nights, or V	Veekends. S agger closing times by 10 minutes.