

Generic Inspection Form

Inventory ID: _____

Asset Number

HP00091

Anticipated Sale Price:

1,200

Short Description:

DATSON Gas. fork lift

Year _____

Manufacturer

DATSON

Model

3000

Please fill in or check if apply

Long Description:

This Equipment: ☐ Is Operable ☐ Is Not Operable ☒ For Parts Only ☒ Needs Repair ☐ The Condition is Unknown

☐ Hours: unknown This equipment was maintained every _____ ☐ Hours ☐ Days

Serial # 11922

Repairs needed: _____

Description of Use

Color Red ☐ Cloth ☐ Vinyl ☐ Leather ☐ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

Location of Asset: 4089 Iron Work Parkway Lex, Ky 40511

For more information contact: Tim Driscoll 502-352-5028