Vehicle Inspection Form

Inventory ID:	Asset Number: 0KB2912	Fair Market Value:
Short Description: Year 2013 Make FORD Model FUSION		
VIN: 3 F A 6 P 0 G 7 6 D R 2 8 0 0 9 1 Title Restriction:		
Long Description: This Vehicle: ■ Starts □ Starts with a Boost & ■ Runs/Driveable □ Engine Runs ■ Does Not Run □ For Parts Only Engine- Type: 2.5 L, V 4 ■ Gas □ Diesel Engine □ Propane/Natural Gas □ Gas/Electric Hybrid Engine Condition: □ Runs ■ Needs repair □ is in unknown condition Repairs needed:		
This vehicle was maintained every 5000		
Exterior: Color: Grey Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Good Tread: #Flat Hubcaps #_Major Damage to: Hail damage. Additional Damage: Big scratches on the bumper, missing lights and tailgate trim. Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Light grey Cloth Vinyl Leather Damage to Seats:		
Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type Location of Asset:		
For more information contact:		