

Vehicle Inspection Form

Inventory ID:	Asset Number: OKB3680	Fair Market Value:																	
Short Description: Year <u>2015</u> Make <u>RAM</u> Model <u>1500</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 600px;"> <tr> <td>3</td><td>C</td><td>6</td><td>J</td><td>R</td><td>7</td><td>D</td><td>T</td><td>1</td><td>F</td><td>G</td><td>6</td><td>8</td><td>7</td><td>6</td><td>2</td><td>3</td> </tr> </table> Title Restriction: ☒ Y ☐ N			3	C	6	J	R	7	D	T	1	F	G	6	8	7	6	2	3
3	C	6	J	R	7	D	T	1	F	G	6	8	7	6	2	3			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr> <td>1</td><td>2</td><td>9</td><td>4</td><td>2</td><td>3</td> </tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	2	9	4	2	3											
1	2	9	4	2	3														
Long Description: This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☒ Does Not Run ☒ For Parts Only Engine- Type: <u>5.7</u> L, V <u>8</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>For parts only. Engine gone.</u> This vehicle was maintained every <u>5000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>4/5/2024</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual ___ Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: <u>Good.</u>																			
Exterior: Color: <u>Silver</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: <u>Fair</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: <u>Drivers side and fender wrecked.</u> Additional Damage: <u>Bed full of parts.</u> Decals: ☐ None ☐ Have Been Sprayed <u>or</u> ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>None</u> ☐ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>No seats</u> Damage to Dash/Floor: _____ Radio: ☒ Stock <u>or</u> ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☐ Door Locks ☐ Seats																			
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type <u>3</u>																			
Location of Asset: _____ For more information contact: <u>Division of Fleet Management - Annie Smith 502-782-0094</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			