

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2008</u> Make <u>FRHT</u> Model <u>MT55</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 250px;"> <tr> <td>4</td><td>U</td><td>Z</td><td>A</td><td>A</td><td>S</td><td>D</td><td>T</td><td>9</td><td>8</td><td>C</td><td>Z</td><td>4</td><td>2</td><td>1</td><td>5</td><td>2</td> </tr> </table> Title Restriction: ☐ Y ☒ N			4	U	Z	A	A	S	D	T	9	8	C	Z	4	2	1	5	2
4	U	Z	A	A	S	D	T	9	8	C	Z	4	2	1	5	2			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 150px;"> <tr> <td>2</td><td>1</td><td>4</td><td>7</td><td>6</td><td>8</td> </tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			2	1	4	7	6	8											
2	1	4	7	6	8														
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost & ☐ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u> </u> L, V <u> </u> ☐ Gas ☒ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>COMPRESSOR NEEDS REPLACED. BATTERIES NEED REPLACED</u> This vehicle was maintained every <u>365</u> ☒ Days ☐ Hours ☐ Miles Date Removed From Service: <u>1/1/25</u> Maintenance Records: ☐ Available ☒ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u> </u> Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____																			
Exterior: Color: <u>Blue/Green</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☐ Dents ☒ Scratches ☐ Dings Tire Condition: <u>Good</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>Grey</u> ☐ Cloth ☐ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: ☐ Stock or ☐ Brand & Model: <u>Inoperable</u> ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☐ Cold ☒ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats																			
Additional Equipment: <u>Onan Generator Model HDKCD</u> Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>100 Airport Road, Frankfort, KY 40601</u> For more information contact: <u>Lori Brown @ lbrown@kheaa.com</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			