

Vehicle Inspection Form

Inventory ID: RM7715	Asset Number:	Fair Market Value:																	
Short Description: Year <u>2016</u> Make <u>Ford</u> Model <u>Escape</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; width: 250px;"> <tr><td>1</td><td>F</td><td>M</td><td>C</td><td>U</td><td>9</td><td>G</td><td>X</td><td>8</td><td>G</td><td>U</td><td>B</td><td>7</td><td>5</td><td>1</td><td>3</td><td>5</td></tr> </table> Title Restriction: ☐ Y ☐ N			1	F	M	C	U	9	G	X	8	G	U	B	7	5	1	3	5
1	F	M	C	U	9	G	X	8	G	U	B	7	5	1	3	5			
Odometer: <table border="1" style="display: inline-table; text-align: center; width: 100px;"> <tr><td>8</td><td>1</td><td>9</td><td>2</td><td>3</td><td></td></tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			8	1	9	2	3												
8	1	9	2	3															
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>1.6</u> L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: <u>Replace transmission case, 02 sensor, drive shaft</u> This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>10/20/2025</u> Maintenance Records: ☒ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>Speed</u> Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: <u>replace transmission case</u> Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: <u>Operable</u>																			
Exterior: Color: <u>white</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: <u>Fair</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: <u>small dent to tailgate</u> Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color <u>Charcoal Black</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>No</u> Damage to Dash/Floor: <u>No</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats																			
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>Division for Air Quality, 2642 Russellville Road, Bowling Green, KY 42101</u> For more information contact: <u>Todd Johnston or Bill Blacketer at (270) 746-7475</u> Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.																			