

# Vehicle Inspection Form

Inventory ID: 005008SG	Asset Number: 23	Fair Market Value:
Short Description: Year 2016 Make FORD Model F250		
VIN: 1FT7X2B63GEB26258	Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other	
Odometer: 174,085 <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours	Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown	
Long Description: This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Runs/Drivable <input type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: 6.2 L, V 8 <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: NONE NOTED This vehicle was maintained every 6 MONTHS <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles/Kilometers Date Removed from Service: 03/11/2025 Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual ___ Speed Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition Repairs Needed: NONE NOTED Drivetrain: <input type="checkbox"/> 2 Wheel Drive <input checked="" type="checkbox"/> 4 Wheel Drive Condition: GOOD		
Exterior: Color: White Windows: <input type="checkbox"/> No Cracked Glass <input checked="" type="checkbox"/> Cracked Windshield Minor: <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: Fair Tread: ___ #Flat ___ Hubcaps # 4 Major Damage to: Right side is dented Additional Damage: N/A Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions Emergency equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed & <input checked="" type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Interior: Color Grey <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: Torn/Stained/Dirty Damage to Dash/Floor: Dirty Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: ___ <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input checked="" type="checkbox"/> Remote Mirrors <input checked="" type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input type="checkbox"/> Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand _____ <input type="checkbox"/> Hitch: Type _____		
Location of Asset: 1990 Siringo Rd. Santa Fe, NM 87505		