

Vehicle Inspection Form

Inventory ID:

G69926

Asset Number:

Fair Market Value:

Short Description:

Year 2007

Make FORD

Model F150

VIN: 1FTPX12V87KC98904

Title: ☒ Clean Title ☐ Salvage Title ☐ No Title
☐ Court Documents Only ☐ SF97 Form ☐ Other

Odometer: 139,570 ☒ Miles ☐ Kilometers ☐ Hours **Odometer Accurate?** ☒ Yes ☐ No ☐ Unknown

Long Description:

This Vehicle: ☒ Starts ☒ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 5.4 L, V 8 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: CHECK ENGINE LIGHT IS ON, ENGINE HAS A MISFIRE AND NO POWER, NEEDS A BATTERY

This vehicle was maintained every 6 MONTHS ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: 01/05/2025 Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☒ Needs repair ☐ Is Unknown Condition

Repairs Needed: FAULT MESSAGE APPEARS IN THE MESSAGE CENTER

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: Fair

Exterior:

Color: White

Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☒ Dents ☒ Scratches ☒ Dings Tire Condition: Fair Tread: 5/32 #Flat Hubcaps # 4

Major Damage to: Paint is chipping off

Additional Damage: Right side has dents,

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color Grey

☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Stained/Dirty

Damage to Dash/Floor: Stained/Dirty Panel under steering wheel is missing

Radio: ☒ Stock or ☐ Brand & Model: AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☐ Unknown ☐ No AC

Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☐ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment:

Manufacturer Model Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand Hitch: Type

Location of Asset: