

Vehicle Inspection Form

Inventory ID: 004559SG	Asset Number:	Fair Market Value:
Short Description: Year <u>2015</u> Make <u>Chevy</u> Model <u>Impala</u>		
VIN: <u>2G1WA5E35F1115108</u>	Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other	
Odometer: <u>43,674</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours	Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown	

Long Description:

This Vehicle: ☐ Starts ☒ Starts with a Boost & ☒ Runs/Drivable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: 3.6 L, V 6 ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: Check engine light is on, poor acceleration, needs a new battery

This vehicle was maintained every 6 MONTHS ☐ Days ☐ Hours ☐ Miles/Kilometers

Date Removed from Service: N/A Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: Stabilitrack light is on

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: Fair

Exterior: Color: White Windows: ☒ No Cracked Glass ☐ Cracked

Minor: ☐ Dents ☒ Scratches ☒ Dings Tire Condition: Fair Tread: 6/32 #Flat Hubcaps # 4

Major Damage to: Brakes are spongy (hard to stop)

Additional Damage: TPMS light is on

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☒ Impressions Remain ☐ No impressions

Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color Grey ☒ Cloth ☐ Vinyl ☐ Leather

Damage to Seats: Stained/Dirty

Damage to Dash/Floor: Stained/Dirty Left front and Right rear window are inoperable

Radio: ☒ Stock or ☐ Brand & Model: ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

AC Condition: ☐ Cold ☐ Unknown ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual

☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate Control

Power: ☒ Steering ☒ Windows ☒ Door Locks ☐ Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: 1990 Siringo Rd. Santa Fe, NM 87505