Vehicle Inspection Form

Inventory ID: G69924	Asset Number:	Fair Market Value:
Short Description: Year 2007 Make Ford Model F150		
VIN: 1FTPX14V87FB33277 Title: Clean Title Salvage Title No Title Court Documents Only SF97 Form Other		
Odometer: 129,379 ✓ Miles Kilometers Hours Odometer Accurate? ✓ Yes No Unknown		
Engine- Type: 5.4 L, V8 \checkmark Engine Condition: \checkmark RunsNeeds referenceRepairs needed:Engine has a misfire, referenceThis vehicle was maintained every 6 MCDate Removed from Service:UnknownTransmission: \checkmark AutomaticManualRepairs Needed:None NotedDrivetrain: 2 Wheel Drive \checkmark 4 WheelExterior:Color:WhiteMinor:Dents \checkmark ScratchesDingsMajor Damage to:Front bumper is demAdditional Damage:Left tail light is brocDecals:NoneHave Been SprayeEmergency equip: \checkmark NoneInterior:ColorGreyDamage to Seats:Torn/Stained/DirtyDamage to Dash/Floor:Stained/DirtyRadio: \checkmark Stock orBrand & Model:	Gas ☐ Diesel Engine ☐ Pro epair ☐ is in unknown condition needs a new battery DNTHS ☐ Days ☐ HoursMaintenance Records: [Speed Condition: ✔ Oper eel Drive Condition: FairWindows: ☐ No Cracke Tire Condition: BadT ted, left exterior mirror is missi oke, paint is peeling, hood stru d or ✔ Have been Removed & Deen removed & ☐ There are hoAM [wn ☐ No ACA emote Mirrors ✔ Climate Control	Miles/Kilometers Available Available Available Not Available For Inspection able Needs repair Is Unknown Condition ed Glass Cracked Windshield read: 4/32 #Flat Hubcaps # 4 ing the housing its are worn out & ✓ Impressions Remain No impressions les in the exterior There are no holes er ✓ AM/FM AM/FM AM/FM Cassette AM/FM Cassette
Additional Equipment:		
Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset: 1990 Siringo Rd. Santa Fe, NM 87505		