

Vehicle Inspection Form

Inventory ID: G50536		Asset Number:		Fair Market Value:	
Short Description: Year <u>2002</u> Make <u>Dodge</u> Model <u>Intrepid</u>					
VIN: <u>2B3AD56M82H218543</u>		Title: <input type="checkbox"/> Clean Title <input checked="" type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other			
Odometer: <u>93,555</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours		Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown			
Long Description: This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Runs/Drivable <input type="checkbox"/> Engine Runs <input checked="" type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u> </u> L, V <u> </u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: <u>Engine cranks with a jump start but will not start</u> This vehicle was maintained every <u>6 MONTHS</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles/Kilometers Date Removed from Service: <u>01/13/2025</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u> </u> Speed Condition: <input type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input checked="" type="checkbox"/> Is Unknown Condition Repairs Needed: <u>None Noted</u> Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: <u>Unknown</u> Exterior: Color: <u>Champagne</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked <u> </u> Minor: <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <u>Fair</u> Tread: <u>5/32</u> #Flat <u> </u> Hubcaps # <u> </u> Major Damage to: <u>Hail damage, paint is faded and chipped in some areas</u> Additional Damage: <u>Clearcoat is peeling</u> Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions Emergency equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes Interior: Color <u>Beige</u> <input checked="" type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>Stained/Dirty</u> Damage to Dash/Floor: <u>Stained/Dirty</u> Radio: <input checked="" type="checkbox"/> Stock or <input type="checkbox"/> Brand & Model: <u> </u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input checked="" type="checkbox"/> Remote Mirrors <input checked="" type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Door Locks <input checked="" type="checkbox"/> Seats Additional Equipment: <u> </u> Manufacturer <u> </u> Model <u> </u> Serial # <u> </u> <input type="checkbox"/> Tool Box <input type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input type="checkbox"/> Utility Body: Brand <u> </u> <input type="checkbox"/> Hitch: Type <u> </u> Location of Asset: <u>1990 Siringo Rd. Santa Fe, NM 87505</u>					