

5942

Vehicle Inspection Form

Inventory ID:

S-19

Asset Number:

332831

Fair Market Value:

Short Description:

Year 2012

Make Chevy

Model

Suburban

VIN:

1GNSC5E04CR103953

Title Restriction: ☐ Y ☒ N

Odometer:

81235

☒ Miles☐ KilometersOdometer Accurate ☒ Y ☐ N:

Long Description:

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts OnlyEngine- Type: 5.3 L, V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric HybridEngine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition

Repairs needed: Air Bag light on

This vehicle was maintained every 5,000 ☐ Days ☐ Hours ☒ MilesDate Removed From Service: 8/4/25 Maintenance Records: ☒ Available ☐ Not Available For InspectionTransmission: ☒ Automatic ☐ Manual ☐ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: NONE

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition:

Exterior:

Color: White

Windows: ☒ No Cracked Glass ☐ CrackedMinor: ☐ Dents ☒ Scratches ☐ Dings

Tire Condition: Good

Tread: 15 #Flat

Hubcaps #4

Major Damage to: NONE

Additional Damage:

Decals: ☒ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No ImpressionsEmergency equip: ☐ None ☒ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior:

Color: Black & Gray

☐ Cloth☐ Vinyl☒ Leather

Damage to Seats: None

Damage to Dash/Floor: Dash Broken

Radio: ☒ Stock or ☐ Brand & Model:☐ AM ☒ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD☒ AC (Condition: ☐ Cold ☐ Unknown) ☒ No ACAir Bags: ☒ Driver's Side ☐ Dual☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☒ Climate ControlPower: ☒ Steering ☐ Windows ☒ Door Locks ☒ Seats

A/C Does not work

Additional Equipment:

Manufacturer

Model

Serial #

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand☐ Hitch: Type

Location of Asset:

West Facility

For more information contact:

Reminder: Do not close items on or surrounding a Holiday, on Friday nights, or Weekends. Stagger closing times by 10 minutes.