

Vehicle Inspection Form

Inventory ID: _____

Asset Number: _____

Fair Market Value: _____

Short Description:

Year 2006 Make Chevrolet Model Silverado 1500

VIN: 3GCEC14X96G151305 Title Restriction: ☐ Y ☐ N

Odometer: 248367 ☒ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: _____

Long Description:

This Vehicle: ☐ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only

Engine- Type: L V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid

Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition

Repairs needed: _____

This vehicle was maintained every 5000 ☐ Days ☐ Hours ☒ Miles

Date Removed From Service: _____ Maintenance Records: ☐ Available ☒ Not Available For Inspection

Transmission: ☒ Automatic ☐ Manual Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition

Repairs Needed: _____

Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____

Exterior: Color: White Windows: ☒ No Cracked Glass ☐ Cracked _____

Minor: ☐ Dents ☒ Scratches ☐ Dings Tire Condition: Fail Tread: F #Flat _____ Hubcaps # _____

Major Damage to: _____

Additional Damage: _____

Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No Impressions

Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes

Interior: Color _____ ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: Worn

Damage to Dash/Floor: Worn Cracked

Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☐ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC

Air Bags: ☐ Driver's Side ☐ Dual

☐ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☐ Climate Control

Power: ☒ Steering ☐ Windows ☐ Door Locks ☐ Seats

Additional Equipment: _____

Manufacturer _____ Model _____ Serial # _____

☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____

Location of Asset: _____

For more information contact: _____