

Vehicle Inspection Form

Inventory ID: _____	Asset Number: _____	Fair Market Value: _____
Short Description: Year <u>2011</u> Make <u>FORD</u> Model <u>CROWN VIC</u>		
VIN: <u>2FABP7BV0Bx121790</u>		Title Restriction: ☒ Y ☐ N
Odometer: <u>157930</u>	☒ Miles ☐ Kilometers	Odometer Accurate ☒ Y ☐ N: _____
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>4.60</u> V ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>11/14/25</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u>Speed</u> Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>TAN</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☐ Dents ☐ Scratches ☒ Dings Tire Condition: <u>Good</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: <u>N/A</u> Additional Damage: <u>N/A</u> Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>BLACK</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: <u>NONE</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☒ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☒ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: _____ For more information contact: _____		