Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year 2011 Make FORD Model Crown VIC		
VIN: 2 F A B P 7 B V 2 B X 1 2 1 7 9 1 Title Restriction: \Box Y \Box N Odometer: \Box 7 7 4 0 9 \Box Miles \Box Kilometers Odometer Accurate \Box Y \Box N:		
Long Description: This Vehicle: Starts Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only Engine- Type: Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed:		
This vehicle was maintained every		
Exterior: Color: AN Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Tread: #Flat Hubcaps # Major Damage to: Additional Damage: Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes Interior: Color Cory Cloth Vinyl Leather Damage to Seats: None Damage to Dash/Floor: None		
Radio: Stock or Brand & Model:		
Additional Equipment: Model Serial #		
Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset: For more information contact:		