Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year 2013 Make Dodge Model Charger		
VIN: 2 C 3 C D X A T 1 D H 6 7 5 3 6 4 Title Restriction: DY DN		
Odometer: / 24309 PMiles Kilometers Odometer Accurate Y N:		
Long Description:		
This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only		
Engine-Type: 5.7 L, V Diesel Engine Propane/Natural Gas Gas/Electric Hybrid		
Engine Condition: Runs Needs repair is in unknown condition		
Repairs needed:		
This vehicle was maintained every 3660 Days Days Hours Miles		
Date Removed From Service: Maintenance Records: Available Not Available For Inspection		
Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition		
Repairs Needed:		
<u>Drivetrain</u> : 2 Wheel Drive Ondition:		
Exterior: Color: White Windows: Windows: Cracked Glass Cracked		
Minor: Dents Dents Dings Tire Condition: Tread: #Flat Hubcaps #_		
Major Damage to:		
Additional Damage: //as Decs/s		
Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions		
Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Meck Usinyl Leather		
Damage to Seats: NIA		
Damage to Dash/Floor:		
Radio: Stock or Brand & Model: AM AM/FM AM/FM Cassette AM/FM CD		
□ AC (Condition: □ Cold ☑ Unknown) □ No AC Air Bags: □ Driver's Side □ Dual		
Cruise Control Tilt Steering Remote Mirrors Climate Control		
Power: Steering Windows Door Locks Deats		
Additional Equipment:		
Manufacturer Mo		
		Hitch: Type
Location of Asset: For more information contact:		