

Vehicle Inspection Form

Inventory ID: _____	Asset Number: _____	Fair Market Value: _____
Short Description: Year <u>97</u> Make <u>Chevrolet</u> Model <u>Z71</u>		
VIN: 2 G C E K 1 9 B 0 V 1 2 5 5 3 8 0 Title Restriction: ☐ Y ☒ N		
Odometer: ☒ Miles ☐ Kilometers Odometer Accurate ☐ Y ☐ N: _____		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☐ Runs/Driveable ☐ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u> L, V </u> ☐ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☐ Runs ☐ Needs repair ☐ is in unknown condition Repairs needed: _____ This vehicle was maintained every _____ ☐ Days ☐ Hours ☐ Miles Date Removed From Service: _____ Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual <u> </u> Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☐ 2 Wheel Drive ☒ 4 Wheel Drive Condition: _____		
Exterior: Color: _____ Windows: ☐ No Cracked Glass ☐ Cracked _____ Minor: ☐ Dents ☐ Scratches ☐ Dings Tire Condition: _____ Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes		
Interior: Color _____ ☐ Cloth ☐ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: ☐ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☐ AC (Condition: ☐ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☐ Dual ☐ Cruise Control ☐ Tilt Steering ☐ Remote Mirrors ☐ Climate Control Power: ☐ Steering ☐ Windows ☐ Door Locks ☐ Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: _____ For more information contact: _____		