

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year <u>2016</u> Make <u>FORD</u> Model <u>EXPLORER</u>		
VIN: 1FM5K8ARXHG B55875 Title Restriction: ☒ Y ☐ N Odometer: 174126 ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N:		
Long Description: This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Runs/Driveable ☒ Engine Runs ☐ Does Not Run ☐ For Parts Only Engine- Type: <u>3.7L V</u> ☒ Gas ☐ Diesel Engine ☐ Propane/Natural Gas ☐ Gas/Electric Hybrid Engine Condition: ☒ Runs ☒ Needs repair ☐ is in unknown condition Repairs needed: <u>Engine has a knock</u> This vehicle was maintained every <u>5,000</u> ☐ Days ☐ Hours ☒ Miles Date Removed From Service: <u>1/13/25</u> Maintenance Records: ☐ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual Speed Condition: ☒ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: _____		
Exterior: Color: <u>White</u> Windows: ☒ No Cracked Glass ☐ Cracked Minor: ☐ Dents ☒ Scratches ☐ Dings Tire Condition: <u>Need replacing</u> Tread: <u>N/A</u> #Flat <u>N/A</u> Hubcaps # <u>No</u> Major Damage to: <u>N/A</u> Additional Damage: <u>N/A</u> Decals: ☐ None ☐ Have Been Sprayed or ☐ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☐ None ☒ Has been removed & ☒ There are holes in the exterior ☐ There are no holes		
Interior: Color <u>BLACK</u> ☒ Cloth ☐ Vinyl ☐ Leather Damage to Seats: <u>Hole in driver's seat. No rear seat</u> Damage to Dash/Floor: <u>None</u> Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☒ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors ☒ Climate Control Power: ☒ Steering ☒ Windows ☒ Door Locks ☒ Seats		
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____		
Location of Asset: _____ For more information contact: _____		