Vehicle Inspection Form

273 TGH PS13/2E

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year 2016 Make DOGE Model CHARGER		
VIN: 2C3CDXAT7GH356698 Title Restriction: DY NO Odometer: 163176 Miles DKilometers Odometer Accurate Y DN:		
Long Description: This Vehicle: Starts Starts with a Boost & Runs/Driveable Engine Runs Does Not Run For Parts Only Engine- Type: STOV Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: Runs Needs repair is in unknown condition Repairs needed: Aves Hours Miles Date Removed From Service: 5-7-25 Maintenance Records: Mavailable Not Available For Inspection Transmission: Automatic Manual Speed Condition: Operable Needs repair Is Unknown Condition Repairs Needed:		
<u>Drivetrain</u> : 2 Wheel Drive □ 4 Wheel Drive Condition:		
Exterior: Color: White Windows: No Cracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: 7004 Tread: #Flat Hubcaps ## Major Damage to: Additional Damage: Decals: None Have Been Sprayed or Have been Removed & Impressions Remain No Impressions Emergency equip: None Has been removed & There are holes in the exterior There are no holes		
Interior: Color Black Cloth Vinyl Leather Damage to Seats: None Damage to Dash/Floor: None		
Radio: Stock or Brand & Model:		
Additional Equipment: Manufacturer Model Serial # Hitch: Type		
Location of Asset: For more information contact:		