

Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value: \$7,500																	
Short Description: Year <u>2020</u> Make <u>Ford</u> Model <u>Van (Lift-Equipped Raised Roof)</u>																			
VIN: <table border="1" style="display: inline-table; text-align: center; font-family: monospace;"> <tr><td>1</td><td>F</td><td>D</td><td>V</td><td>U</td><td>4</td><td>X</td><td>8</td><td>X</td><td>L</td><td>K</td><td>A</td><td>1</td><td>1</td><td>1</td><td>1</td><td>9</td></tr> </table> Title Restriction: ☐ Y ☒ N			1	F	D	V	U	4	X	8	X	L	K	A	1	1	1	1	9
1	F	D	V	U	4	X	8	X	L	K	A	1	1	1	1	9			
Odometer: <table border="1" style="display: inline-table; text-align: center; font-family: monospace;"> <tr><td>1</td><td>7</td><td>5</td><td>5</td><td>4</td><td>6</td></tr> </table> ☒ Miles ☐ Kilometers Odometer Accurate ☒ Y ☐ N: _____			1	7	5	5	4	6											
1	7	5	5	4	6														
Long Description: This Vehicle: ☐ Starts ☒ Starts with a Boost Engine Runs ☒ Drivable at Highway Speed Needs to be Towed Engine- Type: <u>6.8</u> L, V _____ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: ☒ Runs Needs repair is in unknown condition This vehicle was maintained every <u>5,000</u> Days Hours ☒ Miles Date Removed From Service: <u>03/07/2025</u> Maintenance Records: ☒ Available ☐ Not Available For Inspection Transmission: ☒ Automatic ☐ Manual _____ Speed Condition: ☐ Operable ☐ Needs repair ☐ Is Unknown Condition Repairs Needed: _____ Drivetrain: ☒ 2 Wheel Drive ☐ 4 Wheel Drive Condition: <u>Fair</u>																			
Exterior: Color: <u>White</u> Windows: ☒ No Cracked Glass ☐ Cracked _____ Minor: ☒ Dents ☐ Scratches ☐ Dings Tire Condition: <u>Fair</u> Tread: _____ #Flat _____ Hubcaps # _____ Major Damage to: _____ Additional Damage: _____ Decals: ☐ None ☐ Have Been Sprayed or ☒ Have been Removed & ☐ Impressions Remain ☐ No Impressions Emergency equip: ☒ None ☐ Has been removed & ☐ There are holes in the exterior ☐ There are no holes																			
Interior: Color _____ ☐ Cloth ☒ Vinyl ☐ Leather Damage to Seats: _____ Damage to Dash/Floor: _____ Radio: ☒ Stock or ☐ Brand & Model: _____ ☐ AM ☐ AM/FM ☐ AM/FM Cassette ☒ AM/FM CD ☒ AC (Condition: ☒ Cold ☐ Unknown) ☐ No AC Air Bags: ☐ Driver's Side ☒ Dual ☒ Cruise Control ☒ Tilt Steering ☒ Remote Mirrors ☐ Climate Control Power: ☒ Steering ☐ Windows ☒ Door Locks ☐ Seats																			
Additional Equipment: _____ Manufacturer _____ Model _____ Serial # _____ ☐ Tool Box ☐ Light Bar ☐ Ladder Rack ☐ Utility Body: Brand _____ ☐ Hitch: Type _____																			
Location of Asset: <u>Parking Lot on King Street across from Courthouse</u> For more information contact: <u>Angie Greene</u>																			