Vehicle Inspection Form

Inventory ID:	Asset Number:	Fair Market Value:
Short Description: Year_2010		
VIN: 1GCZGFBA3A1173390 Title: ✓ Clean Title		
Odometer: 48,341 ✓ Miles Kilometers Hours Odometer Accurate? ✓ Yes No Unknown Long Description: This Vehicle: Starts ✓ Starts with a Boost & ✓ Runs/Drivable ✓ Engine Runs Does Not Run For Parts Only Engine-Type: 4.8 L, V 8 ✓ Gas Diesel Engine Propane/Natural Gas Gas/Electric Hybrid Engine Condition: ✓ Runs Needs repair is in unknown condition Repairs needed: This vehicle was maintained every Days Hours Miles/Kilometers Date Removed from Service: Maintenance Records: Available Not Available For Inspection Transmission: ✓ Automatic Manual Speed Condition: ✓ Operable Needs repair Is Unknown Condition Repairs Needed: Drivetrain: ✓ 2 Wheel Drive 4 Wheel Drive Condition: Foracked Glass Cracked Minor: Dents Scratches Dings Tire Condition: Windows: Vo Cracked Glass Cracked Minor: Dents Scratches Din		
Cruise Control Tilt Steering Remote Mirrors ✓ Climate Control Power: ✓ Steering Windows Door Locks Seats		
Additional Equipment: Manufacturer Model Serial # Tool Box Light Bar Ladder Rack Utility Body: Brand Hitch: Type		
Location of Asset: 3701 Duncanwood Ln, Baltimore, MD 21213		