

Vehicle Inspection Form

Inventory ID: 36-40	Asset Number:	Fair Market Value: \$7500.00
Short Description: Year <u>1996</u> Make <u>International</u> Model <u>DT466</u>		
VIN: <u>1HTSLAAM9TH336021</u> Title: <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other		
Odometer: <u>156,698</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours Odometer Accurate? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown		
Long Description: This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Runs/Driveable <input checked="" type="checkbox"/> Engine Runs <input type="checkbox"/> Does Not Run <input type="checkbox"/> For Parts Only Engine- Type: <u>7.6</u> L, V <u>8</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine <input type="checkbox"/> Propane/Natural Gas <input type="checkbox"/> Gas/Electric Hybrid Engine Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs repair <input type="checkbox"/> is in unknown condition Repairs needed: <u>small vent to a cargo door where generator is stored.</u> This vehicle was maintained every <u>6,000</u> <input type="checkbox"/> Days <input checked="" type="checkbox"/> Hours <input type="checkbox"/> Miles/Kilometers Date Removed from Service: <u>9/10/2025</u> Maintenance Records: <input checked="" type="checkbox"/> Available <input type="checkbox"/> Not Available For Inspection		
Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Speed Condition: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is Unknown Condition Repairs Needed: <u>N/a</u> Drivetrain: <input checked="" type="checkbox"/> 2 Wheel Drive <input type="checkbox"/> 4 Wheel Drive Condition: <u>Good</u>		
Exterior: Color: <u>Black</u> Windows: <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked Minor: <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <u>good</u> Tread: <u>good</u> #Flat <u> </u> Hubcaps # <u> </u> Major Damage to: <u>None</u> Additional Damage: <u>N/a</u> Decals: <input type="checkbox"/> None <input type="checkbox"/> Have Been Sprayed or <input checked="" type="checkbox"/> Have been Removed & <input checked="" type="checkbox"/> Impressions Remain <input type="checkbox"/> No impressions Emergency equip: <input type="checkbox"/> None <input checked="" type="checkbox"/> Has been removed & <input type="checkbox"/> There are holes in the exterior <input checked="" type="checkbox"/> There are no holes		
Interior: Color <u>Gray</u> <input checked="" type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>None</u> Damage to Dash/Floor: <u>None</u> Radio: <input type="checkbox"/> Stock or <input checked="" type="checkbox"/> Brand & Model: <u>Panasonic</u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown <input type="checkbox"/> No AC Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <input checked="" type="checkbox"/> Climate Control Power: <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Windows <input type="checkbox"/> Door Locks <input checked="" type="checkbox"/> Seats		
Additional Equipment: <u>Light bar with Horton light control box</u> Manufacturer <u>Horton</u> Model <u>N/a</u> Serial # <u>N/a</u> <input checked="" type="checkbox"/> Tool Box <input checked="" type="checkbox"/> Light Bar <input type="checkbox"/> Ladder Rack <input checked="" type="checkbox"/> Utility Body: Brand <u>N/a</u> Hitch: Type <u> </u>		
Location of Asset: <u>130 Homestead Avenue Hillsboro Ohio 45133</u>		