

# Heavy Truck Inspection Form

<b>Inventory ID:</b>	<b>Asset Number:</b> 5370	<b>Fair Market Value:</b>
<b>Short Description:</b> Year <u>2001</u>	<b>Manufacturer:</b> <u>International</u>	<b>Model:</b> <u>4900</u>
<b>VIN:</b> <u>IHTSDAAN32H5150000</u>	<b>Title:</b> <input checked="" type="checkbox"/> Clean Title <input type="checkbox"/> Salvage Title <input type="checkbox"/> No Title <input type="checkbox"/> Court Documents Only <input type="checkbox"/> SF97 Form <input type="checkbox"/> Other	
<b>Odometer:</b> <u>52,291</u> <input checked="" type="checkbox"/> Miles <input type="checkbox"/> Kilometers <input type="checkbox"/> Hours	<b>Odometer Accurate?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Unknown	
<b>Long Description:</b> Primary Use for Vehicle: <u>Aerial lift and Forestry work</u> GVW: <u>33,000</u> This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Is Not Operable <input type="checkbox"/> For Parts Only Date Removed From Service: <u>2/1/25</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection <b>Engine Manufacture:</b> <u>International</u> <b>Engine:</b> <u>L, V8</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel This vehicle was maintained every <u>3,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles # of Axles <u>2</u> <b>Engine Condition:</b> <input checked="" type="checkbox"/> Is operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Jake Brake: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Engine Repairs needed: <u>N/A</u> <b>Transmission Manufacture:</b> <u>International</u> <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual <u>6</u> Speed <b>Transmission Condition is:</b> <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown Rebuilt Date: _____ ) Transmission Repairs Needed: <u>N/A</u>		
<b>Exterior:</b> Color <u>White</u> <b>Windows:</b> <input checked="" type="checkbox"/> No Cracked Glass <input type="checkbox"/> Cracked Minor: <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings <b>Tire Condition:</b> <input type="checkbox"/> Low <input type="checkbox"/> Flat _____ Damage to: <u>Couple cracks in fiberglass service body</u> Additional Damage to: _____ Decals: <input type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input checked="" type="checkbox"/> Have been Removed & <input type="checkbox"/> Impressions Remain <input type="checkbox"/> No Impressions Capacity: <u>N/a</u> Loader: <input type="checkbox"/> Front <input type="checkbox"/> Side Electronic Tarp: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Condition: _____		
<b>Interior:</b> Color <u>Grey</u> <input type="checkbox"/> Cloth <input checked="" type="checkbox"/> Vinyl <input type="checkbox"/> Leather Damage to Seats: <u>tears in driver seat</u> Damage to Dash/Floor: <u>none</u> Radio: Brand <u>unknown</u> <input type="checkbox"/> AM <input checked="" type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD <input checked="" type="checkbox"/> Cruise Control <input checked="" type="checkbox"/> Tilt Steering <input type="checkbox"/> Remote Mirrors <b>Airbags:</b> <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown <b>Power:</b> <input type="checkbox"/> Windows <input type="checkbox"/> Doorlocks <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Seats <b>Additional Equipment:</b> Manufacturer: <u>Versalift</u> Model: <u>VST50001</u> Serial # <u>BC010075</u> Description: <u>50 ft. boom lift</u> Equipment Condition: <input checked="" type="checkbox"/> Is operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition Other Equipment: _____		
<b>Location of Asset:</b> <u>Concord woods</u>		