

Heavy Equipment Inspection Form

| | | |
|--|-----------------------------------|---|
| Inventory ID: | Asset Number <u>007213</u> | Fair Market Value: <u>\$1,000.00</u> |
| Short Description: | | |
| Year <u>2012</u> | Manufacturer <u>Smithco</u> | Model <u>7590</u> |
| Long Description: Equipment Serial # <u>T4103</u> [Required for all Marketing] | | |
| This Equipment: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a Boost & <input type="checkbox"/> Is Operable <input type="checkbox"/> Is not operable <input type="checkbox"/> For Parts Only | | |
| Engine: <u> </u> L, V <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel engine Engine: <input checked="" type="checkbox"/> Hours <u>1985</u> <input type="checkbox"/> Miles <u> </u> | | |
| This vehicle was maintained every <u> </u> <input type="checkbox"/> Hours | | |
| Engine Manufacture: <u>Vanguard</u> Condition: <input checked="" type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition | | |
| Engine Repairs needed: <u>None</u> | | |
| Transmission: <input type="checkbox"/> Automatic <input type="checkbox"/> Manual <u> </u> Speed Transmission: <input type="checkbox"/> Hours <u> </u> <input type="checkbox"/> Miles <u> </u> | | |
| Transmission Manufacture: <u> </u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown | | |
| Transmission Repairs Needed: <u> </u> | | |
| Drivetrain: <input type="checkbox"/> 2WD <input type="checkbox"/> 4WD <input type="checkbox"/> AWD Condition: <u> </u> | | |
| Date Removed From Service: <u>2025</u> Maintenance Records: <input type="checkbox"/> Available <input checked="" type="checkbox"/> Not Available For Inspection | | |
| Exterior: Color <u>Orange</u> Windows: <input type="checkbox"/> No cracked glass <input type="checkbox"/> Cracked <u> </u> | | |
| Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <u> </u> <input type="checkbox"/> Flat <u> </u> | | |
| Damage to: <u> </u> | | |
| Additional Damage to: <u> </u> | | |
| # Of Wheels <u> </u> # Of Axles <u> </u> # Of Tracks <u> </u> | | |
| Dimensions: <u>L 45" W 42" H 48" unit, trailer L 96" W 72" H 42"</u> | | |
| Decals: <input checked="" type="checkbox"/> None <input type="checkbox"/> Have been sprayed <input type="checkbox"/> Have been removed <input type="checkbox"/> Impressions remain <input type="checkbox"/> No impressions | | |
| Interior: Color <u> </u> <input type="checkbox"/> Cloth <input type="checkbox"/> Vinyl <input type="checkbox"/> Leather | | |
| Damage to Seats: <u> </u> | | |
| Damage to Dash/ Floor: <u> </u> | | |
| Radio: Brand <u> </u> <input type="checkbox"/> AM <input type="checkbox"/> AM/FM <input type="checkbox"/> AM/FM Cassette <input type="checkbox"/> AM/FM CD | | |
| <input type="checkbox"/> Cruise Control Power: <input type="checkbox"/> Steering <input type="checkbox"/> Seats <input type="checkbox"/> AC <input type="checkbox"/> No AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown | | |
| Additional Equipment: Manufacturer <u> </u> Model <u> </u> | | |
| Serial # <u> </u> Condition: <input type="checkbox"/> Is Operable <input type="checkbox"/> Needs repair <input type="checkbox"/> Is in Unknown Condition | | |
| Description: <u>w/ Trailer</u> | | |
| Location of Asset: <u>PRCC</u> | | |
| For more information contact: <u>Scott Kaylor</u> | | |