

Listal 2-10-2016

Tractor Inspection Form

Inventory ID: _____	Asset Number <u>KUB-1</u>	Fair Market Value: _____
---------------------	---------------------------	--------------------------

Short Description:
 Year _____ Manufacturer KUBOTA Model ZD221 Serial Number _____

Please fill in or check **Long Description:**

This Equipment: Starts Starts with a Boost & Is Operable Is not operable **For Parts Only**

Engine L, V _____ Gas Diesel engine Hours _____ Miles _____

This vehicle was maintained every _____ Hours Horse Power _____

Engine Manufacture: Kubota **Condition:** Is Operable Needs repair Is in Unknown Condition

Repairs needed: Blown motor

Date Removed From Service: _____ Maintenance Records: Available Not Available For Inspection

Transmission

Transmission: Automatic Manual Speed Transmission: Hours _____ Miles _____

Transmission Manufacture: kubota **Condition:** Is Operable Needs Repair Is Unknown

Drivetrain _____ Repairs Needed: _____

Attachments & Additional Equipment

Backhoe Front End Loader PTO Drive 3 Point Hitch Other: _____

Mowing Deck: Manufacture: _____ Model: _____ Type: _____ Size: 48

Deck Condition: Operable Not Operable & Damage: _____

Other Equipment: Manufacture _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Is in Unknown Condition

Description: _____

Exterior: Color Orange **Windows:** No cracked glass Cracked _____

Minor Dents Scratches Dings **Tire Condition:** Low _____ Flat _____

Minor dents to: Yes

Major damage to: _____

Dimensions: _____

Decals: None Have been sprayed Have been removed Impressions remain No impressions

Interior: Color _____ Cloth Vinyl Leather

Damage to: Seat

Radio: Brand _____ AM AM/FM AM/FM Cassette AM/FM CD

Cruise Control Power: Steering Seats AC No AC Condition: Cold Unknown

Location of Asset: _____

For more information contact: _____