

Generic Inspection Form

Inventory ID:

Asset Number **900HB**

Anticipated Sale Price:

Short Description: **900HB**

Year **2015**

Manufacturer **Sullair air compressor**

Model **900HB**

Please fill in or check if apply

Long Description:

This Equipment: ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only ☐ Needs Repair ☐ The Condition is Unknown

☒ Hours: **2696** This equipment was maintained every **3 to 400** ☒ Hours ☐ Days

Serial # **201501070057**

Repairs needed: **Needs service have filters. The air filters have 19 hrs on them.**

Description of Use

Used for sandblasting, approximately 300 hr per season. Stored indoors during rain and winters.

Color **Green/black** ☐ Cloth ☐ Vinyl ☐ Leather ☒ Metal ☐ Plastic ☐ Wood ☐ Rubber

Minor damage to: _____

Major damage to: _____

Size: Length: Feet: _____ Inches: _____ Width/Depth: Feet: _____ Inches: _____ Height: Feet: _____ Inches: _____

Men's Size: _____ Women's Size: _____

Additional Equipment: Manufacturer **Caterpillar** Model **C 9.3**

Serial # **D9N05305** Condition: ☒ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: **300 HP diesel engine**

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: ☐ Is Operable ☐ Needs repair ☐ Unknown Condition

Description: _____

Comments:

2 in. and two 3/4 in. discharge valves. less than 10,000 miles on tires and axles. Have service manuals and service records.

Location of Asset: _____

For more information contact: _____