

Heavy Truck Inspection Form

Inventory ID: _____

Asset Number: **39T**

Fair Market Value: _____

Short Description:

Year 2009

Manufacturer Navistar

Model 7400 SFA 4x2

VIN:

1 H T W D A A N 3 9 J 1 9 3 6 1 1

Title Restriction: ☐ Y ☒ N

Mileage/Odometer:

1 6 1 6 1 _____

Odometer Accurate ☒ Y ☐ N: _____

Long Description: Primary Use for Vehicle: Sand blasting/painting GVW: 29,000

This Vehicle: ☒ Starts ☐ Starts with a Boost & ☒ Is Operable ☐ Is Not Operable ☐ For Parts Only

Date Removed From Service: 04/1/25 Maintenance Records: ☒ Available ☐ Not Available For Inspection

Engine Manufacture: Maxxforce Engine: 7.6 L, V ☐ Gas ☒ Diesel

This vehicle was maintained every 4 to 5000 ☐ Days ☐ Hours ☒ Miles # of Axles 29,000

Engine Condition: ☒ Is operable ☐ Needs repair ☐ Is in Unknown Condition Jake Brake: ☐ Yes ☒ No

Engine Repairs needed: _____

Transmission Manufacture: Allison ☒ Automatic ☐ Manual _____ Speed

Transmission Condition is: ☒ Operable ☐ Needs Repair ☐ Unknown ☐ Rebuilt (Date: _____)

Transmission Repairs Needed: _____

Exterior: Color Green

Windows: ☒ No Cracked Glass ☐ Cracked _____

Minor: ☐ Dents ☒ Scratches ☐ Dings Tire Condition: ☐ Low _____ ☐ Flat _____

Damage to: Body and windows have paint over spray.

Additional Damage to: Broken battery box cover

Decals: ☐ None ☐ Have been sprayed ☒ Have been Removed & ☒ Impressions Remain ☐ No Impressions

Capacity: _____ Loader: ☐ Front ☐ Side Electronic Tarp: ☐ Yes ☐ No Condition: _____

Interior: Color Gray ☐ Cloth ☒ Vinyl ☐ Leather

Damage to Seats: Torn seats paint on them

Damage to Dash/Floor: paint

Radio: Brand _____ ☐ AM ☒ AM/FM ☐ AM/FM Cassette ☐ AM/FM CD

☒ Cruise Control ☒ Tilt Steering ☐ Remote Mirrors

Airbags: ☐ Driver's Side ☐ Dual

☐ AC ☒ No AC AC Condition: ☐ Cold ☐ Unknown Power: ☐ Windows ☐ Doorlocks ☐ Steering ☐ Seats

Additional Equipment: Manufacturer: _____ Model: _____

Serial # _____ Description: _____

Equipment Condition: ☐ Is operable ☐ Needs repair ☐ Is in Unknown Condition

Other Equipment: Light bar operable

Location of Asset: _____

For more information contact: _____